

Redevelopment of Wan Sin Koon LOT Nos. 1856 (Part), 1857 S.A., 1857 RP, 1858, 1859 and Adjoining Government Land STT1345 Lau Fau Shan, Yuen Long

Geotechnical Planning Review Report

2025-08-13





# **Document distribution**

Redevelopment of Wan Sin Koon LOT Nos. 1856 (Part), 1857 S.A., 1857 RP, 1858, 1859 and Adjoining Government Land STT1345 Lau Fau Shan, Yuen Long

# **Geotechnical Planning Review Report**

2025-08-13

#### Prepared by

WSP 7/F ONE KOWLOON 1 WANG YUEN STREET KOWLOON BAY, HONG KONG T +852 2579 8899

Quality control	Name	Date	Signature
Prepared by:	Larry Yeung	2025-08-13	
Reviewed by:	Terrence Tse	2025-08-13	
Approved by:	Paul Yau	2025-08-13	

#### **Revisions**

Rev	Date	Details
-	2025-08-13	1 <sup>st</sup> Submission



# **Table of contents**

1.	Introduction	5
2.	Description of the site	6
2.1	Site Location	6
2.2	Topographic Condition	7
2.3	Proposed Redevelopment Plan	7
3.	Desktop Investigation	9
3.1	Geological Survey Map	9
3.2	Geotechnical Area Studies Programme	10
3.3	Existing Features Within and Adjacent to the Redevelopment Area	10
3.4	Natural Terrain	14
3.5	Available Site-Specific Ground Investigation Works	14
4.	Anticipated Geotechnical Works	15
4.1	Proposed Site Formation Works	15
4.2	Assessment Slope Stability for the Slope Within Proposed Redevelopment	16
5.	Conclusion	18
Table	3.1 Summary of Existing Features Within the Redevelopment Area	11
Table	3.2 Summary of Existing Features Without the Redevelopment Area	13
Table	4.1 Summary of proposed slope/retaining wall works to be carried out in site	
	formation	15
Figure	e 2.1 1:5000 topographical map	6
Figure		7
Figure	,	8
Figure	·	9
Figure		10
Figure		14
Figure		16
. igaic	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	10



Appendix A – SIS Records

Appendix B – Latest Architectural Drawings



# 1. Introduction

WSP Hong Kong Ltd. is appointed as the Geotechnical and Civil Engineering consultant for the Redevelopment of Wan Fau Sin Koon Lot Nos. 1856 (Part), 1857 S.A., 1857 RP, 1858, 1859 and Adjoining Government Land STT1345 in DD129 Lau Fau Shan at Yuen Long.

The proposed redevelopment includes 6 single-story Columbarium blocks/halls, 3 eco-joss paper furnaces, an ancillary toilet block and an office.

This report is a geotechnical planning review report to provide the preliminary planning review in geotechnically aspects based on the findings of the visual survey; the available existing information obtained from the relevant government departments and available ground investigation.



# 2. Description of the site

#### 2.1 Site Location

The proposed redevelopment (The Site) is located at Wan Fau Sin Koon, Lau Fau Shan, Yuen Long. It consists of five lots including lot nos.1856 (Part), 1875 S.A., 1857 RP, 1858 and 1859 and adjoining government land STT1345 in DD129 Lau Fau Shan at Yuen Long. Wan Fou Sin Koon is located along Deep Bay Road in Lau Fau Shan, Yuen Long District. The site lies at the toe of a gently sloping hillside, with terrain rising prominently from the northeast to the south ranging from 16.1mPD to 31.8mPD, where it is enveloped by the vegetated slopes of Lam Hang Shan.

The site has a total of about 33,078.4m<sup>2</sup>. The surrounding area is characterized by abundant mature trees, dense greenery, and patches of gravelled ground, forming a natural buffer around the site. To the southeast of the site, there is an open storage area.

The 1:5000 topographical map and site location plan with adjacent buildings/roads are shown in **Figure 2.1 & 2.2** respectively.




Figure 2.1 1:5000 topographical map






Figure 2.2 Site Location Layout Plan with adjacent Buildings/roads

# 2.2 Topographic Condition


The topography of the site is at the level varying from about +48mPD (Lam Hang Shan Side) at Southern Site Boundary to +16mPD (Deep Bay Road Side) inside the Site Boundary.

### 2.3 Proposed Redevelopment Plan

The proposed layout plan which shown in **Figure 2.3** depicts a columbarium complex, showcasing a thoughtfully organized layout with multiple designated areas. These include four single-storey columbarium blocks labelled A, B, C, and D, as well as a new family precinct zone named Zone E-Family Precinct. An existing niche area is marked for retention, indicating integration of old and new structures.



Figure 2.3 Proposed Development Scheme





# 3. Desktop Investigation

# 3.1 Geological Survey Map

The Hong Kong Geological Survey Map, Sheet 11 (scale 1:20,000) Solid and Superficial Geology of Hong Kong and Kowloon published by the Geotechnical Control Office (GCO, 2012) indicates that the site situated at debris flow deposits (Qpd) and undivided, Clay, slit, sand and gravel well-sorted to semi-sorted Alluvium (Qfa), Slit, sand, gravel and boulders Alluvium (Qca), phyllite, metasiltstone with metasandstone and graphite schist (Mai Po Member), Equi granular to inequigranular fine to medium grained two mica granite (Tsing Shan Granite\_Jms\_gfm). Part Plan of geological map is presented in below and provided in **Figure 3.1**.




Figure 3.1 Part Plan of The Hong Kong Geological Survey Map, Sheet 2 (scale 1:20,000)



# 3.2 Geotechnical Area Studies Programme

In accordance with the Geotechnical Land Use Map (GLUM) (Ref. No. GASP/20/1/1 2nd Edition) in Geotechnical Area Studies Programme (GASP) Report IV – Hong Kong and Kowloon (1987) issued by CEDD, the terrain in proposed site can be classified as Class I to III. (low to high geotechnical limitations). With reference to cl. 4.1.3 of the report, GLUM Class III terrain is expected to require High geotechnical investigation, and the costs associated with site investigation, site formation, foundation and drainage work will probably be high for the north part of site and lower cost for the south part. Part plan of the relevant GLUM is presented in below and provided in **Figure 3.2**.




Figure 3.2 Part Plan of the GLUM - North West New Territories

# 3.3 Existing Features Within and Adjacent to the Redevelopment Area

There are 22 registered slope features within or in the vicinity of the proposed site. The location of these features is shown on attached **Figure 3.3**. Records of registered slope features, maintenance responsible lot/party, and stability statement or upgrading works are summarized in **Table 3.1**. Relevant information on the existing slopes and retaining walls feature retrieved from Slope Information System (SIS) is enclosed in **Appendix A**.



Table 3.1 Summary of Existing Features Within the Redevelopment Area

Feature Nos.	Responsible Lot / Party	Past Stability Check	Proposed Work(s)
# 2SW-C/C 50	STT1345 / Lands D	Checked by GEO under site formation and drainage works of private development (BD ref. no. 6/9137/03), no robust slope upgrading works had been carried out.  consequence-to-life (CTL) Category 3.	Slope stability assessment will be carried out to ensure on effect to the proposed development.
# 2SW-C/C 63	DD129 LOT 771 / STT1345 / Lands D	Checked by GEO under site formation and drainage works	Slope stability assessment will be
# 2SW-C/C 64	STT1345 / Lands D	of private development (BD ref. no. 6/9137/03), no robust slope upgrading works had been carried out.  consequence-to-life (CTL) Category 3.	carried out to ensure on effect to the proposed development.
# 2SW-C/C 66	DD129 LOT 1855 / DD129 LOT 1857 S.A/ Lands D	No past checking record, consequence-to-life (CTL) Category 3.	Retaining wall /Slope feature will be modified in proposed site formation work; slope stability assessment will be required.
# 2SW-C/C 67	DD129 LOT 1854A / DD129 LOT 1822B / STT1345 / Lands D	The northern slope portion 4 had been formed by Cement fill under site formation and drainage works of private development (BD ref. no. 6/9137/03), no robust slope upgrading works had been carried out. consequence-to-life (CTL) Category 1.	Slope stability assessment will be carried out to ensure on effect to the proposed development.
# 2SW-C/C 68	STT1345 / Lands D	Checked by GEO under site formation and drainage works of private development (BD ref. no. 6/9137/03), no robust slope upgrading works had been carried out.  consequence-to-life (CTL) Category 1	
# 2SW-C/C 93	STT1345 / Lands D	'Miramat" erosion control mat and hydroseeding had been provided on slope but no robust slope upgrading works.	Slope stability assessment will be carried out to ensure on effect to the



Feature Nos.	Responsible Lot / Party	Past Stability Check	Proposed Work(s)
		Checked by GEO under site formation works of private development (BD ref. no. 6/9137/03).	proposed development.
		consequence-to-life (CTL) Category 3.	
# 2SW-C/C 96	Lands D	No past checking record, consequence-to-life (CTL) Category 3.	
# 2SW-C/C 97	STT1345 / Lands D	Slope upgrading works by	
# 2SW-C/C 98	STT1345 / Lands D	installation of soil nails had been done on western portions under site formation and drainage works of private development (BD ref. no. 6/9137/03).	
		consequence-to-life (CTL) Category 3.	
# 2SW-C/C 99	STT1345 / Lands D	No past checking record, consequence-to-life (CTL) Category 3.	
# 2SW-C/CR 101	STT1345 / Lands D	Slope upgrading works by installation of soil nails had been done on western portions under site formation and drainage works of private development (BD ref. no. 6/9137/03). Stage 2 Report is founded for the slope upgrading works.  consequence-to-life (CTL) Category 2	
# 2SW-C/F 10	DD129 LOT 1859 / STT1345 / Lands D	No past checking record, consequence-to-life (CTL) Category 3.	Retaining wall /Slope feature will be modified in proposed site formation work; slope stability assessment will be required.
** 2SW-C/F 11	STT1345 / Lands D		Slope stability
** 2SW-C/F 12	STT1345 / Lands D		assessment will be carried out to ensure on effect to the proposed development.



Feature Nos.	Responsible Lot / Party	Past Stability Check	Proposed Work(s)
# 2SW-C/R 4	DD129 LOT 1857 S.A / STT1345 / Lands D		Retaining wall /Slope feature will be modified in proposed site formation work; slope stability assessment will be required.
# 2SW-C/R 11	DD129 LOT 1857 S.A / STT1345 / Lands D		

<sup>#</sup> For the existing feature located within the site and will be modified by the proposed development

Table 3.2 Summary of Existing Features Without the Redevelopment Area

Feature Nos.	Responsible Lot / Party	Past Stability Check	Proposed Work(s)
2SW-C/C 51	Lands D	No past checking record, consequence-to-life (CTL) Category 3.	Slope stability
2SW-C/C 52	Lands D		assessment may not be required due to no propose works & on change of CTL.
2SW-C/C 69	DD129 Lot1862 / Lands D	No past checking record, consequence-to-life (CTL) Category 3.	Slope stability assessment may not be required due to no propose works & on change of CTL.
2SW-C/F 4	Lands D	No past checking record, consequence-to-life (CTL) Category 3.	Slope stability assessment may not be required due to no propose works & on change of CTL.
2SW-C/F 15	DD129 Lot1862 / Lands D		Slope stability assessment may not be required due to no propose works & on change of CTL.

<sup>\*\*</sup> For the existing feature within the site but no modified by the proposed development



28WCF 10

28WCF 11

28WCF

Figure 3.3 Location plan of Registered Features


# 3.4 Natural Terrain

The site is mainly surrounded by the man-made features and no natural terrain hazard to the site is considered since the proposed redeveloped plan is classified group 4 facility of columbarium, which does not require natural terrain hazard study as per GEO Report No.138.

# 3.5 Available Site-Specific Ground Investigation Works

Previous ground investigation works were carried out by Wai Tat Foundation & Engineering Limited (2007), The Boring Engineering Limited (2011), Vibro (H.K.) Limited (2015), Futher ground investigation works had been carried out by Avance Engineering (HK) Ltd (2023).

Based on the available information, the preliminary typical geological section showing soil / rock profile is shown in **Figure 3.4**. The tentative grade III rockhead level varies from about -7 mPD to +44 mPD.






Figure 3.4 Typical Geological Section



# 4. Anticipated Geotechnical Works

# 4.1 Proposed Site Formation Works

Based on the proposed redevelopment plan attached in Appendix B, site formation works including slope / retaining wall removal / modification shall be carried out to cater for any ground level difference alongside or within the site. The permanent retaining structures such as Solider pile wall, L-shaped R.C. retaining wall are anticipated. **Table 4.1** and **Figure 4.1** shows the proposed slope/retaining wall works to be carried out.

Table 4.1 Summary of proposed slope/retaining wall works to be carried out in site formation

Feature Nos.	Responsible Lot / Party	Proposed Works in this planning
2SW-C/F 10	DD129 LOT 1859 / STT1345 / Lands D	Retained and part of the slope feature to be filled and excavated in site formation work
2SW-C/R 4	DD129 LOT 1857 S.A / STT1345 / Lands D	Retained and part of the retaining wall feature to be modified in site formation work
2SW-C/R 11	DD129 LOT 1857 S.A / STT1345 / Lands D	Retained and part of the retaining wall feature to be removed in site formation work
2SW-C/C 66	DD129 LOT 1855 / DD129 LOT 1857 S.A/ Lands D	Retained and part of the slope feature to be modified in site formation work
2SW-C/C 93	STT1345 / Lands D	Retained and part of the slope feature to be filled and excavated in site formation work



NFW NEW COLUMBARIUM COLUMBARIUM A LAND FILL AREA LAND EXCAVATION AREA 2SW-C/F 11 LAND FILL F2 AREA:386.184 sqm DEPTH: 0m ~ 1m 2SW-C/F AREA:23.328 sam NEW DEPTH: 0m ~ 1.6m COLUMBARIUM D NFW COLUMBARIUM B LAND EXCAVATION E1 SITE AREA:279.674 sqm DEPTH: 0m ~ 2.2m LAND EXCAVATION E2 AREA:986.801 sqm NEW **DEPTH: 0m ~ 0.8m** COLUMBARIUM C 2SW-C/R 11 **EXISTING NICHE** 2SW-C/R 4 NEW FAMIL TO BE RETAINED PRECINCT COLUMBA JM E LAND FILL AREA:264.224 sqm DEPTH: 0m ~ 3.1m AND FILL F3 AREA:1374.523 sqm DEPTH: 0m ~ 0.8m 67 2SW

Figure 4.1 Location of proposed slope/retaining wall works to be carried out

Stability assessment and improvement works will be required for the remain features with marginal stability conditions to meet current safety standards. The stability of the affected features will be checked in the detailed design stage.

Upon completion of the permanent site formation work, the modified features or newly formed features shall be registered, and maintenance manual shall be prepared to the owner for maintenance purpose. All removed features shall require deregistration.

Safety measures and monitoring scheme will be provided along the site to ensure safety of pedestrians and adjacent facilities from construction hazards.



site will be assessed to ensure meeting with current safety standards. If any slope features are found not meeting current standard, slope upgrading works will be proposed, subject to detailed design considerations.



# 5. Conclusion

Based on the available information, it is considered that the proposed redevelopment is geotechnically feasible. The likely involved geotechnical works shall have no adverse effects on the adjacent grounds, slope, retaining wall, underground utilities and structures. All slopes and retaining walls affecting or being affected by the proposed redevelopment plan will be assessed, if necessary, upgrading works will be implemented in detailed design of the proposed building plan.



# A SIS Records





# Appendix A – SIS Records

Lau Fau Shan Project - Manmade Features 2SW-C/C 51 Man-made Features 2SW-C/C 2SW-C/C 34 50 Cut slopes 2SW-C/F 4 2SW-C/C 52 Disturbed -20--26terrain Fill slopes 2SW-C/F NT defence 2SW-C/C 63 measures 骨殖甕 2SW-C/F 11 NT stabilisation Graves measures 2SW-C/C 2SW-C/F 10 Retaining walls 2SW-C/C 70 18.5 Slope Features 19.0 The Site 露天貨倉 Open Storage TS Niches 2SW-C/R 11 2SW-C/F 15 26.2 Wan Fau Sin Koon SW-C/R 焚化爐 21.0 Incinerator 22 2SW-C/C 墓地 Graves 26.6 19.0 12.2 Division 2SW-0/C 67 ZSW-0/C 64 Scale 1:1,000 2SW-C/C 98 Date 28/07/2022 GEOTECHNICAL ENGINEERING 10 20 40 60 80 CIVIL ENGINEERING AND DEVELOPMENT DEPARTMENT Meters The Government of the Hong Kong SAR. Map Sheet: 2SW-17C, 2SW-17D, 2SW-22A, 2SW-22B (Printed by Lee Roger Jo Wah)

#### **BASIC INFORMATION**

Location: WAN FAU SIN KOON, LAU FAU SHAN, YUEN LONG

Registration Date: 06-05-1998
Ranking Score (NPRS): 0 (LPMit)
Date of Formation: post-1977

Date of Construction/

Modification:

Data Source: SIRST

Approximate Coordinates: Easting: 817220 Northing: 837156

#### **CONSEQUENCE-TO-LIFE CATEGORY**

Facility at Crest: Undeveloped green belt

Distance of Facility from Crest (m): 0

Facility at Toe: District open space

Distance of Facility from Toe (m): 0

Consequence-to-life Category: 3

Remarks: N/A

#### **SLOPE PART**

(1) Max. Height (m): 4.5 Length (m): 126 Average Angle (deg): 45

#### **WALL PART**

N/A

#### MAINTENANCE RESPONSIBILITY

(1) Sub Div.: 1 Mixed Feature Party: DD129 LOT 771 Agent: N/A Land Cat.: 1 Reason Code: 1 MR Endorsement Date: 20-06-2012 (2) Sub Div.: 2 Agent: Lands D Land Cat.: 1,5b(vi) Mixed Feature Party: Lands D Reason Code: 59 MR Endorsement Date: 20-06-2012 (3) Sub Div.: 2 Mixed Feature Party: STT1345 Agent: N/A Land Cat.: 1,5b(vi) Reason Code: 3 MR Endorsement Date: 20-06-2012

#### **DETAILS OF SLOPE / RETAINING WALL**

Date of Inspection: 09-03-1998

Data Source: SIRST

Slope Part Drainage: N/A

Wall Part Drainage: N/A

#### **SLOPE PART**

Slope Part (1)

Surface Protection (%): Bare: 40 Vegetated: 60 Chunam: 0 Shotcrete: 0 Other Cover: 0

Material Description: Material type: Soil Geology: Decomposed granite
Berm: No. of Berms: N/A Min. Berm Width (m): N/A

Weepholes: Size (mm): N/A Spacing (m): N/A

#### **WALL PART**

N/A

# **SERVICES**

N/A

#### **CHECKING STATUS INFORMATION**

Tagmark: SCS\_3343 Part: O Checking Status: Others (See remarks) Checking Certificate No.: N/A

#### **BACKGROUND INFORMATION**

GIU Cell Ref.: 2SW22A3

Map Sheet Reference (1:1000): 2SW-22A

Aerial Photos: A 15845 (1988), A 15844 (1988)

Nearest Rainguage Station

(Station Number):

Hong Shui House, Shui Pin Wai Estate(N12)

Data Collected On:

09-03-1998

Date of Construction, Subsequent

Modification and Demolition:

Modification: Constructed Before: 1988

fore: 1988 After: 1987

Related Reports/Files or Documents:

File/Report: Development

Ref. No.: GCMW 9068/95

File/Report: Development

Ref. No.: GCMW 9068/95

File/Report: Development File/Report: Development

Ref. No.: GCMW 9068/95 Ref. No.: GCMW 9068/95

Remarks: N/A

Follow Up Actions: N/A

DH-Order (To Be Confirmed None with Buildings Department):

Advisory Letter (To Be Confirmed None with Buildings Department):

LPMIS: None

#### **ENHANCED MAINTENANCE INFORMATION**

From Maintenance Department: (Last Updated Date: 26/05/2022)

#### **STAGE 1 STUDY REPORT**

 $Inspected\ On:$ 

Weather:

District: MW

Section No: 1-1

Height(m):

Type of Toe Facility: District open space

Distance from Toe(m): 0

Type of Crest Facility: Undeveloped green belt

Distance from Crest(m): 0

Consequence Category:

**Engineering Judgement:** 

Section No: 2-2

Type of Toe Facility:

Distance from Toe(m):

Type of Crest Facility:

Distance from Crest(m):

Consequence Category:

**Engineering Judgement:** 

Sign of Seepage:

Criterion A satisfied:

Sign of Distress:

Criterion D satisfied:

Non-routine maintenance required:

Note:

Masonry wall/Masonry facing:

Note:

Consequence category (for critical section):

Observations: N/A

**Emergency Action Required:** 

Action By: N/A

#### **ACTION TO INITIATE PREVENTIVE WORKS**

Criterion A/Criterion D: N/A

Action By: N/A

Further Study:

Action By: N/A

#### OTHER EXTERNAL ACTION

Check / repair Services:


Action By: N/A

Non-routine Maintenance:

Action By: N/A

# <u>PHOTO</u>





#### **BASIC INFORMATION**

Location: South of Wan Fau Siu Koon, Lau Fau Shan

Registration Date: 06-05-1998

Ranking Score (NPRS): 0 (EI)

Date of Formation: pre-1977

Date of Construction/

Modification:

Data Source: Agreement CE 59/2002 (GE)

Approximate Coordinates: Easting: 817231 Northing: 836968

#### **CONSEQUENCE-TO-LIFE CATEGORY**

Facility at Crest: Road/footpath with low traffic density

Distance of Facility from Crest (m): 0

Facility at Toe: District open space

Distance of Facility from Toe (m): 0

Consequence-to-life Category: 3

Remarks: N/A

#### **SLOPE PART**

(1) Max. Height (m): 3 Length (m): 55 Average Angle (deg): 45

#### **WALL PART**

N/A

#### MAINTENANCE RESPONSIBILITY

(1) Sub Div.: 1 Mixed Feature Party: STT1345 Agent: N/A Land Cat.: 1,5b(vi) Reason Code: 3 MR Endorsement Date: 03-08-2012 (2) Sub Div.: 1 Land Cat.: 1,5b(vi) Mixed Feature Party: Lands D Agent: Lands D Reason Code: 59 MR Endorsement Date: 03-08-2012 (3) Sub Div.: 2 Mixed Feature Party: Lands D Agent: Lands D Land Cat.: 5b(vi) Reason Code: 62 MR Endorsement Date: 03-08-2012

#### **DETAILS OF SLOPE / RETAINING WALL**

Date of Inspection: 18-03-2003

Data Source: Agreement CE 59/2002 (GE)

Slope Part Drainage: N/A

Wall Part Drainage: N/A

#### **SLOPE PART**

Slope Part (1)

Surface Protection (%): Bare: 40 Vegetated: 60 Chunam: 0 Shotcrete: 0 Other Cover: 0

Material Description: Material type: Soil Geology: Decomposed granite
Berm: No. of Berms: N/A Min. Berm Width (m): N/A

Weepholes: Size (mm): N/A Spacing (m): N/A

#### **WALL PART**

N/A

# **SERVICES**

N/A

#### **CHECKING STATUS INFORMATION**

Tagmark: SCS\_1325 Part: O Checking Status: Others (See remarks) Checking Certificate No.: N/A

#### **BACKGROUND INFORMATION**

GIU Cell Ref.: 2SW22A5

Map Sheet Reference (1:1000): 2SW-22A

Aerial Photos: CW33565 (2001), CW33566 (2001)

Nearest Rainguage Station Hong Shui H

(Station Number):

Hong Shui House, Shui Pin Wai Estate(N12)

Data Collected On: 18-03-2003

Date of Construction, Subsequent Modification: Constructed Before: 1974 After: 1964

**Modification and Demolition:** 

Related Reports/Files or Documents: N/A

Remarks: N/A

Follow Up Actions: N/A

DH-Order (To Be Confirmed None with Buildings Department):

Advisory Letter (To Be Confirmed None with Buildings Department):

LPMIS: None


#### **ENHANCED MAINTENANCE INFORMATION**

From Maintenance Department: (Last Updated Date: 26/05/2022)

# **STAGE 1 STUDY REPORT**

Inspected On: 18-03-2003
Weather: Mainly Fine

District: MW



Section No: 1-1

Height(m): H1:3, H2:0

Type of Toe Facility: District open space

Distance from Toe(m): 0

Type of Crest Facility: Road/footpath with low traffic density

Distance from Crest(m): 0
Consequence Category: 3
Engineering Judgement: P

Section No: 2-2

Type of Toe Facility: N/A

Distance from Toe(m): 0 Type of Crest Facility: N/A

Distance from Crest(m): 0
Consequence Category: 3

Engineering Judgement: P

Sign of Seepage: Slope : No sign of seepage

Wall: N/A

Criterion A satisfied:

Sign of Distress: Slope : Minor (near crest, mid-portion)

Wall: N/A

Criterion D satisfied: N

Non-routine maintenance required: N

Note: N/A

Masonry wall/Masonry facing: N

Note: N/A

Consequence category (for critical section): 3

Observations: N/A

Emergency Action Required: N

Action By: N/A

# **ACTION TO INITIATE PREVENTIVE WORKS**

Criterion A/Criterion D: N/A

Action By: N/A

Further Study: N

Action By: N/A

### OTHER EXTERNAL ACTION

Check / repair Services: N

Action By: N/A

Non-routine Maintenance: N

Action By: N/A

# <u>PHOTO</u>







### **BASIC INFORMATION**

Location: Wan Fau Sin Koon, Deep Bay Road, Lau Fau Shan

Registration Date: 06-05-1998

Ranking Score (NPRS): 0 (EI)

Date of Formation: post-1977

Date of Construction/

Modification:

Data Source: EI(Lands D)

Approximate Coordinates: Easting: 817216 Northing: 837032

# **CONSEQUENCE-TO-LIFE CATEGORY**

Facility at Crest: Road/footpath with low traffic density

Distance of Facility from Crest (m): 0.5

Facility at Toe: Road/footpath with very low traffic density

Distance of Facility from Toe (m): 0

Consequence-to-life Category: 3

Remarks: N/A

# **SLOPE PART**

(1) Max. Height (m): 3.6 Length (m): 60 Average Angle (deg): 45

### **WALL PART**

### MAINTENANCE RESPONSIBILITY

(1) Sub Div.: 1 Mixed Feature Party: DD129 LOT 1857 S.A Agent: N/A Land Cat.: 1 Reason Code: 1 MR Endorsement Date: 16-06-2021 Party: DD129 LOT 1855 Agent: N/A Land Cat.: 1 MR Endorsement Date: 16-06-2021 (2) Sub Div.: 2 Mixed Feature Reason Code: 1 (3) Sub Div.: 3 Mixed Feature Party: Lands D Agent: Lands D Land Cat.: 5b(vi) Reason Code: 62,90 MR Endorsement Date: 16-06-2021

# **DETAILS OF SLOPE / RETAINING WALL**

Date of Inspection: 01-11-2001

Data Source: El(Lands D)

Slope Part Drainage: N/A

Wall Part Drainage: N/A

# **SLOPE PART**

Slope Part (1)

Surface Protection (%): Bare: 0 Vegetated: 100 Chunam: 0 Shotcrete: 0 Other Cover: 0

Material Description: Material type: Soil Geology: Decomposed granite
Berm: No. of Berms: N/A Min. Berm Width (m): N/A

Weepholes: Size (mm): N/A Spacing (m): N/A

# **WALL PART**

N/A

# **SERVICES**

# **CHECKING STATUS INFORMATION**

Tagmark: SCS\_3344 Part: O Checking Status: Others (See remarks) Checking Certificate No.: N/A

### **BACKGROUND INFORMATION**

GIU Cell Ref.: 2SW22A3

Map Sheet Reference (1:1000): 25W-22A

Aerial Photos: A 34472 (1993), A 34473 (1993)

Nearest Rainguage Station Hong

(Station Number):

Hong Shui House, Shui Pin Wai Estate(N12)

Data Collected On:

01-11-2001

Date of Construction, Subsequent

Modification: Constructed Before: 1993 After: 1991

 $\label{lem:modification} \textbf{Modification and Demolition:}$ 

Related Reports/Files or Documents: File/Report: Development Ref. No.: GCMW 9068/95

File/Report: Development Ref. No.: GCMW 9068/95
File/Report: Development Ref. No.: GCMW 9068/95
File/Report: Development Ref. No.: GCMW 9068/95

Remarks: N/A

Follow Up Actions: N/A

DH-Order (To Be Confirmed None with Buildings Department):

Advisory Letter (To Be Confirmed None with Buildings Department):

LPMIS: None

# **ENHANCED MAINTENANCE INFORMATION**

From Maintenance Department: (Last Updated Date: 26/05/2022)

# **STAGE 1 STUDY REPORT**

Inspected On: Weather:

District: MW

Section No: 1-1

Height(m):

Type of Toe Facility: Road/footpath with very low traffic density

Distance from Toe(m): 0

Type of Crest Facility: Road/footpath with low traffic density

Distance from Crest(m): 0.5

Consequence Category:

**Engineering Judgement:** 

Section No: 2-2

Type of Toe Facility:

Distance from Toe(m):

Type of Crest Facility:

Distance from Crest(m):

Consequence Category:

**Engineering Judgement:** 

Sign of Seepage:

Criterion A satisfied:

Sign of Distress:

Criterion D satisfied:

Non-routine maintenance required:

Note:

Masonry wall/Masonry facing:

Note:

Consequence category (for critical section):

Observations: N/A

**Emergency Action Required:** 

Action By: N/A

# **ACTION TO INITIATE PREVENTIVE WORKS**

Criterion A/Criterion D: N/A

Action By: N/A

Further Study:

Action By: N/A

### OTHER EXTERNAL ACTION

Check / repair Services:

Action By: N/A

Non-routine Maintenance:


Action By: N/A

# <u>PHOTO</u>





Feature No. 2SW-C/C 66



# **BASIC INFORMATION**

Location: Wan Fau Sin Koon, Lau Fau Shan

Registration Date: 06-05-1998

Ranking Score (NPRS): 0 (EI)

Date of Formation: post-1977

Date of Construction/

Modification:

Data Source: AP

Approximate Coordinates: Easting: 817202 Northing: 836978

# **CONSEQUENCE-TO-LIFE CATEGORY**

Facility at Crest: Other thinly populated buildings

Distance of Facility from Crest (m): 2

Facility at Toe: Road/footpath with very low traffic density

Distance of Facility from Toe (m): 0

Consequence-to-life Category: 1

Remarks: N/A

# **SLOPE PART**

(1) Max. Height (m): 7.7 Length (m): 72 Average Angle (deg): 36

### **WALL PART**

### MAINTENANCE RESPONSIBILITY

(1) Sub Div.: 1 Mixed Feature Party: DD129 LOT 1854A Agent: N/A Land Cat.: 1 Reason Code: 1 MR Endorsement Date: 22-06-2012 (2) Sub Div.: 2 Mixed Feature Party: DD129 LOT 1822B Agent: N/A Land Cat.: 1 Reason Code: 1 MR Endorsement Date: 22-06-2012 (3) Sub Div.: 3 Mixed Feature Party: STT1345 Agent: N/A Land Cat.: 1,5b(vi) Reason Code: 3 MR Endorsement Date: 22-06-2012 Agent: Lands D Land Cat.: 1,5b(vi) (4) Sub Div.: 3 Mixed Feature Party: Lands D Reason Code: 59 MR Endorsement Date: 22-06-2012 Party: STT1345 Land Cat.: 1 Reason Code: 3 MR Endorsement Date: 22-06-2012 (5) Sub Div.: 4 Mixed Feature Agent: N/A

# **DETAILS OF SLOPE / RETAINING WALL**

Date of Inspection: 02-05-2013

Data Source: AP

Slope Part Drainage: (1) Position: Crest Size(mm): 225

Wall Part Drainage: N/A

# **SLOPE PART**

Slope Part (1)

Surface Protection (%): Bare: 0 Vegetated: 85 Chunam: 0 Shotcrete: 15 Other Cover: 0

Material Description: Material type: Soil Geology: N/A

Berm: No. of Berms: N/A Min. Berm Width (m): N/A

Weepholes: Size (mm): 75 Spacing (m): 1.5

# **WALL PART**

N/A

# **SERVICES**

# **CHECKING STATUS INFORMATION**

Tagmark: SCS\_1326 Part: O Checking Status: Feature modified/upgraded to current standard Checking Certificate No.: N/A

### **BACKGROUND INFORMATION**

GIU Cell Ref.: 2SW22A6

Map Sheet Reference (1:1000): 2SW-22A

Aerial Photos: A34472 (1993), A 34473 (1993)

Nearest Rainguage Station

(Station Number):

Hong Shui House, Shui Pin Wai Estate(N12)

Data Collected On:

02-05-2013

Date of Construction, Subsequent

Modification: Constructed Before: 1993 After: 1991

Modification and Demolition:

Related Reports/Files or Documents: File/Report: Development Ref. No.: GCMW 9068/95

File/Report: Development Ref. No.: GCMW 9068/95
File/Report: Development Ref. No.: GCMW 9068/95
File/Report: Development Ref. No.: GCMW 9068/95

Remarks: N/A

Follow Up Actions: N/A

DH-Order (To Be Confirmed None with Buildings Department):

Advisory Letter (To Be Confirmed None with Buildings Department):

LPMIS: None

# **ENHANCED MAINTENANCE INFORMATION**

From Maintenance Department: (Last Updated Date: 26/05/2022)

# **STAGE 1 STUDY REPORT**

Inspected	On:
Weat	her:

District: MW

Section No: 1-1

Height(m):

Type of Toe Facility: Road/footpath with very low traffic density

Distance from Toe(m): 0

Type of Crest Facility: Other thinly populated buildings

Distance from Crest(m): 2

Consequence Category:

**Engineering Judgement:** 

Section No: 2-2

Type of Toe Facility:

Distance from Toe(m):

Type of Crest Facility:

Distance from Crest(m):

Consequence Category:

**Engineering Judgement:** 

Sign of Seepage:

Criterion A satisfied:

Sign of Distress:

Criterion D satisfied:

Non-routine maintenance required:

Note:

Masonry wall/Masonry facing:

Note:

Consequence category (for critical section):

Observations: N/A

**Emergency Action Required:** 

Action By: N/A

# **ACTION TO INITIATE PREVENTIVE WORKS**

Criterion A/Criterion D: N/A

Action By: N/A

Further Study:

Action By: N/A

### OTHER EXTERNAL ACTION

Check / repair Services:

Action By: N/A


Non-routine Maintenance:

Action By: N/A

# <u>PHOTO</u>







### **BASIC INFORMATION**

Location: New Temple, Wan Fau Sin Koon, Lau Fau Shan

Registration Date: 06-05-1998
Ranking Score (NPRS): 0 (LPMit)
Date of Formation: post-1977
Date of Construction/ 24-04-2013

Modification:

Data Source: Districts

Approximate Coordinates: Easting: 817154 Northing: 837120

# **CONSEQUENCE-TO-LIFE CATEGORY**

Facility at Crest: Road/footpath with very low traffic density

Distance of Facility from Crest (m): 0

Facility at Toe: Temple

Distance of Facility from Toe (m): 0

Consequence-to-life Category: 1

Remarks: N/A

# **SLOPE PART**

(1) Max. Height (m): 6 Length (m): 103 Average Angle (deg): 35

### **WALL PART**

### MAINTENANCE RESPONSIBILITY

(1) Sub Div.: 1 Mixed Feature Party: STT1345 Agent: N/A Land Cat.: 1,5b(vi) Reason Code: 3 MR Endorsement Date: 28-07-2016 (2) Sub Div.: 1 Mixed Feature Party: Lands D Agent: Lands D Land Cat.: 1,5b(vi) Reason Code: 59 MR Endorsement Date: 28-07-2016 (3) Sub Div.: 2 Mixed Feature Party: STT1345 Agent: N/A Land Cat.: 1,5a Reason Code: 3,47 MR Endorsement Date: 28-07-2016

# **DETAILS OF SLOPE / RETAINING WALL**

Date of Inspection: 31-07-2013

Data Source: Districts

Slope Part Drainage: (1) Position: Crest Size(mm): 450

(2) Position: Toe Size(mm): 300

Wall Part Drainage: N/A

# **SLOPE PART**

Slope Part (1)

Surface Protection (%): Bare: 0 Vegetated: 100 Chunam: 0 Shotcrete: 0 Other Cover: 0

Material Description: Material type: Soil Geology: N/A

Berm: No. of Berms: N/A Min. Berm Width (m): N/A

Weepholes: Size (mm): N/A Spacing (m): N/A

# **WALL PART**

N/A

# **SERVICES**

# **CHECKING STATUS INFORMATION**

Tagmark: SCS\_3345 Part: O Checking Status: Others (See remarks) Checking Certificate No.: N/A

### **BACKGROUND INFORMATION**

GIU Cell Ref.: 2SW22A3

Map Sheet Reference (1:1000): 2SW-22A

Aerial Photos: 39309 (1981), 39310 (1981)

Nearest Rainguage Station

Hong Shui House, Shui Pin Wai Estate(N12)

Data Collected On:

(Station Number):

31-07-2013

Date of Construction, Subsequent

Modification: Constructed Before: 1981 After: 1979

Modification and Demolition:

Related Reports/Files or Documents: File/Report: Development Ref. No.: GCMW 9068/95

File/Report: Development Ref. No.: GCMW 9068/95
File/Report: Development Ref. No.: GCMW 9068/95
File/Report: Development Ref. No.: GCMW 9068/95

Remarks: N/A

Follow Up Actions: N/A

DH-Order (To Be Confirmed None with Buildings Department):

Advisory Letter (To Be Confirmed None with Buildings Department):

LPMIS: None

# **ENHANCED MAINTENANCE INFORMATION**

From Maintenance Department: (Last Updated Date: 26/05/2022)

# **STAGE 1 STUDY REPORT**

Inspected	l On:
Weat	ther:

District: MW

Section No: 1-1

Height(m):

Type of Toe Facility: Temple

Distance from Toe(m): 0

Type of Crest Facility: Road/footpath with very low traffic density

Distance from Crest(m): 0

Consequence Category:

**Engineering Judgement:** 

Section No: 2-2

Type of Toe Facility:

Distance from Toe(m):

Type of Crest Facility:

Distance from Crest(m):

Consequence Category:

**Engineering Judgement:** 

Sign of Seepage:

Criterion A satisfied:

Sign of Distress:

Criterion D satisfied:

Non-routine maintenance required:

Note:

Masonry wall/Masonry facing:

Note:

Consequence category (for critical section):

Observations: N/A

**Emergency Action Required:** 

Action By: N/A

# **ACTION TO INITIATE PREVENTIVE WORKS**

Criterion A/Criterion D: N/A

Action By: N/A

Further Study:

Action By: N/A

### OTHER EXTERNAL ACTION

Check / repair Services:

Action By: N/A

Non-routine Maintenance:

Action By: N/A

# <u>PHOTO</u>














# **BASIC INFORMATION**

Location: Wan Fau Sin Koon, Lau Fau Shan

Registration Date: 06-05-1998

Ranking Score (NPRS): 0 (EI)

Date of Formation: post-1977
Date of Construction/ 16-09-2010

Modification:

Data Source: AP

Approximate Coordinates: Easting: 817325 Northing: 837094

# **CONSEQUENCE-TO-LIFE CATEGORY**

Facility at Crest: Undeveloped green belt

Distance of Facility from Crest (m): 0

Facility at Toe: Columbarium

Distance of Facility from Toe (m): 0

Consequence-to-life Category: 3

Remarks: N/A

# **SLOPE PART**

(1) Max. Height (m): 6 Length (m): 135 Average Angle (deg): 35

### **WALL PART**

### MAINTENANCE RESPONSIBILITY

(1) Sub Div.: 0 Mixed Feature Party: Lands D Agent: Lands D Land Cat.: 1,5b(vi) Reason Code: 59 MR Endorsement Date: 05-06-2012 (2) Sub Div.: 0 Mixed Feature Party: STT1345 Agent: N/A Land Cat.: 1,5b(vi) Reason Code: 3 MR Endorsement Date: 05-06-2012

# **DETAILS OF SLOPE / RETAINING WALL**

Date of Inspection: 27-02-2013

Data Source: AP

Slope Part Drainage: (1) Position: Crest Size(mm): 375

(2) Position: Toe Size(mm): 600

Wall Part Drainage: N/A

# **SLOPE PART**

Slope Part (1)

Surface Protection (%): Bare: 0 Vegetated: 85 Chunam: 15 Shotcrete: 0 Other Cover: 0

Material Description: Material type: Soil Geology: N/A

Berm: No. of Berms: N/A Min. Berm Width (m): N/A

Weepholes: Size (mm): N/A Spacing (m): N/A

# **WALL PART**

N/A

# **SERVICES**

#### CHECKING STATUS INFORMATION

Tagmark: SCS\_3347 Part: 1 Checking Status: Feature to be modified/upgraded to current standard Checking Certificate No.: N/A

### **BACKGROUND INFORMATION**

GIU Cell Ref.: 2SW22B1

Map Sheet Reference (1:1000): 25W-22B

Aerial Photos: A 24888 (1990), A 24891 (1990)

Nearest Rainguage Station

(Station Number):

Hong Shui House, Shui Pin Wai Estate(N12)

Data Collected On:

27-02-2013

Date of Construction, Subsequent

N/A

**Modification and Demolition:** 

Related Reports/Files or Documents:

File/Report: DLC/BC Ref. No.: GCMW 4/1C/2-2 pt.19 f(13,14,17,22)

File/Report: DLC/BC Ref. No.: GCMW 4/1C/2-2 pt.19 f(13,14,17,22)

File/Report: Development Ref. No.: GCMW 9068/95
File/Report: Development Ref. No.: GCMW 9068/95
File/Report: Development Ref. No.: GCMW 9068/95
File/Report: LA Ref. No.: GCMW 9068/95
File/Report: LA Ref. No.: GCMW 5/3/10(W) pt.6 f(55,60)
File/Report: LA Ref. No.: GCMW 5/3/10(W) pt.6 f(55,60)

Remarks: N/A

Follow Up Actions: N/A

DH-Order (To Be Confirmed None with Buildings Department):

Advisory Letter (To Be Confirmed None with Buildings Department):

LPMIS: None

# **ENHANCED MAINTENANCE INFORMATION**

From Maintenance Department: (Last Updated Date: 26/05/2022)

### **STAGE 1 STUDY REPORT**

 $Inspected\ On:$ 

Weather:

District: MW

Section No: 1-1

Height(m):

Type of Toe Facility: Columbarium

Distance from Toe(m): 0

Type of Crest Facility: Undeveloped green belt

Distance from Crest(m): 0

Consequence Category:

**Engineering Judgement:** 

Section No: 2-2

Type of Toe Facility:

Distance from Toe(m):

Type of Crest Facility:

Distance from Crest(m):

Consequence Category:

**Engineering Judgement:** 

Sign of Seepage:

Criterion A satisfied:

Sign of Distress:

Criterion D satisfied:

Non-routine maintenance required:

Note:

Masonry wall/Masonry facing:

Note:

Consequence category (for critical section):

Observations: N/A

**Emergency Action Required:** 

Action By: N/A

# **ACTION TO INITIATE PREVENTIVE WORKS**

Criterion A/Criterion D: N/A

Action By: N/A

Further Study:

Action By: N/A

### OTHER EXTERNAL ACTION

Check / repair Services:

Action By: N/A

Non-routine Maintenance:

Action By: N/A

# <u>PHOTO</u>










Feature No. 2SW-C/C 93



### **BASIC INFORMATION**

Location: South of Wan Fau Koon Temple, Lau Fau Shan

Registration Date: 06-05-1998

Ranking Score (NPRS): 0 (EI)

Date of Formation: pre-1977

Date of Construction/

Modification:

Data Source: EI(Lands D)

Approximate Coordinates: Easting: 817270 Northing: 836939

### **CONSEQUENCE-TO-LIFE CATEGORY**

Facility at Crest: Undeveloped green belt

Distance of Facility from Crest (m): 0

Facility at Toe: Cemetery

Distance of Facility from Toe (m): 0

Consequence-to-life Category: 3

Remarks: N/A

# **SLOPE PART**

(1) Max. Height (m): 3 Length (m): 10 Average Angle (deg): 40

### **WALL PART**

### **MAINTENANCE RESPONSIBILITY**

(1) Sub Div.: O Government Feature Party: Lands D Agent: Lands D Land Cat.: 5b(vi) Reason Code: 62 MR Endorsement Date: 07-12-1999

# **DETAILS OF SLOPE / RETAINING WALL**

Date of Inspection: 07-11-2001

Data Source: EI(Lands D)

Slope Part Drainage: N/A

Wall Part Drainage: N/A

# **SLOPE PART**

Slope Part (1)

Surface Protection (%): Bare: 0 Vegetated: 100 Chunam: 0 Shotcrete: 0 Other Cover: 0

Material Description: Material type: Soil Geology: Other geology
Berm: No. of Berms: N/A Min. Berm Width (m): N/A

Weepholes: Size (mm): N/A Spacing (m): N/A

# **WALL PART**

N/A

# **SERVICES**

### **CHECKING STATUS INFORMATION**

Tagmark: SCS\_3350 Part: O Checking Status: Others (See remarks) Checking Certificate No.: N/A

# **BACKGROUND INFORMATION**

GIU Cell Ref.: N/A

Map Sheet Reference (1:1000): 2SW-22B

Aerial Photos: N/A

Nearest Rainguage Station ()

(Station Number):

Data Collected On: 07-11-2001

Date of Construction, Subsequent  $_{\rm N/A}$ 

Modification and Demolition:

Related Reports/Files or Documents: N/A

Remarks: N/A

Follow Up Actions: N/A

DH-Order (To Be Confirmed None with Buildings Department):

Advisory Letter (To Be Confirmed None with Buildings Department):

LPMIS: None

# **ENHANCED MAINTENANCE INFORMATION**

From Maintenance Department: (Last Updated Date: 26/05/2022)

### **STAGE 1 STUDY REPORT**

Inspected On:

Weather:

District: N/A

Section No: 1-1

Height(m):

Type of Toe Facility: Cemetery

Distance from Toe(m): 0

Type of Crest Facility: Undeveloped green belt

Distance from Crest(m): 0

Consequence Category:

**Engineering Judgement:** 

Section No: 2-2

Type of Toe Facility:

Distance from Toe(m):

Type of Crest Facility:

Distance from Crest(m):

Consequence Category:

**Engineering Judgement:** 

Sign of Seepage:

Criterion A satisfied:

Sign of Distress:

Criterion D satisfied:

Non-routine maintenance required:

Note:

Masonry wall/Masonry facing:

Note:

Consequence category (for critical section):

Observations: N/A

**Emergency Action Required:** 

Action By: N/A

# **ACTION TO INITIATE PREVENTIVE WORKS**

Criterion A/Criterion D: N/A

Action By: N/A

Further Study:

Action By: N/A

### OTHER EXTERNAL ACTION

Check / repair Services:

Action By: N/A


Non-routine Maintenance:

Action By: N/A

# <u>PHOTO</u>







#### **BASIC INFORMATION**

Location: Wan Fau Sin Koon, Lau Fau Shan

Registration Date: 06-05-1998

Ranking Score (NPRS): 0 (EI)

Date of Formation: pre-1977
Date of Construction/ 16-11-2012

Modification:

Data Source: AP

Approximate Coordinates: Easting: 817297 Northing: 836977

### **CONSEQUENCE-TO-LIFE CATEGORY**

Facility at Crest: Road/footpath with very low traffic density

Distance of Facility from Crest (m): 0.5

Facility at Toe: Road/footpath with very low traffic density

Distance of Facility from Toe (m): 0.6
Consequence-to-life Category: 3

Remarks: N/A

# **SLOPE PART**

(1) Max. Height (m): 6.4 Length (m): 130 Average Angle (deg): 40

### **WALL PART**

#### MAINTENANCE RESPONSIBILITY

(1) Sub Div.: 1 Mixed Feature Party: STT1345 Agent: N/A Land Cat.: 1,5b(vi) Reason Code: 3 MR Endorsement Date: 12-06-2015 (2) Sub Div.: 1 Mixed Feature Party: Lands D Agent: Lands D Land Cat.: 1,5b(vi) Reason Code: 59 MR Endorsement Date: 12-06-2015 (3) Sub Div.: 2 Mixed Feature Party: STT1345 Agent: N/A Land Cat.: 1,5a Reason Code: 3,48 MR Endorsement Date: 12-06-2015

### **DETAILS OF SLOPE / RETAINING WALL**

Date of Inspection: 04-01-2013

Data Source: AP

Slope Part Drainage: (1) Position: Crest Size(mm): 375

(2) Position: On slope Size(mm): 375

(3) Position: Toe Size(mm): 375

Wall Part Drainage: N/A

### **SLOPE PART**

Slope Part (1)

Surface Protection (%): Bare: 0 Vegetated: 85 Chunam: 0 Shotcrete: 15 Other Cover: 0

Material Description: Material type: Soil Geology: N/A

Berm: No. of Berms: N/A Min. Berm Width (m): N/A

Weepholes: Size (mm): N/A Spacing (m): N/A

# **WALL PART**

N/A

# **SERVICES**

### **CHECKING STATUS INFORMATION**

Tagmark: SCS\_1327 Part: O Checking Status: Others (See remarks) Checking Certificate No.: N/A

### **BACKGROUND INFORMATION**

GIU Cell Ref.: 2SW22B4

Map Sheet Reference (1:1000): 2SW-22B

Aerial Photos: 24540 (1978), 24541 (1978)

**Nearest Rainguage Station** 

Hong Shui House, Shui Pin Wai Estate(N12)

Data Collected On:

(Station Number):

04-01-2013

Date of Construction, Subsequent

N/A

Modification and Demolition:

Related Reports/Files or Documents: N/A

Remarks: N/A

Follow Up Actions: N/A

DH-Order (To Be Confirmed None with Buildings Department):

Advisory Letter (To Be Confirmed None with Buildings Department):

LPMIS: None

# **ENHANCED MAINTENANCE INFORMATION**


From Maintenance Department: (Last Updated Date: 26/05/2022)

### **STAGE 1 STUDY REPORT**

Inspected On: 12-03-1998

Weather: Some Rain

District: MW



Section No: 1-1

Height(m): H1

H1:5,H2:0

Type of Toe Facility: Road/footpath with very low traffic density

Distance from Toe(m): 0.6

Type of Crest Facility: Road/footpath with very low traffic density

Distance from Crest(m): 0.5
Consequence Category: 3
Engineering Judgement: P

Section No: 2-2

Type of Toe Facility: N/A

Distance from Toe(m): 0 Type of Crest Facility: N/A

Distance from Crest(m): 0
Consequence Category: 3

Engineering Judgement: P

Sign of Seepage: Slope : No signs of seepage

Wall: N/A

Criterion A satisfied:

Sign of Distress: Slope : Reasonable (mid-portion, at toe)

Wall: N/A

Criterion D satisfied: N

Non-routine maintenance required:

Note: N/A

Note: N/A

Consequence category (for critical section): 3

Observations: N/A

Emergency Action Required: N

Action By: N/A

# **ACTION TO INITIATE PREVENTIVE WORKS**

Criterion A/Criterion D: N/A

Action By: N/A

Further Study: Y

Action By: Mixed

### OTHER EXTERNAL ACTION

Check / repair Services: N

Action By: N/A


Non-routine Maintenance: N

Action By: N/A

# <u>PHOTO</u>







### **BASIC INFORMATION**

Location: Wan Fau Sin Koon, Lau Fau Shan

Registration Date: 06-05-1998

Ranking Score (NPRS): 0 (EI)

Date of Formation: pre-1977
Date of Construction/ 16-11-2012

Modification:

Data Source: AP

Approximate Coordinates: Easting: 817319 Northing: 836959

### **CONSEQUENCE-TO-LIFE CATEGORY**

Facility at Crest: Undeveloped green belt

Distance of Facility from Crest (m): 0.6

Facility at Toe: Road/footpath with very low traffic density

Distance of Facility from Toe (m): 0.6
Consequence-to-life Category: 3

Remarks: N/A

# **SLOPE PART**

(1) Max. Height (m): 6.8 Length (m): 115 Average Angle (deg): 38

### **WALL PART**

#### MAINTENANCE RESPONSIBILITY

(1) Sub Div.: 1 Mixed Feature Party: STT1345 Agent: N/A Land Cat.: 1,5b(vi) Reason Code: 3 MR Endorsement Date: 12-06-2015 (2) Sub Div.: 1 Mixed Feature Party: Lands D Agent: Lands D Land Cat.: 1,5b(vi) Reason Code: 59 MR Endorsement Date: 12-06-2015

(3) Sub Div.: 2 Mixed Feature Party: STT1345 Agent: N/A Land Cat.: 1 Reason Code: 3 MR Endorsement Date: 12-06-2015

### **DETAILS OF SLOPE / RETAINING WALL**

Date of Inspection: 04-01-2013

Data Source: AP

Slope Part Drainage: (1) Position: Crest Size(mm): 375

(2) Position: On slope Size(mm): 375

(3) Position: Toe Size(mm): 375

Wall Part Drainage: N/A

### **SLOPE PART**

Slope Part (1)

Surface Protection (%): Bare: 0 Vegetated: 95 Chunam: 0 Shotcrete: 5 Other Cover: 0

Material Description: Material type: Soil Geology: N/A

Berm: No. of Berms: N/A Min. Berm Width (m): N/A

Weepholes: Size (mm): N/A Spacing (m): N/A

# **WALL PART**

N/A

# **SERVICES**

### **CHECKING STATUS INFORMATION**

Tagmark: SCS\_1328 Part: O Checking Status: Others (See remarks) Checking Certificate No.: N/A

#### **BACKGROUND INFORMATION**

GIU Cell Ref.: 2SW22B4

Map Sheet Reference (1:1000): 25W-22B

Aerial Photos: 24540 (1978), 24541 (1978)

Nearest Rainguage Station

(Station Number):

Hong Shui House, Shui Pin Wai Estate(N12)

Data Collected On:

04-01-2013

Date of Construction, Subsequent

N/A

**Modification and Demolition:** 

Related Reports/Files or Documents:

File/Report: DLC/BC Ref. No.: GCMW 4/1C/2-2 PT.19 F(13,14,17,22)

File/Report: DLC/BC Ref. No.: GCMW 4/1C/2-2 PT.19 F(13,14,17,22)

File/Report: Development Ref. No.: GCMW 9068/95
Ref. No.: GCMW 9068/95

Remarks: N/A

Follow Up Actions: N/A

DH-Order (To Be Confirmed None with Buildings Department):

Advisory Letter (To Be Confirmed None with Buildings Department):

LPMIS: None


# **ENHANCED MAINTENANCE INFORMATION**

From Maintenance Department: (Last Updated Date: 26/05/2022)

### **STAGE 1 STUDY REPORT**

Inspected On: 11-03-1998
Weather: Some Rain

District: MW



Section No: 1-1

Height(m): H1:5, H2:0

Type of Toe Facility: Road/footpath with very low traffic density

Distance from Toe(m): 0.6

Type of Crest Facility: Undeveloped green belt

Distance from Crest(m): 0.6
Consequence Category: 3
Engineering Judgement: P

Section No: 2-2

Type of Toe Facility: N/A

Distance from Toe(m): 0 Type of Crest Facility: N/A

Distance from Crest(m): 0

Consequence Category: 3

Engineering Judgement: P

Sign of Seepage: Slope : No signs of seepage

Wall: N/A

Criterion A satisfied:

Sign of Distress: Slope : Reasonable (mid-portion, at toe)

Wall: N/A

Criterion D satisfied: N

Non-routine maintenance required:

Note: N/A

Masonry wall/Masonry facing: N

Note: N/A

Consequence category (for critical section): 3

Observations: N/A

Emergency Action Required: N

Action By: N/A

# **ACTION TO INITIATE PREVENTIVE WORKS**

Criterion A/Criterion D: N/A

Action By: N/A

Further Study: Y

Action By: Mixed

### OTHER EXTERNAL ACTION

Check / repair Services: N

Action By: N/A

Non-routine Maintenance: N


Action By: N/A

# <u>PHOTO</u>





Feature No. 2SW-C/C 98



### **BASIC INFORMATION**

Location: WAU FAU SIN KOON, LAU FAU SHAN, YUEN LONG

Registration Date: 06-05-1998

Ranking Score (NPRS): 0 (EI)

Date of Formation: pre-1977

Date of Construction/

Modification:

Data Source: SIRST

Approximate Coordinates: Easting: 817318 Northing: 836948

### **CONSEQUENCE-TO-LIFE CATEGORY**

Facility at Crest: Undeveloped green belt

Distance of Facility from Crest (m): 0

Facility at Toe: Undeveloped green belt

Distance of Facility from Toe (m): 0

Consequence-to-life Category: 3

Remarks: N/A

# **SLOPE PART**

(1) Max. Height (m): 9 Length (m): 62 Average Angle (deg): 40

### **WALL PART**

#### MAINTENANCE RESPONSIBILITY

(1) Sub Div.: 0 Mixed Feature Party: Lands D Agent: Lands D Land Cat.: 1,5b(vi) Reason Code: 59 MR Endorsement Date: 20-06-2012 (2) Sub Div.: 0 Mixed Feature Party: STT1345 Agent: N/A Land Cat.: 1,5b(vi) Reason Code: 3 MR Endorsement Date: 20-06-2012

### **DETAILS OF SLOPE / RETAINING WALL**

Date of Inspection: 11-02-1998

Data Source: SIRST

Slope Part Drainage: N/A

Wall Part Drainage: N/A

### **SLOPE PART**

Slope Part (1)

Surface Protection (%): Bare: 0 Vegetated: 100 Chunam: 0 Shotcrete: 0 Other Cover: 0

Material Description: Material type: Soil Geology: Decomposed granite
Berm: No. of Berms: N/A Min. Berm Width (m): N/A

Weepholes: Size (mm): N/A Spacing (m): N/A

# **WALL PART**

N/A

# **SERVICES**

#### CHECKING STATUS INFORMATION

Tagmark: SCS\_3351 Part: O Checking Status: Others (See remarks) Checking Certificate No.: N/A

#### **BACKGROUND INFORMATION**

GIU Cell Ref.: 2SW22B4

Map Sheet Reference (1:1000): 2SW-22B

Aerial Photos: 24540 (1978), 24541 (1978)

Nearest Rainguage Station

(Station Number):

Hong Shui House, Shui Pin Wai Estate(N12)

Data Collected On:

11-02-1998

Date of Construction, Subsequent

N/A

**Modification and Demolition:** 

Related Reports/Files or Documents:

File/Report: DLC/BC Ref. No.: GCMW 4/1C/2-2 pt.19 f(13,14,17,22)

File/Report: DLC/BC Ref. No.: GCMW 4/1C/2-2 pt.19 f(13,14,17,22)

File/Report: Development Ref. No.: GCMW 9068/95

Remarks: N/A

Follow Up Actions: N/A

DH-Order (To Be Confirmed None with Buildings Department):

Advisory Letter (To Be Confirmed None with Buildings Department):

LPMIS: None


# **ENHANCED MAINTENANCE INFORMATION**

From Maintenance Department: (Last Updated Date: 26/05/2022)

## **STAGE 1 STUDY REPORT**

Inspected On: 11-02-1998
Weather: Some Rain

District: MW



Section No: 1-1

Height(m): H1:9, H2:0

Type of Toe Facility: Undeveloped green belt

Distance from Toe(m): 0

Type of Crest Facility: Undeveloped green belt

Distance from Crest(m): 0
Consequence Category: 3
Engineering Judgement: P

Section No: 2-2

Type of Toe Facility: N/A

Distance from Toe(m): 0

Type of Crest Facility: N/A

Distance from Crest(m): 0
Consequence Category: 3

Engineering Judgement: P

Sign of Seepage: Slope : No signs of seepage

Wall: N/A

Criterion A satisfied:

Sign of Distress: Slope: N/A

Wall: N/A

Criterion D satisfied: N

Non-routine maintenance required: N

Note: N/A

Masonry wall/Masonry facing:  $\,N\,$ 

Note: N/A

Consequence category (for critical section): 3

Observations: N/A

Emergency Action Required: N

Action By: N/A

# **ACTION TO INITIATE PREVENTIVE WORKS**

Criterion A/Criterion D: N/A

Action By: N/A

Further Study: Y

Action By: Mixed

## OTHER EXTERNAL ACTION

Check / repair Services:

Action By: N/A


Non-routine Maintenance: N

Action By: N/A

# <u>PHOTO</u>



Feature No. 2SW-C/C 99



#### **BASIC INFORMATION**

Location: WAN FAU SIN KOON, LAU FAU SHAN

Registration Date: 06-05-1998

Ranking Score (NPRS): 0 (EI)

Date of Formation: pre-1977

Date of Construction/

Modification:

Data Source: EI(Lands D)

Approximate Coordinates: Easting: 817300 Northing: 836989

## **CONSEQUENCE-TO-LIFE CATEGORY**

Facility at Crest: Other non-crowded built-up facilities

Distance of Facility from Crest (m): 2

Facility at Toe: Lightly-used open area/facilities

Distance of Facility from Toe (m): 0

Consequence-to-life Category: 2

Remarks: N/A

# **SLOPE PART**

(1) Max. Height (m): 6 Length (m): 160 Average Angle (deg): 55

#### **WALL PART**

(1) Max. Height (m): 1 Length (m): 8.6 Face Angle (deg): 90

#### MAINTENANCE RESPONSIBILITY

(1) Sub Div.: 0 Mixed Feature Party: Lands D Agent: Lands D Land Cat.: 1,5b(vi) Reason Code: 59 MR Endorsement Date: 26-08-2010 (2) Sub Div.: 0 Mixed Feature Party: STT1345 Agent: N/A Land Cat.: 1,5b(vi) Reason Code: 3 MR Endorsement Date: 26-08-2010

## **DETAILS OF SLOPE / RETAINING WALL**

Date of Inspection: 15-05-2013

Data Source: EI(Lands D)

Slope Part Drainage: (1) Position: Crest Size(mm): 200

(2) Position: On slope Size(mm): 300

(3) Position: Toe Size(mm): 300

Wall Part Drainage: N/A

## **SLOPE PART**

Slope Part (1)

Surface Protection (%): Bare: 0 Vegetated: 100 Chunam: 0 Shotcrete: 0 Other Cover: 0

Material Description: Material type: Soil Geology: N/A

Berm: No. of Berms: N/A Min. Berm Width (m): N/A

Weepholes: Size (mm): N/A Spacing (m): N/A

## **WALL PART**

Wall Part (1)

Type of Wall: Wall Material: Concrete Wall Location: Wall at toe Berm: No. of Berms: N/A Min. Berm Width (m): N/A

Weepholes: Size (mm): 75 Spacing (m): 1.5

# **SERVICES**

N/A

## **CHECKING STATUS INFORMATION**

Tagmark: SCS\_1329 Part: O Checking Status: Others (See remarks) Checking Certificate No.: N/A

## **BACKGROUND INFORMATION**

GIU Cell Ref.: 2SW22B4

Map Sheet Reference (1:1000): 2SW-22B

Aerial Photos: 24540 (1978), 24541 (1978)

**Nearest Rainguage Station** 

Kainguage Station Hong Shui House, Shui Pin Wai Estate(N12) (Station Number):

Data Collected On:

15-05-2013

Date of Construction, Subsequent

N/A

Modification and Demolition:

Related Reports/Files or Documents: N/A

Remarks: N/A

Follow Up Actions: N/A

DH-Order (To Be Confirmed None with Buildings Department):

Advisory Letter (To Be Confirmed None with Buildings Department):

LPMIS: Agreement No.: CE48/2006 Report No.: S2R8/2009


# **ENHANCED MAINTENANCE INFORMATION**

From Maintenance Department: (Last Updated Date: 26/05/2022)

## **STAGE 1 STUDY REPORT**

Inspected On: 12-03-1998
Weather: Some Rain

District: MW



Section No: 1-1

Height(m): H1:6, H2:0

Type of Toe Facility: Lightly-used open area/facilities

Distance from Toe(m): 0

Type of Crest Facility: Other non-crowded built-up facilities

Distance from Crest(m): 2
Consequence Category: 2
Engineering Judgement: P

Section No: 2-2

Type of Toe Facility: N/A

Distance from Toe(m): 0 Type of Crest Facility: N/A

Distance from Crest(m): 0
Consequence Category: 2
Engineering Judgement: P

Sign of Seepage: Slope : Signs of seepage

Wall: N/A

Criterion A satisfied: N

Sign of Distress: Slope : Reasonable (near crest, mid-portion)

Wall: N/A

Criterion D satisfied: N

Non-routine maintenance required:

Note: N/A

Note: N/A

Consequence category (for critical section): 2

Observations: N/A

Emergency Action Required: N

Action By: N/A

# **ACTION TO INITIATE PREVENTIVE WORKS**

Criterion A/Criterion D: N/A

Action By: N/A

Further Study: Y

Action By: Mixed

## OTHER EXTERNAL ACTION

Check / repair Services: N

Action By: N/A

Non-routine Maintenance: N

Action By: N/A

#### **eLPMIS**

#### LPM/LPMit Details Report

LPM Study Feature No.: 2SW-C/C 101 Location: WAN FAU SIN KOON, LAU FAU SHAN

District Council: Yuen Long

Maintenance Responsibility (At the Time of Selection): Private Responsible Party for Maintenance of Government Portion: N/A

Private Lot No.: N/A

#### LPM/LPMit Study

Agreement No.: CE48/2006 Study Type: Stage 2 Study Consultant: Halcrow China Ltd.

GEO Managing Section / Engineer: SS / SS2

Study Status: Study completed

Design Approach: N/A

Option Assessment Accepted:  $\ensuremath{\mathrm{N}/\mathrm{A}}$ 

Study Report No.: S2R8/2009

Programme / Actual Commencement: 24-06-2008 Programme / Actual Completion: 26-03-2010

Report Recommendation (For Stage 2 Study): No action required

District Check Status: Exempted from checking

Checking Certificate No.: N/A GEO Engineer's Remarks: N/A

#### LPM/LPMit Works

Works Contract No.: N/A

GEO Managing Section / Engineer: N/A / N/A

Contractor: N/A
Progress Status: N/A

Reason of Study Termination / Works Deletion (If Necessary): N/A

Forecast Commencement Date: N/A Forecast Completion Date: N/A Completion Cert. Issued: N/A

Site Handed Over to Maintenance Department on: N/A

Estimated Cost for Upgrading (HK\$M): N/A

Maintenance Manual No.: N/A

Actual Works: N/A

No. of Tree Felled: N/A

No. of Tree Planted (Incl. Transplant): N/A

% Bare of Slope Surfacing: N/A

% Vegetated of Slope Surfacing: N/A

% Shotcrete of Slope Surfacing: N/A

Other Hard Surface of Slope Surfacing: N/A

# <u>PHOTO</u>












Feature No. 2SW-C/CR 101



#### LPM Stage 2 / 3 Study

Date

Forecast Completion Date N/A

Name	Value	
LPM/LPMit Details (CE48/2006)		
LPM Study Feature No.	2SW-C/C 101	
Location	WAN FAU SIN KOON, LAU FAU SHAN	
District Council	Yuen Long	
Maintenance Responsibility (at the time of selection)	Private	
Responsible Party for maintenance of Government portion	N/A	
Private Lot No.	$_{ m N/A}$	
LPM/LPMit Study		
Agreement No.	CE48/2006	
Study Type	Stage 2 Study	
Consultant	Halcrow China Ltd.	
GEO Managing Section / Engineer	SS/SS2	
Study Status	Study completed	
Design Approach	N/A	
Option Assessment Accepted	N/A	
Study Report No.	S2R8/2009	
Programme / Actual Commencement	24-06-2008	
Programme / Actual Completion	26-03-2010	
Report Recommendation (for stage 2 study)	No action required	
District Check Status	Exempted from checking	
Checking Certificate No.	N/A	
GEO Engineer's Remarks	N/A	
LPM/LPMit Works		
Works Contract No.	N/A	
GEO Managing Section / Engineer	N/A/N/A	
Contractor	N/A	
Progress Status	N/A	
Reason of Study Termination / Works Deletion (if necessary)	N/A	
RECORDERETINEMEDIEROM SIS	®№28/07/2022 09:11 Page 1	

Name	Value
Maintenance Manual No.	N/A
Actual Works	N/A
No. of Tree Felled	N/A
No. of Tree Planted (incl. transplant)	N/A
% Bare of Slope Surfacing	N/A
% Vegetated of Slope Surfacing	N/A
% Shotcrete of Slope Surfacing	N/A
Other Hard Surface of Slope Surfacing	N/A
Study Report	
S2R008/2009	Open Link

RECORD RETRIEVED FROM SIS ON 28/07/2022 09:11

# FEATURE NO. 2SW-C/C101 STT NO. STT1345 WAN FAU SIN KOON, LAU FAU SHAN

Prepared by HALCROW CHINA LTD

#### Disclaimer for the Release of Stage 2 Study Report

- 1. This Report summarizes the findings of a Stage 2 Study on Feature No. 2SW-C/C101.
- 2. The main objective of this Stage 2 Study is to confirm whether prima facie evidence on the feature can be established for serving a Dangerous Hillside Order under the Buildings Ordinance. This Study is not a detailed investigation to confirm whether or not the feature meets current safety standards. If the owners or the maintenance parties of the feature wish to confirm whether the feature meets current safety standards, they should engage a professionally qualified geotechnical engineer to carry out a Stability Assessment in accordance with Geoguide 5: "Guide to Slope Maintenance" published by the Geotechnical Engineering Office of the Civil Engineering and Development Department.
- 3. The information, descriptions, presentation, findings, interpretation, etc. contained in this Report are subject to a number of limitations, including but not limited to the approach used and assumptions made in the study, the methods adopted in data collection, and the site conditions at the time of inspection. The Government makes no warranty on the accuracy or correctness of any information, description, representation, findings, interpretation, etc. ("the information") in this Report.
- 4. The owners or the maintenance parties of the feature should not rely solely on the information contained herein in deciding whether or not to undertake any planning/study/construction/remedial/maintenance works or any other works which concern the safety of the feature. If they rely solely on the information contained in this Report, they are doing so entirely at their own risk. They should also obtain specialist professional advice to assist in interpreting the information provided in the Report.
- 5. The Government will under no circumstances whatsoever be responsible for or held responsible or liable for any loss or damage to any property or any injury suffered by or death occasioned to any person which may howsoever arise either directly or indirectly as a result of or incidental to using any of the information contained in this Report.

## 第二階段研究報告免責聲明

- 1. 本報告總結斜坡編號 2SW-C/C101 第二階段研究的結果。
- 2. 本第二階段研究的主要目的是確定上述斜坡有否足夠表面證據,可以根據《建築物條例》發出危險斜坡修葺令。本研究不是一項詳細勘測,以確定斜坡是否符合現行安全標準。斜坡業主或負責維修人士如欲確定斜坡是否符合現行安全標準,應聘用合資格的專業岩土工程師按照土木工程拓展署土力工程處出版的《岩土指南》第五冊:《斜坡維修指南》進行穩定性評估。
- 3. 本報告所載的資訊、描述、陳述、研究結果、詮釋等均受到若干限制。這些限制包括但不限於研究方法和所作的設定、收集數據的方法,以及勘測時場地的情況。政府不保證本報告所載的資訊、描述、陳述、研究結果、詮釋等(下稱 "資料")均準確無誤。
- 4. 斜坡業主或負責維修人士不應單憑本報告所載的資料決定是否進行任何與斜坡安全有關的規劃/研究/建造/補救/維修工程或其他工程。他們若單憑本報告的資料作出決定,須自行承擔所有風險。他們亦應向專家尋求專業意見,協助詮釋本報告所提供的資料。
- 5. 如因使用本報告所載的任何資料而直接或間接導致或引致 任何財物損失或損毀或任何人士傷亡,政府在任何情況下均無須 負責或負上任何法律責任。

## Stage 2 Study Report CHECKING CERTIFICATE **Feature No. 2SW-C/C101**

Agreement No. & Title	:	CE 48/2006 (GE)
1 161001110111 1 10. CC 1 1110	•	CL +0/2000 (GL)

10-Year Extended LPM Project

Phase 7, Package K

Stability Studies of Private Slopes

in Hong Kong and New Territories - Investigation

Stage 2 Study Report Title : Feature No. 2SW-C/C101

STT No. STT1345 Wan Fau Sin Koon,

Lau Fau Shan

Consulting Engineers : Halcrow China Ltd.

- 1. I certify that this Stage 2 Study complies with the standards and requirements set out in the Agreement and with amendments agreed by the Director's Representative.
- 2. I confirm that I have independently checked this Stage 2 Study Report. All reasonable and professional skill, care and diligence have been exercised.

Signed	
Name	Ir Gerry Daughton Independent Checking Engineer
Professional Qualifications	FHKIE FGS CGeol RPE(G)
Date	20/3/12

Agreement No. & Title

CE 48/2006 (GE)

10-Year Extended LPM Project

Phase 7, Package K

Stability Studies of Private Slopes

in Hong Kong and New Territories - Investigation

Document Title STAGE 2 STUDY REPORT

Feature No. 2SW-C/C101 STT No. STT1345 Wan Fau Sin Koon, Lau Fau Shan

Month:

March

Year:

2012

Prepared by

S T Tsui

Date

Checked and Approved by

John Luk

Date

Revision record (optional)

Date	Description	Prepared	Checked	Approved
1				
	Date	Date Description	Date Description Prepared	Date Description Prepared Checked

#### **FOREWORD**

#### **Short Term Tenancy No. STT1345**

This report presents the findings of a safety screening study carried out on Feature No. **2SW-C/C101** located at Wan Fau Sin Koon, Lau Fau Shan. Based on the relevant Systematic Identification of Maintenance Responsibility of Slopes in the Territory (SIMAR) reports, the tenants of STT1345 are responsible for the routine maintenance of the feature whereas the Lands Department (Lands D) is responsible for the upgrading and improvement of the feature.

Apart from the study feature, there are fifteen other features, namely Feature Nos. 2SW-C/C50, 2SW-C/C63, 2SW-C/C64, 2SW-C/C67, 2SW-C/C68, 2SW-C/C93, 2SW-C/C97, 2SW-C/C98, 2SW-C/C99, 2SW-C/F10, 2SW-C/F11, 2SW-C/F12, 2SW-C/F13, 2SW-C/R4 and 2SW-C/R11, also lie partly or wholly within STT No. STT1345.


The following table summarizes the study status and maintenance responsibilities of the features:

Feature No.	Included in this Safety Screening Study	Sub-division No. stated in SIMAR report	Maintenance Responsibility	Reasons for not selected for study
2SW-C/C101	Yes	·	Lands D & STT1345	-
2SW-C/C50	No	1	Lands D	G
25 W-C/C30	140	2	STT1345	0
2SW-C/C63	No	1	STT1345	G
25 W-C/C03	NO	2	DD129 Lot 771	U
2SW-C/C64	No	3 <del>.0</del> 0	STT1345	G
		1	STT1345	
2SW-C/C67	No	2	DD129 Lot1854A	G
		3	DD129 Lot1822B	
2SW-C/C68	No	-	STT1345	G
2SW-C/C93	No	-	STT1345	G
2SW-C/C97	No	-	STT1345	G
2SW-C/C98	No	j.e.	STT1345	G
2SW-C/C99	No		STT1345	G
20W C/E10	NI-	1	DD129 Lot1859	G
2SW-C/F10	No	2	STT1345	
2SW-C/F11	No	-	STT1345	G
2SW-C/F12	No	-	STT1345	G
2SW-C/F13	No	-	STT1345	G
2CW C/D4	NI-	1	DD129 Lot1857	
25W-C/K4	2SW-C/R4 No		STT1345	G
20VI O/D11	N	1	STT1345	0
2SW-C/R11	No	2	DD129 Lot1857	G

Screen-out Code:

G - Do not meet the current selection criteria for study

A location plan of the feature is shown below:



This Study was undertaken by Halcrow China Ltd. (HCL) for the Geotechnical Engineering Office (GEO), Civil Engineering and Development Department under Agreement No. CE 48/2006 (GE). The scope of the Study includes desk study, site inspection, aerial photograph interpretation and stability analysis. No ground investigation work was undertaken for the Study.

#### FEATURE STUDIED IN THIS REPORT

Feature No. **2SW-C/C101** has been assessed based on the guidelines given in the relevant Works/Development Bureau Technical Circulars, GEO Circulars and other technical publications. The results of stability analysis indicate that the feature does not satisfy the requirements for the service of a Dangerous Hillside Order in accordance with GEO Circular No. 24. According to the SIMAR report, Lands Department is responsible for the upgrading and improvement of the feature. Hence, in accordance with GEO Circular No. 30, follow-up action on this feature should be undertaken by Government as appropriate.

The tenants of STT1345 are responsible for the routine maintenance of the feature. In view of the follow-up action recommended to Government and no routine maintenance works were identified during site inspection, no statutory action is recommended to the tenants of STT1345.

#### FEATURES NOT STUDIED IN THIS REPORT

Feature Nos. 2SW-C/C50, 2SW-C/C63, 2SW-C/C64, 2SW-C/C67, 2SW-C/C68, 2SW-C/C93, 2SW-C/C97, 2SW-C/C98, 2SW-C/C99, 2SW-C/F10, 2SW-C/F11, 2SW-C/F12, 2SW-C/F13, 2SW-C/R4 and 2SW-C/R11 have not been studied as part of this Stage 2 Study as they do not meet the current selection criteria for study.

Leonard Tang

Project Director

Halcrow China Ltd.

#### 前言

短期租約編號:STT1345


本報告載有上述短期租約範圍內斜坡安全篩選勘察的資料及結果。所勘察的斜坡編號 **2SW-C/C101**位於流浮山雲浮仙館。根據相關的系統性鑑辨本港斜坡維修責任(SIMAR) 報告,短期租約編號STT1345之承租人需要負責該斜坡的例行維修,而地政總署則需要負責該斜坡的鞏固工程。

除以上斜坡外,還有十五幅擋土牆及斜坡編號2SW-C/C50, 2SW-C/C63, 2SW-C/C64, 2SW-C/C67, 2SW-C/C68, 2SW-C/C93, 2SW-C/C97, 2SW-C/C98, 2SW-C/C99, 2SW-C/F10, 2SW-C/F11, 2SW-C/F12, 2SW-C/F13, 2SW-C/R4 及2SW-C/R11的全部或部分位於短期租約編號STT1345之範圍以內。

上述斜坡的勘察和維修責任概況列於下表:

斜坡編號	有否在本研 究中進行安 全篩選勘察	SIMAR報告 的劃分編號	維修責任	不進行研 究的原因
2SW-C/C101	Yes	8.	地政總署及 STT1345	æ
2SW-C/C50	No	1	地政總署	G
25 W-C/C30	NO	2	STT1345	G
2SW-C/C63	No	1	STT1345	G
25 W -C/C03	NO	2	DD129 Lot 771	ď
2SW-C/C64	No	-	STT1345	G
		1	STT1345	
2SW-C/C67	No	2	DD129 Lot1854A	G
		3	DD129 Lot1822B	
2SW-C/C68	No	9	STT1345	G
2SW-C/C93	No	=	STT1345	G
2SW-C/C97	No	3	STT1345	G
2SW-C/C98	No	2	STT1345	G
2SW-C/C99	No	3	STT1345	G
2SW-C/F10	No	1	DD129 Lot1859	G
25 W-C/I 10	140	2	STT1345	G
2SW-C/F11	No		STT1345	G
2SW-C/F12	No	:=	STT1345	G
2SW-C/F13	No	i e	STT1345	G
2SW-C/R4	No	1	DD129 Lot1857	G
25 W-C/R4	140	2	STT1345	G .
2SW-C/R11	No	1	STT1345	G
25 W -C/K11	110	2	DD129 Lot1857	U

篩選準則:



本研究是由土木工程拓展署土力工程處委託合樂中國有限公司對私人負責維修的斜坡進行研究,顧問合約編號為 CE48/2006 (GE)。本研究內容包括資料搜查、現場視察、航空照片解譯和穩定性分析,但不包括岩土勘探工作。

#### 本報告研究過的斜坡

根據發展局/前工務局和土力工程處的技術指引及其他技術資料對斜坡編號2SW-C/C101作出穩定性評估。結果顯示根據土力工程處通告編號24,此斜坡並未符合發出危險斜坡修葺令之條件。然而,根據系統性鑑辨本港斜坡維修責任報告,地政總署應負責該斜坡的鞏固工程。因此根據土力工程處通告編號30之指引,政府應對此斜坡作出適當的跟進。

因短期租約編號STT1345的承租人只需要負責該斜坡的例行維修。鑑於已向政府建議對該斜坡作出適當的跟進,並且經過現場視察後,發現該斜坡並無作出例行維修的需要,故建議無需向短期租約編號STT1345之承租人採取法律行動。

#### 本報告未有研究過的斜坡

斜坡編號2SW-C/C50, 2SW-C/C63, 2SW-C/C64, 2SW-C/C67, 2SW-C/C68, 2SW-C/C93, 2SW-C/C97, 2SW-C/C98, 2SW-C/C99, 2SW-C/F10, 2SW-C/F11, 2SW-C/F12, 2SW-C/F13, 2SW-C/R4 及2SW-C/R11因不符合現行的選擇標準作進一步研究,故此本第二階段研究未有對這些斜坡進行研究。

簽署

鄧國樑項目總監 合樂中國有限公司

多图形

## **CONTENTS**

				Page N
	Titl	e Page		1
	FOI	REWORD	)	2
	前			5
	CO	NTENTS		8
1.	INT	RODUCT	ΓΙΟΝ	10
	1.1	Backgr	round	10
	1.2	Site De	escription	10
	1.3	Mainte	nance Responsibility (MR)	10
2.	GEO	DTECHN	ICAL INVESTIGATION	11
	2.1	Backgr	ound/Desk Study	11
		2.1.1	Aerial Photograph Interpretation (API)	11
		2.1.2	Geotechnical Engineering Office (GEO)	11
		2.1.3	Buildings Department (BD)	11
		2.1.4	Existing Services	11
		2.1.5	Geological Survey	11
		2.1.6	Past Instability	12
	2.2	Visual 1	Inspection	12
3.	GEC	TECHNI	CAL ASSESSMENT	12
	3.1	Topogra	aphy	12
	3.2	0.	y and Geological Model	12
	3.3		water Condition	13
	3.4		ters for Analysis	13
	3.5	-	y Analysis	13
	3.6	-	uence-to-Life	13
4.			OF CALCULATED FACTORS OF SAFETY	14
5.			NS AND RECOMMENDATIONS	14
6.	REFI	ERENCE:	S	14

LIST OF FIGURES
LIST OF PLATES

APPENDICES		
APPENDIX	A	SYSTEMATIC IDENTIFICATION OF MAINTENANCE RESPONSIBILITY OF SLOPES IN THE TERRITORY (SIMAR) REPORT
APPENDIX	В	AERIAL PHOTOGRAPH INTERPRETATION (API) REPORT
APPENDIX	С	PHASE 2 SYSTEMATIC INSPECTION OF FEATURES IN THE TERRITORY (SIFT) STUDY
APPENDIX	D	SIS DATA SHEET & SIS PLAN
APPENDIX	Е	BUILDING DEPARTMENT RECORD
APPENDIX	F	UTILITIES RECORDS
APPENDIX	G	PART PRINT OF 1:20 000 GEOLOGICAL MAP OF HONG KONG SHEET NO. 2
APPENDIX	Н	STABILITY ANALYSIS OF SECTION 1-1
APPENDIX	I	STAGE 2 STUDY/LPM CHECKLIST

#### 1 <u>INTRODUCTION</u>

#### 1.1 Background

This report presents a Stage 2 Study on Feature No. **2SW-C/C101** located at Wan Fau Sin Koon, Lau Fau Shan. The feature lies wholly within STT1345.

This study does not include the stability checking of Feature Nos. 2SW-C/C50, 2SW-C/C63, 2SW-C/C64, 2SW-C/C67, 2SW-C/C68, 2SW-C/C93, 2SW-C/C97, 2SW-C/C98, 2SW-C/C99, 2SW-C/F10, 2SW-C/F11, 2SW-C/F12, 2SW-C/F13, 2SW-C/R4 and 2SW-C/R11 which also lie partly or wholly within STT No. STT1345. These features do not meet the current selection criteria for study.

The location of the feature in Hong Kong Grid Reference is listed as follow:

Feature No.	Hong Kong Metric Grid Co-ordinates	
2SW-C/C101	817 300E, 836 989N	

The location of the study feature is shown in Figure 1. The boundary of the study feature has been determined from the Slope Information System (SIS) plan obtained from the Geotechnical Engineering Office (GEO), SIMAR Report from the Lands Department and observations made during the site inspection.

This Stage 2 Study commenced in December 2008. The scope of the Study includes desk study, site inspection, aerial photograph interpretation and stability analysis. No ground investigation (GI) was carried out for this study.

#### 1.2 <u>Site Description</u>

Feature No. **2SW-C/C101** is a 160m long cut slope with maximum height of about 5.5m and it is generally facing north. A footpath and an open car park are located at the crest and toe of the feature respectively. The detailed description of the feature is shown in Section 2.2 of this report.

### 1.3 <u>Maintenance Responsibility</u>

The maintenance responsibility of the study feature, according to the relevant Systematic Identification of Maintenance Responsibility of Slopes in the Territory (SIMAR) report (Appendix A), is listed as follows:

Feature No.	Sub-Division No. stated in SIMAR Report	Maintenance Responsibility	Remarks
2SW-C/C101	9.	Lands Department	Responsible for Upgrading and Improvement
		STT1345	Responsible for Routine Maintenance

## 2 <u>GEOTECHNICAL INVESTIGATION</u>

## 2.1 Background/Desk Study

# 2.1.1 <u>Aerial Photograph Interpretation (API)</u>

Aerial photographs taken between 1945 and 2006 were examined. According to the API report (Appendix B), the feature was formed between 1975 and 1976. Wan Fau Sin Koon was constructed between 1976 and 1981. No evidence of past instability relevant to the study feature was identified. No evidence of the presence of boulders or natural drainage path affecting the study feature could be identified.

## 2.1.2 <u>Geotechnical Engineering Office (GEO)</u>

Phase 2 Systematic Inspection of Features in the Territory (SIFT) Study was carried out on the feature by the SIFT Consultant for the GEO in January 1998 (Appendix C). The report indicates that the feature (SIFT No. 2SW-22/B-S11) was formed between 1976 and 1978.

The SIS data sheet, SIS plan and Stage 1 Study Report for the study feature obtained from GEO are enclosed in Appendix D.

## 2.1.3 Buildings Department (BD)

There is no BD file relevant to the study feature. Copy of the correspondence from the BD stating that no records of approved building works on the subject Lot is enclosed in Appendix E.

#### 2.1.4 Existing Services

Drainage Services Department (DSD) and Water Supplies Department (WSD) were requested to provide information on existing utilities/services located within or in the vicinity of the feature. With reference to the DSD record plan, there is storm water drain running along the toe of the study feature. With reference to the WSD record plan, there are no fresh water mains within or in the vicinity of the feature. The existing services plans are enclosed in Appendix F.

Water pipes located within the vicinity of study feature were noted during the site inspection. As no signs of leakage were observed, no leakage investigation is required.

#### 2.1.5 Geological Survey

Based on the 1:20 000 Geological Map of Hong Kong Sheet No. 2 published by The Hong Kong Government (Appendix G), the area concerned is mainly underlain by finegrained granite (gf).

#### 2.1.6 Past Instability

No record of past instability related to the feature was identified from the available documents or files maintained by BD/GEO.

## 2.2 <u>Visual Inspections</u>

Visual inspections on the study feature were carried out in December 2008 and February 2012 respectively.

At the time of inspection in December 2008, the study feature was a 160m long cut slope and it was generally facing north. The maximum height of the slope was about 5.5m and the average slope angle was about 50°. The feature was mainly covered with vegetation exc(Plates 1 & 2). There was a 0.5m high concrete retaining wall located at the toe of the western portion of the feature. A 300mm U-channel was running along the toe of the wall. There were water mains running along the slope crest and across the slope with no signs of leakage observed. An open car park and a horticulture garden were located in front of the western and eastern portion of the feature respectively. There was a footpath located at the crest of the western portion of the feature (Plate 3) whereas a densely vegetated open area was located at the crest of the eastern portion of the feature. No signs of seepage or distress were noted during site inspection.

At the time of inspection in March 2011, no changes of the feature were observed except the western end portion of the feature was being modified with a new structure being constructed at its crest (Plates 4 & 5). No signs of seepage or distress were observed during the site inspection.

## 3 GEOTECHNICAL ASSESSMENT

#### 3.1 Topography

Section 1-1 was selected for the stability analysis of the feature and the location of this section is shown in Figure 2. The location of this section is shown in Figure 2. The profile of this section was determined through direct measurement taken on site.

Section 1-1 consists of a slope of about 5.5m in height with a slope angle of  $50^{\circ}$  (Figure 3).

## 3.2 <u>Geology and Geological Model</u>

Based on the 1:20 000 Geological Map of Hong Kong (Appendix G), the area concerned is mainly underlain by fine-grained granite.

According to our site inspection, the study feature was mainly composed of completely decomposed granite (CDG). Hence, the study feature was assumed to consist of CDG only. The inferred geological profile for Section 1-1 is shown in Figures 3.

#### 3.3 Groundwater Condition

No groundwater monitoring records exist for the study feature and no signs of seepage were observed on site. A groundwater level at one-third of the slope height was adopted to account for 1 in 10 year return period of rainfall.

#### 3.4 Parameters for Analysis

In the absence of any relevant soil laboratory test data for the study feature, the slope material was inspected on site and it was found to be CDG. A shear strength parameters of c' = 5 kPa and  $\phi' = 35^{\circ}$  which equal to the lower bound values of CDG as stipulated in Table 8 of the Geoguide 1, was conservatively adopted in this study. A summary of soil parameters adopted for stability analysis is tabulated below:

Soil Material	Shear Streng	th Parameters	Bulk Unit Weight
	c' (kPa)	φ' (°)	$\gamma (kN/m^3)$
CDG	5	35	19

#### 3.5 Stability Analysis

Slope stability analysis was carried out for Section 1-1 based on the inferred geological model, groundwater condition and shear strength parameters as discussed in Sections 3.2 to 3.4. Surcharge of 5kPa was applied at the crest of the feature to represent the loading of the footpath. The Morgenstern-Price Method in SLOPE/W Version 6.2 (BD reference No. G0138) was used for the stability analysis. The calculated Factor of Safety (FOS) are tabulated below:

Section	Slip Surface No.	FOS
1-1	1	1.404
	2	1.331
	3	1.384

The results of stability analysis for Sections 1-1 are presented in Figures 3 and the computer outputs of the stability analysis are enclosed in Appendix H.

#### 3.6 Consequence-to-life

The consequence-to-life in the event of failure has been assessed in accordance with Table 3 of WBTC No. 13/99 and GEO Technical Guidance Note No. 15 (TGN 15). The feature has been assessed as Category 2 as failure of the feature would affect the open car park and horticulture garden at its toe.

## 4 <u>DISCUSSION OF CALCULATED FACTORS OF SAFETY</u>

In accordance with Criterion F as stated in GEO circular No. 24, the FOS calculated from a stability assessment without site-specific GI for slope having significant consequence-to-life in the event of failure shall not be less than 1.20.

The results of the slope stability analysis for Section 1-1 indicate that the calculated minimum FOS is 1.331.

## 5 <u>CONCLUSIONS & RECOMMENDATIONS</u>

Feature No. **2SW-C/C101** does not satisfy the requirements for the service of a Dangerous Hillside Order in accordance with GEO Circular No. 24. According to the SIMAR report, Lands Department is responsible for the upgrading and improvement of the feature. Hence, in accordance with GEO Circular No. 30, follow-up action on this feature should be undertaken by Government as appropriate.

The tenants of STT1345 are responsible for the routine maintenance of the feature. In view of the follow-up action recommended to Government and no routine maintenance works were identified during site inspection, no statutory action is recommended to the tenants of STT1345.

The extent of the feature subject to follow-up action by Government is coloured blue in Figure 4.

#### 6 REFERENCES

Geotechnical Engineering Office (1998). <u>Phase 2 Systematic Inspection of Features in the Territory</u> (Phase 2 SIFT) Study.

Geotechnical Engineering Office (1984). <u>Geotechnical Manual for Slopes</u>. (Second Edition)

Geotechnical Engineering Office (1993). <u>Geoguide 1 : Guide to Retaining Wall Design.</u>

GEO Circular No. 24 (2010). <u>Dangerous Hillside Orders and Advisory Letters</u>.


GEO Circular No. 30 (2009). <u>Stage 1 and Stage 2 Geotechnical Studies of Slopes and Retaining Walls.</u>


Work Bureau Technical Circular No. 13/99. <u>Geotechnical Manual for Slopes - Guidance on Interpretation and Updating.</u>


GEO Technical Guidance Note No. 15 (TGN 15). <u>Guidelines for Classification of Consequence-to-Life Category for Slope Features.</u>

# LIST OF FIGURES

Figure No.	
1	General Location Plan
2	Location Plan of Section
3	Geological Profile and Stability Analysis of Section 1-1
4	Action To Be Taken







### LEGEND:

① SLIP SURFACE NO. 1 (NO. 1 OF 3)

{CDG} COMPLETELY DECOMPOSED GRANITE

### ADOPTED SOIL PARAMETERS

SOIL	c'(kPa)	ø'(°)	¥(kN/m³)		
CDG	5	35	19		

SLIP SURFACE NO.	FOS
1	1-404
2	1.331
3	1.384


0 1 2m Scale

Civil Engineering and Development Department Geotechnical Engineering in Office Agreement No. CE48 / 2006 (GE)
10-Year Extended LPM Project
Phase 7, Package K
Stability Studies of Private Slopes
in Hong Kong Island and New Territories
— Investigation

GEOLOGICAL PROFILE & STABILITY ANALYSIS OF SECTION 1-1


# Scale 1:100 Date JAN. 09 Figure No.

26 -



### LIST OF PLATES

Plate No.	
PH/01	Direction of Plates
1	Side View of the Western Portion of the Feature (Photo Taken in December 2008)
2	General View of the Eastern Portion of the Feature (Photo Taken in December 2008)
3	Crest View of the Western Portion of the Feature (Photo Taken in December 2008)
4	Side View of the Western Portion of the Feature (Photo Taken in February 2012)
5	General View of the Western End Portion of the Feature (Photo Taken in February 2012)





AGREEMENT NO. CE 48/2006 (GE)

10-YEAR EXTENDED LPM PROJECT, PHASE 7, PACKAGE K

SIDE VIEW OF THE WESTERN PORTION OF THE FEATURE (PHOTO TAKEN IN DECEMBER 2008)





AGREEMENT NO. CE 48/2006 (GE) 10-YEAR EXTENDED LPM PROJECT, PHASE 7, PACKAGE K

**Halcrow** 

GENERAL VIEW OF THE EASTERN PORTION OF THE FEATURE (PHOTO TAKEN IN DECEMBER 2008)



AGREEMENT NO. CE 48/2006 (GE)

10-YEAR EXTENDED LPM PROJECT, PHASE 7, PACKAGE K

**Halcrow** 

CREST VIEW OF THE WESTERN PORTION OF THE FEATURE (PHOTO TAKEN IN DECEMBER 2008)



AGREEMENT NO. CE 48/2006 (GE) 10-YEAR EXTENDED LPM PROJECT, PHASE 7, PACKAGE K

**Halcrow** 

SIDE VIEW OF THE WESTERN PORTION OF THE FEATURE (PHOTO TAKEN IN FEBRUARY 2012)



AGREEMENT NO. CE 48/2006 (GE)

10-YEAR EXTENDED LPM PROJECT, PHASE 7, PACKAGE K

**Halcrow** 


GENERAL VIEW OF THE WESTERN END PORTION OF THE FEATURE (PHOTO TAKEN IN FEBRUARY 2012)

### APPENDIX A

SYSTEMATIC IDENTIFICATION OF MAINTENANCE RESPONSIBILITY OF SLOPE IN THE TERRITORY (SIMAR) REPORT

## **Slope Report**

### FOR IDENTIFICATION PURPOSES ONLY



Slope Number

2SW-C/C101

IASMP01001

### **SIMAR REGISTER**

13/03/2012 03:50 PM

Slope No.	Slope Sub- division No.	Location	Responsible Lot(s) / Party(s)	Maintenance Agent	Slope Plan*	Remarks
2SW-C/C101		WITHIN STT1345	Lands D	Lands D	as per the attached	For enquiries about the maintenance of this slope / sub-division of the slope, please contact the Maintenance Agent direct.
2SW-C/C101		WITHIN STT1345	STT1345	N/A	as per the attached	

### - End of Report -

<sup>\*</sup> Note: (i) The attached slope plan(s) are for the purpose of identification of the slope(s) only.

<sup>(</sup>ii) The slope(s) mentioned in the Register may not be shown in the attached slope plan(s).

## APPENDIX B

**AERIAL PHOTOGRAPH INTERPRETATION (API) REPORT** 

# API Report on Feature No. 2SW-C/C101 Wan Fau Sin Koon, Lau Fau Shan

### 1. <u>Summary</u>

Feature No. **2SW-C/C101** is located at Wan Fau Sin Koon, Lau Fau Shan. The available aerial photographs taken between the years 1945 and 2006 were examined. From the available aerial photographs, the study feature was formed between 1975 and 1976. No evidence of past instability relevant to the study feature was identified. No evidence of the presence of boulders or natural drainage path affecting the study feature could be identified.

### 2. Site History

The following site history has been interpreted from the available aerial photographs from 1945 to 2006:

	Year	Observation					
2.1	1945	Feature No. <b>2SW-C/C101</b> had not been formed. Agricultural fields were observed at the study area.					
2.2	1949-1975	No significant changes to the study area were observed.					
2.3	1976	Feature No. <b>2SW-C/C101</b> was formed by cutting and a large open space was observed at the toe of the feature. Wan Fau Sin Koon had not been constructed yet.					
2.5	1978-1979	No significant changes to the feature were observed. Construction work of the Wan Fau Sin Koon was in progress. Buildings were observed to the north of the feature.					
2.6	1981	No significant changes to the feature were observed. Construction work of the Wan Fau Sin Koon was completed.					
2.7	1982	No significant change to the feature was observed.					
2.8	1983	No significant change to the feature was observed.					
2.9	1984	No significant change to the feature was observed.					
3.0	1985-1990	No significant change to the feature was observed.					
3.1	1991-1995	No significant change to the feature was observed.					
3.2	1996-2000	No significant change to the feature was observed.					

- 3.3 2001-2003 No significant change to the feature was observed.
- 3.4 2004-2006 No significant change to the feature was observed.

### 3. <u>Past Instability</u>

No past instability was observed from the aerial photographs.

### 4. <u>Boulders</u>

No boulders could be identified from the aerial photographs.


### 5. Surface Hydrology

No natural drainage path could be identified from the aerial photographs.

## List of Photographs viewed

# Stage 2 Study <u>Feature No. **2SW-C/C101**</u> <u>Wan Fau Sin Koon,</u> <u>Lau Fau Shan</u>

Year	Photograph No.
1945	Y00856-57
1949	Y02482-84
1954	Y02871-72
1963	Y09685-86
1964	Y13057-58
1973	7919-20
1974	10007-08
1975	11926-27
1976	16028-29
1978	20634-24541
1979	28473-74
1981	39309-10
1982	42873-74
1983	51432-33
1984	55783-84
1985	A01821-22
1986	A07454-55
1987	A10788-89
1988	A15844-45
1989	A19110-11
1990	A24264-65
1991	A28189-90
1992	A30616-17
1993	CN4997-98
1994	A38458-59
1995	CN9808-09
1996	CN16471-72
1997	CN17703-04
1998	CN20232-33
1999	CN22500-01
2000	CN26487-88
2001	CW31518-19
2002	CW40524-25
2003	CW46743-44
2004	CW61699-700
2005	CW64095-96
2006	CS04094-95




## APPENDIX C

PHASE 2 SYSTEMATIC INSPECTION OF FEATURES IN THE TERRITORY (SIFT) STUDY

# PHASE 2 SYSTEMATIC INSPECTION OF FEATURES IN THE TERRITORY (SIFT 2 Version 4.5)

900

SIFT No: 25W - 22 R - SI GEO Reg. No: Grid Ref. : See - Table 4 in SIFT I	Report
Location: Above Monastery	
1. Registration Criteria from GEO Circular 7/93:  P. greater than 3m high F. or FR greater than 5m high.  Part of Larger	
is distance from the party of the distance ment and the distance m	
of the less than 3m light watch pose a direct risk to the in the cross of the less than 3m light watch pose a direct risk to the in the cross of the less than 3m light watch pose a direct risk to the in the cross of the less than 3m light watch pose a direct risk to the in the cross of the less than 3m light watch pose a direct risk to the light watch pose a direct risk t	
Cor CR greater than 3m high.	
WC (Work Complete) WIP (Work In Progress) Date:, registerable features may be present.	
ADT (Abandoned Disturbed Terrain), Type	
OTHER	
2. SIFT Classification: from Guidelines for Phase 2 SIFT Version 3.1 and Addendum 5	
Aerial Photograph Year and Number (978 24540 - 41	
Class A Fill feature considered to have similar circumstances to the Baguio landslide site.	
Class B Fill feature considered to meet GEO criteria for slope registration bet does not meet criteria A.	
B1 Have been formed or substantially modified before 30.6.78 or to have been illegally formed after 30.6.78.	
B2 Have been formed or substantially modified after 30.6.78, studied to GEO Stage 2, or equivalent or to be Housing Dept. Feature.	
and the state of t	
Class C Cut feature considered to meet GEO criteria for slope registration.	
CI Have been formed or substantially modified before 30.6.78 or to have been illegally formed after 30.6.78.	
C2 Have been formed or substantially modified after 30.6.78	
*	
Formation/Medification before Confirmed by API	
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
erafter 30.6.78 determined by:- Assumed (Reason: Construction Detulen 17.76 19.76)	
3. Consequence: (Modified B&P Assessment of Risk for A, B1 only. See Section 4 below for details.)	
	y High
Low Low to moderate Moderate Moderate to High	
4. Modified B&P Assessment of Risk: (For Class A.B1 only)	
4. Wodined Del Assessment of Rose . (to class rast any	
4.1 Feature Dimensions	•
Estimated Slope Height m. Estimated Slope Length m. Estimated Slope Gradient Estimated Slope Height Estimated Slop	
Estimated Retaining Wall Height m. Estimated Max. Fill Width m. Estimated Fill Thickness  Part of Larger Fill Body? (Y/N)	
Total Height of Featurem. Part of Larger Fill Body? (1774)	
VOIDING CARCUIATION	
4.2 Estimated critical section profile: circle the appropriate model below or draw others as appropriate.	
A C E G FW	
FILL FILL	
D E HI J	
FILE SILL SILL SILL SILL SILL SILL SILL S	
Via December 4 Planas Signe	
4.3 Topographic Situation Adjacent / Traversed : Drainage Line / Topographic Depression or Spurline / Planar Slope	
Catchment area: (1=<100m², 2=100-500m², 3=500-1000m², 4=1000-10000m², 5=>10000m²)	
To Fill Body To Drainage Line (if Affected Structure located downstream)	
Intervening Ground, feature to facility: Platform / Slope / Drainage Line . Natural / Cut / Fill . Vegetation (Y / N)	
Debris Trail: Channelisation; Spread; Erosion and Entrainment; Assumed to occur along debris trail	
4.4 Facilities	
Facility(ies) below feature.  Bus Shelter (Y / N)  Bisson Biss Shelter (Y / N)	•
Facility Distance, Plan m, Vertical m, Angle m,	
Facility	
Facility(ies) on slope/platform of feature: road / building / other	
4.5 Consequences of Slope Failure / Remarks :	
Compiled by P.A.Spiers API CONSULTANT/ 17 dated January 14	1998
Complete of	
TELS.NIFTEMAS.VI	



# APPENDIX D SIS DATA SHEET & SIS PLAN

printed on: 03-07-2008 15:40

**BASIC INFORMATION** 

Feature Ref. No. :

2SW-C/C 101

Location: WAN FAU SIN KOON, LAU FAU SHAN

**Approximate Coordinates** 

Northing: 836989

Easting

817300

SLOPE PART

Max. Height (m): 6

Length (m):

160

Avg. Angle (deg): 55

WALL PART

Max. Height ( m ):

Length (m):

CONSEQUENCE-TO-LIFE CATEGORY

Facility at Crest: Road/footpath with very low traffic density

Distance of Facility from Crest (m): .3

Facility at Toe:

Open car park

Distance of Facility from Toe ( m ):

Consequence-to-life Category: 2

Sift Class:

**C**1

Remark:

NIL

Maintenance Responsibility:

Sub Div. No: 0

Main. Parties: STT1345

printed on: 03-07-2008 15:40

Other Information

Feature Ref. No.:

Improved by

2SW-C/C 101

**CNPCS: 2.86** 

SIFT Ref.: 2SW-22B/S 11

CNPCS Source: SIRST record: Provided by SIRST Consultants

**ENHANCED MAINTENANCE** 

Upgraded by

Prescriptive Design Using GEO Report No. 56

Non-prescriptive Design including Conventional Design

Type 1/Type 2 Prescriptive Measures Type 3 Prescriptive Measures (not up to upgrading standard)

Actual Completion Date

**NULL** 

NULL

NULL

**NULL** 

**NULL** 

DADS

**DH Order** 

Recommendation Date Served Date Defaulted Date Lot Address **NULL** 

NULL

**NULL** 

**NULL** 

File Reference Notice No. NULL NULL

Discharged Date NULL

**Advisory Letter** 

Recommendation Date | Served Date | Lot Address **NULL** 

NULL NULL File Reference NULL

Status of Letter

NULL

**CHECKING STATUS** 

Relevant Files:

Part: **NULL**  **Checking Status:** 

NULL

LPMIS

Agreement No.: CE48/2006

Study Type: Stage 2 Study

**GE/Consultant:** Halcrow

Study Status:

Study has not commenced yet

Report No.:

**Draft Report Date:** 

**Study Completion Date:** 

Recommendation:

Remarks:

**LPM Contract No.:** 

**Works Status:** 

**Works Commencement Date:** 

**Works Completion Date:** 

Type of Upgrading Works:

**Drawing No.:** 

Maintenance Manual No.:

printed on: 03-07-2008 15:40

Slope / Wall Detail Data

Feature Ref. No. :

2SW-C/C 101

### SLOPE PART

Material Description: Material Type:

Soil & Rock

Geology:

Decomposed granite

Dimensions:

Max. Height (m):

Length (m):

160

Average Angle (deg): 55

No. of Berms:

Min. Berm Width (m):

Surface Protection:

% Bare:

70

% Shotcrete:

0

% Vegetated:

30

% Other Cover:

0

% Chunam:

0

Weepholes:

Size (mm):

Spacing (m):

Drainage:

Type

Size (mm)

NULL

NULL

### **WALL PART**

NULL

### **SERVICES**

Utilities Type	Size	Location	Remark
Water Main	80	On crest	
Electricity		On crest	Size cannot be determined
Water Main	80	On slope	
Electricity		On slope	Size cannot be determined

STAGE 1 STUDY REPORT FOR C, CR AND R FEATURES   Feature Reference No.: 2SW-C/C 101											
Location WAN FAU SIN KOON, LAU FAU SHAN											
Inspected by : Chan, W.L. on 12 MAR 1998 Weather Some Rain District MW GE Area :											
Inspected by : Chan, W.L.  on 12 MAR 1998 Weather Some Rain  District MW GE Area:  CAR ASS  PARK  SECTION 1-1											
Section No.	Heig H1	ght (m)	Type of	f Toe Facility	Distance from Toe (m)	Type of Crest Fac	ility	Distance from Crest (m)	Conseque   Category		Engineering Judgement#
1-1	6	0	Open ca	arpark	.5	Road with very lo	ow traffic	.3	2		P
Slope : Sign	Sign of Seepage: Slope: Yes Slope: Signs of seepage NO Sign of Distress: Slope: Reasonable (near crest, mid-portion) Criterion D satisfied? NO										
Note:	Non-routine maintenance required: NO Masonry wall/Masonry facing? NO Consequence category (for critical section):							egory (for ical section) :			
Observati	ons :										
Emergen	cy act	ion re	quired	NO	Private :	BD	Govern	ment :			
Action to preventive Study				Criterion A/ Criterion D	Action by	Private Government	Furth Study		Action by	Gove	te Owner(s)
Other ex	terna	l actior	1	Check/repair service		]	Engineer In		Governme		Maintenance
		034	greed :	Action b	У	Post :	<b>✓</b>		Date :		

### Legend & Notes for Stage 1 Study Report Form

### Legend:

- H1 Critical height relative to the structure at risk.
- H2 Height of lowest daylighting point for realistic slip surface above the toe of the slope (at the same location as the "Critical Height"). This should be used to estimate the "Effective Height" of the slope for Criterion D of GEO Circular No. 4/97.
- # For definition of Engineering Judgement and Consequence Category, refer to SIRST Procedural Manual.
- + Criterion A There are significant signs of distress, or visual or documented evidence of continuing harzardous movement, of a landslip, slope, excavation, retaining structure, boulder or rock fragment.
- +++ Criterion D Only applicable for soil cut slopes in weathered granite or tuff having an effective height and mean slope inclination (at the critical section) failing within the hatched zone shown on Figure 1 of GEO Circular No. 4/97. Effective height is the difference in elevation between the crest and the lowest daylighting point of realistic slip surfaces. The use of this criterion can be applied to sites located in the rock formation given in Appendix E of the Procedure Manual for Slope Cataloguing.

### Notes:

- 1. The appropriate recommendation(s) should be made from observations made during the Stage 1 Study, indicating either one or a combination of the following:
  - (a) Emergency Action Emergency action should be recommended for those features which have shown signs of immediate danger. For private features, emergency works are implemented by the Buildings Department (BD) through their Emergency Contractor to ensure public safety. For Government features, urgent repair works are carried out by the maintenance department as stipulated in LWBTC 9/87.
  - (b) Action to Initiate Preventive Works/Study
    - (i) For private features involving a significant risk to life or serious damage to property and whose conditions satisfy either Criterion A or Criterion D as stpulated in GEO Circular No. 4/97, DH Order should be recommended to BD for them to initiate study/preventive works. Advisory Letter should be recommended for cases not involving a significate risk to life or serious damage to property. For public features which satisfy Criterion A or Criterion D, GEO should initiate urgent repair works and/ or LPM works if needed.
  - (ii) Further study should be recommended for the features unless preventive measure are not necessary.
  - (c) Other ExternalAction This falls under actions not normally resulting in preventive works/study.
  - (i) Check/repair Service Advise the responsible party to check/repair an suspected leaking water carrying services.
  - (ii) For features which the inspecting GE considers no further study is needed including for features requiring maintenance works (including preventive maintenance) as covered by Engineer Inspection, the Engineer Inspection box should be ticked but the action is assumed to be taken by the owners (both public and private) since Engineer Inspection is required for all features; Geoguide on Slope Maintenance and/or WBTC 9/96.
  - (iii) Non-routine maintenance refers to maintenance works which the inspecting GE considers needs to be implemented within the next 12 months to prevent deterioration of the slope to a point when it could become dangerous. For more urgent works, the inspecting GE should qualify in the Notes box that the works should be implemented either ASAP or before the onset of wet season. For private features, the private owners should be informed through issue of Advisory Letter by BD. For public features, the responsible department should be informed of the recommendation.

2SW-C/C 101

Date Taken




2SW-C/C 101

GENERAL VIEW

F20

Geotechnical Engineering Office - Civil Engineering and Development Department



# APPENDIX E BUILDING DEPARTMENT RECORD



VOUR REF SHIPS

OUR REF 本署檔號 FAX 圖文傳真 08110804

TO/SSSK/11.1/8141031

TEL WWW.bd.gov.hk

2625 4367 2626 1207

Fax No.: 28278352

Tsui Shing Tin Level 10 Millennium City 6 392 Kwun Tong Road



7 November 2008

Dear Sir/Madam,

Application for Inspecting Building Records/One Stop Service

Application Number: 08110804 Address of Building: STT1345

We refer to your above application and regret to inform you that the Buildings Department (BD) does not have the requested records of the subject building for the following reason(s):

- 8. There is no such record of approved building works on the subject lot / land.
- 2. For any queries about your application, please contact us at 2626 1207.

Yours faithfully,


Building Information Centre Buildings Department


Note: To save paper, we will provide Chinese translation of this letter only on request. Please contact us at 2626 1207 for details. 為節省用紙,現只提供英文本。如需要中文譯本,請撥電 2626 1207與我們聯絡。
This computer print-out requires no signature.

此乃電腦文件、母須簽署。

BIC-SL 4 (Rev. 5/2008)


# APPENDIX F UTILITIES RECORDS





## APPENDIX G

PART PRINT OF 1:20 000 GEOLOGICAL MAP OF HONG KONG SHEET NO. 2



## HONG KONG GEOLOGICAL SURVEY

香港地質調查

## SAN TIN 新田

## Sheet 2 編號

#### SOLID AND SUPERFICIAL GEOLOGY 基岩和表土地質圖

Series HGM20 組別 Scale 1:20 000 比例


#### SUPERFICIAL DEPOSITS 表土沉積

		GENETIC CLASSIFICATION OR NAMED DIVISIONS	成因類型 或地層名稱	主要物質成份	PRINCIPAL MATERIALS
		Fill; sanitary fill ( Qfs )		细泥和废物	Natural earth and waste
		Alluvium	沖積物 Qa	分通性夏好至中等的 粘土、粉砂、砂和礫石	Clay/silt, sand and gravel well-sorted to semi-sorted
	of her	Estuarine deposits	··河口潤沉積 Qan	粘土質粉砂或砂	Clayey silt or sand
, W		Beach deposits ······	海灘沉積 Qb	8	Sand
全新就 HOLOCENE	{	Raised beach deposits	高位海灣沉積 〇四	<i>b</i>	Sand
	HAAU		ОНН	主要為深灰色海相泥(未分)…	
+7	HANG	MANUFACTURE BY	ms	海相砂・部份粉砂質	Marine sand, part silt
<b>新</b> 第 第					
1 7 4 ( )					
夏斯-全新税 PLESTOCENE AND HOLOCENE		Debris flow deposits	坡積、洪稜物 Qd	未分遷的砂、鞣至濃鞣、 基質為粘土/粉砂	Unsorted sand, gravel, cobbles and boulders; clay/silt matrix
		Debris flow deposits	坡積、洗貨物 Qd	参复典格工/初步 	Unsorted sand, gravel, cobbles and boulders; clay/silt matrix  Clay/silt, gravelly sandy well-sorted to semi-sorted
同当 PLES AND I	THE STATE OF THE S		·····································	◆養養	and boulders; clay/silt matri Clay/silt, gravelly sandy well-sorted to semi-sorter
	於關係 K LAP KOK RMATION	Terraced alluvium ·····	·····································	分選性及好至中等的 器質、砂質粘土/粉砂 未分磨:夾中聯和源號的 器質、粘土質物砂/砂	and boulders; clay/silt matrix  Clay/silt, gravelly sandy  well-sorted to semi-sorter

#### SOLID GEOLOGY 基岩地質

	SI	EDIMENTARY AND VOLCANIC ROCKS	沉積岩和火山岩		
		NAMED ROCK DIVISIONS 地層單位名稱	主要岩石類型/特徵 PRINCIPAL ROCK TYPES/CHARACTERS		
中 生 界 MESOZOIC	L B W H CRETACTEOUS	Kat' O Formation 查询图	Breccla with conglomerate Breccia with conglomerate and coarse-grained sandstone		
	上体腰桩 UPPER JURASSIC ※本種類	Tai Mo Shan Formation, 大帽山祖(未分) UTM undivided	個火山灰晶屑豪灰岩 Coarse ash crystal tuff 砂岩 Sandstone		
古生界 PALAEOZOIC	AR AR	Lok Ma Chau Formation, undivided 港島湖鄉(未分)  Yuen Long Formation, undivided 元帥鄉(未分)	千枚岩、變質粉砂岩灰 Phyllita, metasiltstone with 數質砂岩和石星片岩 metasandstone and graphite schist		
ا≧رد	MA ∫ Š'∪ <b>ﷺ</b> `	JOR INTRUSIVE IGNEOUS ROCKS ±9	學侵入火成岩		

# APPENDIX H STABILITY ANALYSIS OF SECTION 1-1



#### Section 1-1.fac

DATESTAMP 1/7/2009 TIMESTAMP 9:44:00 AM 3=METHOD 3=NO. OF SLIP SURFACES 1=NO. OF RADII 2=SIDE FUNCTION TYPE -734.5000=X-COOR. 556.0000=Y-COOR. COMPUTED AXIS SLIP X-**ITERATION FACTOR OF SAFETY** NO. COORD. COORD. **RADIUS** NO. LAMBDA (MOMENT) (FORCE) 1 -734.500556.000 907.227 0.0000 1.3139058 1.5704787 907.227 907.227 1 -734.500 556.000 6 0.0000 1.3666962 1.3628470 -734.500 556.000 1 3 -0.25001.4041532 1.4069983 2 -734.500 556.000 907.558 1 0.0000 1.4209506 1.2206115 2 2 3 -734.500 556.000 907.558 0.0000 1.2979275 1.2943115 907.558 907.919 907.919 -734.500 556.000 3 1.3314194 1.3332040 -0.25001.2436726 -734.500 1.4492883 556.000 1 0.0000 3 -734.500 556.000 4 0.0000 1.3483138 1.3414110 -734.500 556.000 907.919 1.3842808 1.3855355 -0.2500| SUMMARY OF MINIMUM FACTORS OF SAFETY | MOMENT EQUILIBRIUM: FELLENIUS OR ORDINARY METHOD -734.5000=X-COOR. 556.0000=Y-COOR. 907.5578=RADIUS 1.2206115=F.S. 2=SLIP# MOMENT EQUILIBRIUM: BISHOP SIMPLIFIED METHOD -734.5000=x-COOR. 556.0000=Y-COOR. 907.5578=RADIUS 1.2979275=F.S. 2=SLIP# FORCE EQUILIBRIUM: JANBU SIMPLIFIED METHOD (NO fo FACTOR) -734.5000=X-COOR. 556.0000 = Y - COOR. 907.5578=RADIUS 1.2943115=F.S. 2=SLIP# MOMENT AND FORCE EQUILIBRIUM: MORGENSTERN-PRICE METHOD -734.5000=x-coor. 556.0000=Y-COOR. 907.5578=RADIUS 1.3314194=F.S. 2=SLIP# NORMAL TERMINATION OF SLOPE MOST\_CRITICAL # SLIP\_SURFACE # \_\_\_\_\_\_ SLIP\_SURFACE # **AUTOTENSIONELEV** 

\_\_\_\_\_\_

# APPENDIX I STAGE 2 STUDY/LPM CHECKLIST

## SS-F-02 Sample Stage 2 Study General Checklist

Proj	eet En	gincer: John Luk Section: 1	-1	
Prep	ared l	y: S. J. JSUI Date: 24/	11/2008	
(A)	Ma	aintenance Responsibility (MR)	Yes	No
	(a)	There is doubt that sub-lots have not been identified by SIMAR If yes, check land status at Lands Dept/Land Registry & draw GEO, CES/EM, Lands D attention to the issue		
	(b)	Doubt over SIMAR findings. (please specify)		
		If yes, draw GEO, CES/EM, Lands D attention to the issue		
	(c)	It appears that the government portion of the feature was formed by the lot owners based on API/site setting but withou documentary evidence If yes, draw GEO and maintenance department's attention to the issue		
	(d)	Urgent repair / maintenance works were carried out by government authority on private MR feature If yes, clarification should be made in Stage 2 Study Repor (S2R)	<u> </u>	
(B)	Dis	screpancy between GEO's records/actual condition		
	(a)	Feature boundary		
	(h)	Feature type		
	(c)	Geometry		
	(d)	Affected facilities		
	(c)	Others (please specify)		
		if yes to any items above, address in S2R & notify relevan division of GEO	ţ	
(C)	Des	sk Study		
		cord, files & previous studies related to adjacent features/lots- cked & reviewed		
(D)	Sta	bility Assessment		2
	(a)	Any site-specific GI data including laboratory testing results If no, soil strength parameters for sensitivity analyses should be determined by an experienced engineer based on site-specific assessment. Critical review/discussion on sensitivity analyses results should be performed by the experienced engineer		
		Stage 2 / LPM Feature No. 2SW -	C/CIDI	
	- (	General Checklist (Sheet Lof 2) Location : WANTEN &	AL DONALLA	1112 1111

Project Eng	gineer: John Luk	Section:	-
Prepared by		Date:	24/11/2008
(b)	Extraordinarily high groundwater table water stain or signs of dampness obsertif yes, the adopted groundwater table	ved	Yes No
(c)	an experienced engineer	ature	
(d)	Any recorded/unrecorded water carry in within the vicinity of the feature. If yes, address the effect of potent whether leakage investigation is required.	tial leakage & state	
(e)	If all existing beneficial factors, such a wall friction & existing structural residuly considered	·	
(f)	Have adjoining features been consider integrated approach in the stability ass		
(g)	The study feature consists of Fill slope If yes, address liquefaction potential in		
(h)	Justification of geological model inclu profile, soil parameters, groundwater etc. adopted for stability assessment is	table and surcharge	
(i)	The feature is a mixed MR feature If yes, stability of each MR portion Local stability of each MR portion shifthe MR are sub-divided vertically		
(E) DHO	O Recommendation		NA
(a)	Have the scale of consequence been du to finalization Stage 2 Study recommen		N/A
(b)	DHO recommendation based on criteri Circular No. 24 & min. FOS ranging for If yes, review of the DHO reco- experienced engineer before issue of the	rom 1.1 to 1.2 mmendation by an	
G	Stage 2 / LPM eneral Checklist (Sheet 2 of 2)	Feature No. 2S Location: WAN	

#### **BASIC INFORMATION**

Location: WAN FAU SIN KOON, LAU FAU SHAN, YUEN LONG

Registration Date: 06-05-1998

Ranking Score (NPRS): 7 (EI)

Date of Formation: post-1977

Date of Construction/

Modification:

Data Source: SIRST

Approximate Coordinates: Easting: 817205 Northing: 837121

#### **CONSEQUENCE-TO-LIFE CATEGORY**

Facility at Crest: District open space

Distance of Facility from Crest (m): 0

Facility at Toe: Lightly-used open area/facilities

Distance of Facility from Toe (m): 0

Consequence-to-life Category: 3

Remarks: N/A

## **SLOPE PART**

(1) Max. Height (m): 3 Length (m): 26 Average Angle (deg): 37

#### **WALL PART**

N/A

#### MAINTENANCE RESPONSIBILITY

(1) Sub Div.: 1 Mixed Feature Party: DD129 LOT 1859 Agent: N/A Land Cat.: 1 Reason Code: 1 MR Endorsement Date: 20-06-2012 (2) Sub Div.: 2 Agent: Lands D Land Cat.: 1,5b(vi) Mixed Feature Party: Lands D Reason Code: 59 MR Endorsement Date: 20-06-2012 (3) Sub Div.: 2 Mixed Feature Party: STT1345 Agent: N/A Land Cat.: 1,5b(vi) Reason Code: 3 MR Endorsement Date: 20-06-2012

#### **DETAILS OF SLOPE / RETAINING WALL**

Date of Inspection: 09-03-1998

Data Source: SIRST

Slope Part Drainage: N/A

Wall Part Drainage: N/A

#### **SLOPE PART**

Slope Part (1)

Surface Protection (%): Bare: 0 Vegetated: 100 Chunam: 0 Shotcrete: 0 Other Cover: 0

Material Description: Material type: Soil Geology: N/A

Berm: No. of Berms: N/A Min. Berm Width (m): N/A

Weepholes: Size (mm): N/A Spacing (m): N/A

## **WALL PART**

N/A

## **SERVICES**

N/A

#### **CHECKING STATUS INFORMATION**

Tagmark: SCS\_3336 Part: O Checking Status: Others (See remarks) Checking Certificate No.: N/A

#### **BACKGROUND INFORMATION**

GIU Cell Ref.: 2SW22A3

Map Sheet Reference (1:1000): 2SW-22A

Aerial Photos: 39309 (1981), 39310 (1981)

Nearest Rainguage Station

(Station Number):

Hong Shui House, Shui Pin Wai Estate(N12)

Data Collected On:

09-03-1998

Date of Construction, Subsequent

Modification: Constructed Before: 1981 After: 1979

**Modification and Demolition:** 

Related Reports/Files or Documents: File/Report: Development Ref. No.: GCMW 9068/95

File/Report: Development Ref. No.: GCMW 9068/95
File/Report: Development Ref. No.: GCMW 9068/95
File/Report: Development Ref. No.: GCMW 9068/95

Remarks: N/A

Follow Up Actions: N/A

DH-Order (To Be Confirmed None with Buildings Department):

Advisory Letter (To Be Confirmed None with Buildings Department):

LPMIS: None

## **ENHANCED MAINTENANCE INFORMATION**

From Maintenance Department: (Last Updated Date: 26/05/2022)

#### **STAGE 1 STUDY REPORT**

 $Inspected\ On:$ 

Weather:

District: MW

Section No: 1-1

Height(m):

Type of Toe Facility: Lightly-used open area/facilities

Distance from Toe(m): 0

Type of Crest Facility: District open space

Distance from Crest(m): 0

Consequence Category:

**Engineering Judgement:** 

Section No: 2-2

Type of Toe Facility:

Distance from Toe(m):

Type of Crest Facility:

Distance from Crest(m):

Consequence Category:

**Engineering Judgement:** 

Sign of Seepage:

Criterion A satisfied:

Sign of Distress:

Criterion D satisfied:

Non-routine maintenance required:

Note:

Masonry wall/Masonry facing:

Note:

Consequence category (for critical section):

Observations: N/A

**Emergency Action Required:** 

Action By: N/A

## **ACTION TO INITIATE PREVENTIVE WORKS**

Criterion A/Criterion D: N/A

Action By: N/A

Further Study:

Action By: N/A

#### OTHER EXTERNAL ACTION


Check / repair Services:


Action By: N/A

Non-routine Maintenance:

Action By: N/A

## <u>PHOTO</u>





#### **BASIC INFORMATION**

Location: WAN FAU SIN KOON, DEEP BAY ROAD, LAU FAU SHAN

Registration Date: 06-05-1998

Ranking Score (NPRS): 4 (EI)

Date of Formation: post-1977

Date of Construction/

Modification:

Data Source: SIRST

Approximate Coordinates: Easting: 817174 Northing: 837147

#### **CONSEQUENCE-TO-LIFE CATEGORY**

Facility at Crest: Road/footpath with low traffic density

Distance of Facility from Crest (m): 0

Facility at Toe: Lightly-used open area/facilities

Distance of Facility from Toe (m): 0

Consequence-to-life Category: 3

Remarks: N/A

## **SLOPE PART**

(1) Max. Height (m): 3 Length (m): 60 Average Angle (deg): 35

#### **WALL PART**

N/A

#### MAINTENANCE RESPONSIBILITY

(1) Sub Div.: 0 Mixed Feature Party: Lands D Agent: Lands D Land Cat.: 1,5b(vi) Reason Code: 59 MR Endorsement Date: 20-06-2012 (2) Sub Div.: 0 Mixed Feature Party: STT1345 Agent: N/A Land Cat.: 1,5b(vi) Reason Code: 3 MR Endorsement Date: 20-06-2012

#### **DETAILS OF SLOPE / RETAINING WALL**

Date of Inspection: 09-03-1998

Data Source: SIRST

Slope Part Drainage: N/A

Wall Part Drainage: N/A

#### **SLOPE PART**

Slope Part (1)

Surface Protection (%): Bare: 0 Vegetated: 100 Chunam: 0 Shotcrete: 0 Other Cover: 0

Material Description: Material type: Soil Geology: N/A

Berm: No. of Berms: N/A Min. Berm Width (m): N/A

Weepholes: Size (mm): N/A Spacing (m): N/A

## **WALL PART**

N/A

## **SERVICES**

N/A

#### **CHECKING STATUS INFORMATION**

Tagmark: SCS\_3337 Part: O Checking Status: Others (See remarks) Checking Certificate No.: N/A

#### **BACKGROUND INFORMATION**

GIU Cell Ref.: 2SW22A3

Map Sheet Reference (1:1000): 2SW-22A

Aerial Photos: 39309 (1981), 39310 (1981)

Nearest Rainguage Station

Hong Shui House, Shui Pin Wai Estate(N12)

Data Collected On:

(Station Number):

09-03-1998

Date of Construction, Subsequent

Modification: Constructed Before: 1981 After: 1979

**Modification and Demolition:** 

Related Reports/Files or Documents: File/Report: Development

Ref. No.: GCMW 9068/95

File/Report: Development File/Report: Development File/Report: Development Ref. No.: GCMW 9068/95 Ref. No.: GCMW 9068/95 Ref. No.: GCMW 9068/95

Remarks: N/A

Follow Up Actions: N/A

DH-Order (To Be Confirmed None with Buildings Department):

Advisory Letter (To Be Confirmed None with Buildings Department):

LPMIS: None

## **ENHANCED MAINTENANCE INFORMATION**

From Maintenance Department: (Last Updated Date: 26/05/2022)

#### **STAGE 1 STUDY REPORT**

Insp	ected	Un:
	Weat	her:

District: MW

Section No: 1-1

Height(m):

Type of Toe Facility: Lightly-used open area/facilities

Distance from Toe(m): 0

Type of Crest Facility: Road/footpath with low traffic density

Distance from Crest(m): 0

Consequence Category:

**Engineering Judgement:** 

Section No: 2-2

Type of Toe Facility:

Distance from Toe(m):

Type of Crest Facility:

Distance from Crest(m):

Consequence Category:

**Engineering Judgement:** 

Sign of Seepage:

Criterion A satisfied:

Sign of Distress:

Criterion D satisfied:

Non-routine maintenance required:

Note:

Masonry wall/Masonry facing:

Note:

Consequence category (for critical section):

Observations: N/A

**Emergency Action Required:** 

Action By: N/A

## **ACTION TO INITIATE PREVENTIVE WORKS**

Criterion A/Criterion D: N/A

Action By: N/A

Further Study:

Action By: N/A

#### OTHER EXTERNAL ACTION

Check / repair Services:

Action By: N/A


Non-routine Maintenance:

Action By: N/A

## <u>PHOTO</u>



Feature No. 2SW-C/F 11



#### **BASIC INFORMATION**

Location: WAN FAU SIN FOON, DEEP BAY ROAD, LAU FAU SHAN

Registration Date: 06-05-1998

Ranking Score (NPRS): 0 (EI)

Date of Formation: post-1977

Date of Construction/

Modification:

Data Source: SIRST

Approximate Coordinates: Easting: 817203 Northing: 837160

#### **CONSEQUENCE-TO-LIFE CATEGORY**

Facility at Crest: District open space

Distance of Facility from Crest (m): 0

Facility at Toe: Lightly-used open area/facilities

Distance of Facility from Toe (m): 0

Consequence-to-life Category: 3

Remarks: N/A

## **SLOPE PART**

(1) Max. Height (m): 3 Length (m): 55 Average Angle (deg): 40

#### **WALL PART**

N/A

#### MAINTENANCE RESPONSIBILITY

(1) Sub Div.: 0 Mixed Feature Party: Lands D Agent: Lands D Land Cat.: 1,5b(vi) Reason Code: 59 MR Endorsement Date: 20-06-2012 (2) Sub Div.: 0 Mixed Feature Party: STT1345 Agent: N/A Land Cat.: 1,5b(vi) Reason Code: 3 MR Endorsement Date: 20-06-2012

#### **DETAILS OF SLOPE / RETAINING WALL**

Date of Inspection: 09-03-1998

Data Source: SIRST

Slope Part Drainage: N/A

Wall Part Drainage: N/A

#### **SLOPE PART**

Slope Part (1)

Surface Protection (%): Bare: 15 Vegetated: 85 Chunam: O Shotcrete: O Other Cover: O

Material Description: Material type: Soil Geology: N/A

Berm: No. of Berms: N/A Min. Berm Width (m): N/A

Weepholes: Size (mm): N/A Spacing (m): N/A

## **WALL PART**

N/A

## **SERVICES**

N/A

#### **CHECKING STATUS INFORMATION**

Tagmark: SCS\_3338 Part: O Checking Status: Others (See remarks) Checking Certificate No.: N/A

#### **BACKGROUND INFORMATION**

GIU Cell Ref.: 2SW22A3

Map Sheet Reference (1:1000): 2SW-22A

Aerial Photos: 39309 (1981), 39310 (1981)

Nearest Rainguage Station

(Station Number):

Hong Shui House, Shui Pin Wai Estate(N12)

Data Collected On:

09-03-1998

Date of Construction, Subsequent

Modification and Demolition:

Modification: Constructed Before: 1981 After: 1979

Related Reports/Files or Documents:

File/Report: Development Ref. No.: GCMW 9068/95

File/Report: Development Ref. No.: GCMW 9068/95
File/Report: Development Ref. No.: GCMW 9068/95
File/Report: Development Ref. No.: GCMW 9068/95

Remarks: N/A

Follow Up Actions: N/A

DH-Order (To Be Confirmed None with Buildings Department):

Advisory Letter (To Be Confirmed None with Buildings Department):

LPMIS: None

## **ENHANCED MAINTENANCE INFORMATION**

From Maintenance Department: (Last Updated Date: 26/05/2022)

#### **STAGE 1 STUDY REPORT**

Inspected On:	
Weather:	

District: MW

Section No: 1-1

Height(m):

Type of Toe Facility: Lightly-used open area/facilities

Distance from Toe(m): 0

Type of Crest Facility: District open space

Distance from Crest(m): 0

Consequence Category:

**Engineering Judgement:** 

Section No: 2-2

Type of Toe Facility:

Distance from Toe(m):

Type of Crest Facility:

Distance from Crest(m):

Consequence Category:

**Engineering Judgement:** 

Sign of Seepage:

Criterion A satisfied:

Sign of Distress:

Criterion D satisfied:

Non-routine maintenance required:

Note:

Masonry wall/Masonry facing:

Note:

Consequence category (for critical section):

Observations: N/A

**Emergency Action Required:** 

Action By: N/A

## **ACTION TO INITIATE PREVENTIVE WORKS**

Criterion A/Criterion D: N/A

Action By: N/A

Further Study:

Action By: N/A

#### OTHER EXTERNAL ACTION

Check / repair Services:


Action By: N/A

Non-routine Maintenance:

Action By: N/A

## <u>PHOTO</u>





#### **BASIC INFORMATION**

Location: WAN FAU SIN KOON, DEEP BAY ROAD, LAU FAU SHAN

Registration Date: 06-05-1998
Ranking Score (NPRS): 0 (Notional)
Date of Formation: post-1977

Date of Construction/

Modification:

Data Source: SIRST

Approximate Coordinates: Easting: 817229 Northing: 837048

#### **CONSEQUENCE-TO-LIFE CATEGORY**

Facility at Crest: Road/footpath with low traffic density

Distance of Facility from Crest (m): 2

Facility at Toe: District open space

Distance of Facility from Toe (m): 0

Consequence-to-life Category: 3

Remarks: N/A

## **SLOPE PART**

N/A

#### **WALL PART**

(1) Max. Height (m): 4 Length (m): 39 Face Angle (deg): 90

### MAINTENANCE RESPONSIBILITY

(1) Sub Div.: 1 Mixed Feature Party: DD129 LOT 1857 S.A Agent: N/A Land Cat.: 1 Reason Code: 1 MR Endorsement Date: 16-06-2021 (2) Sub Div.: 2 Mixed Feature Party: Lands D Agent: Lands D Land Cat.: 1,5b(vi) Reason Code: 59 MR Endorsement Date: 16-06-2021 (3) Sub Div.: 2 Mixed Feature Party: STT1345 Agent: N/A Land Cat.: 1,5b(vi) Reason Code: 3 MR Endorsement Date: 16-06-2021

# **DETAILS OF SLOPE / RETAINING WALL**

Date of Inspection: 09-03-1998

Data Source: SIRST

Slope Part Drainage: N/A

Wall Part Drainage: N/A

### **SLOPE PART**

### **WALL PART**

Wall Part (1)

Type of Wall: Wall Material: Concrete Wall Location: Retaining wall with level platform

Berm: No. of Berms: N/A Min. Berm Width (m): N/A

Weepholes: Size (mm): N/A Spacing (m): N/A

# **SERVICES**

(1) Utilities Type: Water Main Size(mm): 60 Location: On crest Remark: N/A

### **CHECKING STATUS INFORMATION**

Tagmark: SCS\_3340 Part: O Checking Status: Others (See remarks) Checking Certificate No.: N/A

### **BACKGROUND INFORMATION**

GIU Cell Ref.: 2SW22A3

Map Sheet Reference (1:1000): 2SW-22A

Aerial Photos: 39309 (1982), 39310 (1982)

Nearest Rainguage Station

(Station Number):

Hong Shui House, Shui Pin Wai Estate(N12)

Data Collected On:

09-03-1998

Date of Construction, Subsequent

Modification: Constructed Before: 1981 After: 1979

Modification and Demolition:

Related Reports/Files or Documents: File/Report: Development Ref. No.: GCMW 9068/95

File/Report: Development Ref. No.: GCMW 9068/95
File/Report: Development Ref. No.: GCMW 9068/95
File/Report: Development Ref. No.: GCMW 9068/95

Remarks: N/A

Follow Up Actions: N/A

DH-Order (To Be Confirmed None with Buildings Department):

Advisory Letter (To Be Confirmed None with Buildings Department):

LPMIS: None

# **ENHANCED MAINTENANCE INFORMATION**

From Maintenance Department: (Last Updated Date: 26/05/2022)

### **STAGE 1 STUDY REPORT**

 $Inspected\ On:$ 

Weather:

District: MW

Section No: 1-1

Height(m):

Type of Toe Facility: District open space

Distance from Toe(m): 0

Type of Crest Facility: Road/footpath with low traffic density

Distance from Crest(m): 2

Consequence Category:

**Engineering Judgement:** 

Section No: 2-2

Type of Toe Facility:

Distance from Toe(m):

Type of Crest Facility:

Distance from Crest(m):

Consequence Category:

**Engineering Judgement:** 

Sign of Seepage:

Criterion A satisfied:

Sign of Distress:

Criterion D satisfied:

Non-routine maintenance required:

Note:

Masonry wall/Masonry facing:

Note:

Consequence category (for critical section):

Observations: N/A

**Emergency Action Required:** 

Action By: N/A

# **ACTION TO INITIATE PREVENTIVE WORKS**

Criterion A/Criterion D: N/A

> Action By: N/A

Further Study:

Action By: N/A

### OTHER EXTERNAL ACTION

Check / repair Services:

Action By: N/A

Non-routine Maintenance:

Action By: N/A

# <u>PHOTO</u>





### **BASIC INFORMATION**

Location: WAN FAU SIN KOON, LAU FAU SHAN, YUEN LONG

Registration Date: 06-05-1998

Ranking Score (NPRS): 0 (EI)

Date of Formation: post-1977

Date of Construction/

Modification:

Data Source: EI(Lands D)

Approximate Coordinates: Easting: 817270 Northing: 837056

### **CONSEQUENCE-TO-LIFE CATEGORY**

Facility at Crest: District open space

Distance of Facility from Crest (m): 0

Facility at Toe: Columbarium

Distance of Facility from Toe (m): 0

Consequence-to-life Category: 3

Remarks: N/A

# **SLOPE PART**

N/A

### **WALL PART**

(1) Max. Height (m): 4.5 Length (m): 97 Face Angle (deg): 90

### MAINTENANCE RESPONSIBILITY

(1) Sub Div.: 1 Mixed Feature Party: DD129 LOT 1857 S.A Agent: N/A Land Cat.: 1 Reason Code: 1 MR Endorsement Date: 16-06-2021 (2) Sub Div.: 2 Mixed Feature Party: Lands D Agent: Lands D Land Cat.: 1,5b(vi) Reason Code: 59 MR Endorsement Date: 16-06-2021 (3) Sub Div.: 2 Mixed Feature Party: STT1345 Agent: N/A Land Cat.: 1,5b(vi) Reason Code: 3 MR Endorsement Date: 16-06-2021

# **DETAILS OF SLOPE / RETAINING WALL**

Date of Inspection: 15-07-2015

Data Source: EI(Lands D)

Slope Part Drainage: N/A

Wall Part Drainage: N/A

### **SLOPE PART**

### **WALL PART**

Wall Part (1)

Type of Wall: Wall Material: Concrete Wall Location: Retaining wall with level platform

Berm: No. of Berms: N/A Min. Berm Width (m): N/A

Weepholes: Size (mm): N/A Spacing (m): N/A

# **SERVICES**

### CHECKING STATUS INFORMATION

Tagmark: SCS\_3341 Part: O Checking Status: Others (See remarks) Checking Certificate No.: N/A

### **BACKGROUND INFORMATION**

GIU Cell Ref.: 2SW22B1

Map Sheet Reference (1:1000): 25W-22B

Aerial Photos: 39309 (1981), 39310 (1981)

Nearest Rainguage Station

(Station Number):

Hong Shui House, Shui Pin Wai Estate(N12)

Data Collected On:

15-07-2015

Date of Construction, Subsequent

N/A

**Modification and Demolition:** 

Related Reports/Files or Documents:

File/Report: DLC/BC Ref. No.: GCMW 4/1C/2-2 pt.19 f(13,14,17,22)

File/Report: DLC/BC Ref. No.: GCMW 4/1C/2-2 pt.19 f(13,14,17,22)

File/Report: Development Ref. No.: GCMW 9068/95

Remarks: N/A

Follow Up Actions: N/A

DH-Order (To Be Confirmed None with Buildings Department):

Advisory Letter (To Be Confirmed None with Buildings Department):

LPMIS: None

# **ENHANCED MAINTENANCE INFORMATION**

From Maintenance Department: (Last Updated Date: 26/05/2022)

### **STAGE 1 STUDY REPORT**

Inspected On:

Weather:

District: MW

Section No: 1-1

Height(m):

Type of Toe Facility: Columbarium

Distance from Toe(m): 0

Type of Crest Facility: District open space

Distance from Crest(m): 0

Consequence Category:

**Engineering Judgement:** 

Section No: 2-2

Type of Toe Facility:

Distance from Toe(m):

Type of Crest Facility:

Distance from Crest(m):

Consequence Category:

**Engineering Judgement:** 

Sign of Seepage:

Criterion A satisfied:

Sign of Distress:

Criterion D satisfied:

Non-routine maintenance required:

Note:

Masonry wall/Masonry facing:

Note:

Consequence category (for critical section):

Observations: N/A

**Emergency Action Required:** 

Action By: N/A

# **ACTION TO INITIATE PREVENTIVE WORKS**

Criterion A/Criterion D: N/A

Action By: N/A

Further Study:

Action By: N/A

### OTHER EXTERNAL ACTION

Check / repair Services:

Action By: N/A

Non-routine Maintenance:

Action By: N/A


# <u>PHOTO</u>











### **BASIC INFORMATION**

Location: Near Wan Fau Sin Koon, Deep Bay Road, Lau Fau Shan, Yuen Long.

Registration Date: 06-05-1998

Ranking Score (NPRS): 0 (EI)

Date of Formation: pre-1977

Date of Construction/

Modification:

Data Source: EI(Lands D)

Approximate Coordinates: Easting: 817177 Northing: 837205

### **CONSEQUENCE-TO-LIFE CATEGORY**

Facility at Crest: Road/footpath with low traffic density

Distance of Facility from Crest (m): 0

Facility at Toe: Lightly-used open area/facilities

Distance of Facility from Toe (m): 0

Consequence-to-life Category: 3

Remarks: N/A

# **SLOPE PART**

(1) Max. Height (m): 5.5 Length (m): 42 Average Angle (deg): 30

### **WALL PART**

### **MAINTENANCE RESPONSIBILITY**

(1) Sub Div.: O Government Feature Party: Lands D Agent: Lands D Land Cat.: 5b(vi) Reason Code: 62 MR Endorsement Date: 06-07-1999

# **DETAILS OF SLOPE / RETAINING WALL**

Date of Inspection: 17-03-2015

Data Source: EI(Lands D)

Slope Part Drainage: N/A

Wall Part Drainage: N/A

# **SLOPE PART**

Slope Part (1)

Surface Protection (%): Bare: 0 Vegetated: 100 Chunam: 0 Shotcrete: 0 Other Cover: 0

Material Description: Material type: Soil Geology: N/A

Berm: No. of Berms: N/A Min. Berm Width (m): N/A

Weepholes: Size (mm): N/A Spacing (m): N/A

# **WALL PART**

N/A

# **SERVICES**

### **CHECKING STATUS INFORMATION**

N/A

### **BACKGROUND INFORMATION**

GIU Cell Ref.: N/A

Map Sheet Reference (1:1000): N/A

Aerial Photos: N/A

Nearest Rainguage Station () (Station Number):

Data Collected On: 17-03-2015

Date of Construction, Subsequent

Modification and Demolition:

Modification: Constructed Before: 1981 After: 1978

Related Reports/Files or Documents: File/Report: DLC/BC Ref. No.: GCMW 4/1C/2-3 pt.3 f(20), pt.18 f(6, 7)

File/Report: DLC/BC Ref. No.: GCMW 4/1C/2-3 pt.3 f(20), pt.18 f(6, 7)

File/Report: LA Ref. No.: GCMW 5/3/10(W) pt. 6 f(55, 60) File/Report: LA Ref. No.: GCMW 5/3/10(W) pt. 6 f(55, 60)

Remarks: N/A

Follow Up Actions: N/A

DH-Order (To Be Confirmed None with Buildings Department):

Advisory Letter (To Be Confirmed None with Buildings Department):

LPMIS: None

# **ENHANCED MAINTENANCE INFORMATION**

From Maintenance Department: (Last Updated Date: 10/08/2023)

### **STAGE 1 STUDY REPORT**

Inspected On: Weather:

> District: N/A

Section No: 1-1

Height(m):

Type of Toe Facility: Lightly-used open area/facilities

Distance from Toe(m): 0

Type of Crest Facility: Road/footpath with low traffic density

Distance from Crest(m): 0

Consequence Category:

**Engineering Judgement:** 

**Section No:** 2-2

Type of Toe Facility:

Distance from Toe(m):

Type of Crest Facility:

Distance from Crest(m):

Consequence Category:

**Engineering Judgement:** 

Sign of Seepage:

Criterion A satisfied:

Sign of Distress:

Criterion D satisfied:

Non-routine maintenance required:

Note:

Masonry wall/Masonry facing:

Note:

Consequence category (for critical section):

Observations: N/A

**Emergency Action Required:** 

Action By: N/A

# **ACTION TO INITIATE PREVENTIVE WORKS**

Criterion A/Criterion D: N/A

Action By: N/A

Further Study:

Action By: N/A

### OTHER EXTERNAL ACTION

Check / repair Services:

Action By: N/A

Non-routine Maintenance:

Action By: N/A

# <u>PHOTO</u>










Feature No. 2SW-C/F 4



### **BASIC INFORMATION**

Location: Near Wan Fau Sin Koon, Deep Bay Road, Lau Fau Shan, Yuen Long

Registration Date: 06-05-1998

Ranking Score (NPRS): 0 (EI)

Date of Formation: post-1977

Date of Construction/

Modification:

Data Source: El

Approximate Coordinates: Easting: 817168 Northing: 837263

### **CONSEQUENCE-TO-LIFE CATEGORY**

Facility at Crest: Road/footpath with low traffic density

Distance of Facility from Crest (m): 0

Facility at Toe: Lightly-used open area/facilities

Distance of Facility from Toe (m): 0

Consequence-to-life Category: 3

Remarks: N/A

# **SLOPE PART**

(1) Max. Height (m): 5.5 Length (m): 85 Average Angle (deg): 55

### **WALL PART**

### **MAINTENANCE RESPONSIBILITY**

(1) Sub Div.: O Government Feature Party: Lands D Agent: Lands D Land Cat.: 5b(vi) Reason Code: 62 MR Endorsement Date: 24-11-2006

# **DETAILS OF SLOPE / RETAINING WALL**

Date of Inspection: 13-09-2001

Data Source: El

Slope Part Drainage: N/A

Wall Part Drainage: N/A

# **SLOPE PART**

Slope Part (1)

Surface Protection (%): Bare: 0 Vegetated: 0 Chunam: 0 Shotcrete: 0 Other Cover: 100

Material Description: Material type: Soil Geology: Decomposed granite
Berm: No. of Berms: N/A Min. Berm Width (m): N/A

Weepholes: Size (mm): N/A Spacing (m): N/A

# **WALL PART**

N/A

# **SERVICES**

### **CHECKING STATUS INFORMATION**

Tagmark: 15081\_1\_5 Part: 1 Checking Status: No checking records Checking Certificate No.: N/A

### **BACKGROUND INFORMATION**

GIU Cell Ref.: 2SW17C9

Map Sheet Reference (1:1000): 25W-17C

Aerial Photos: 51451 (1983), 51452 (1983)

Nearest Rainguage Station

Hong Shui House, Shui Pin Wai Estate(N12)

(Station Number):

Data Collected On: 13-09-2001

Date of Construction, Subsequent N

Modification: Constructed Before: 1983 After: 1981

**Modification and Demolition:** 

Related Reports/Files or Documents: N/A

Remarks: N/A

Follow Up Actions: N/A

DH-Order (To Be Confirmed None with Buildings Department):

Advisory Letter (To Be Confirmed None with Buildings Department):

LPMIS: None

# **ENHANCED MAINTENANCE INFORMATION**

From Maintenance Department: (Last Updated Date: 10/08/2023)

### **STAGE 1 STUDY REPORT**

Insp	ected	On:
	Weat	her:

District: MW

Section No: 1-1

Height(m):

Type of Toe Facility: Lightly-used open area/facilities

Distance from Toe(m): 0

Type of Crest Facility: Road/footpath with low traffic density

Distance from Crest(m): 0

Consequence Category:

**Engineering Judgement:** 

Section No: 2-2

Type of Toe Facility:

Distance from Toe(m):

Type of Crest Facility:

Distance from Crest(m):

Consequence Category:

**Engineering Judgement:** 

Sign of Seepage:

Criterion A satisfied:

Sign of Distress:

Criterion D satisfied:

Non-routine maintenance required:

Note:

Masonry wall/Masonry facing:

Note:

Consequence category (for critical section):

Observations: N/A

**Emergency Action Required:** 

Action By: N/A

# **ACTION TO INITIATE PREVENTIVE WORKS**

Criterion A/Criterion D: N/A

Action By: N/A

Further Study:

Action By: N/A

### OTHER EXTERNAL ACTION

Check / repair Services:

Action By: N/A

Non-routine Maintenance:


Action By: N/A

# <u>PHOTO</u>









### **BASIC INFORMATION**

Location: Near Wan Fau Sin Koon, Deep Bay Road, Lau Fau Shan, Yuen Long

Registration Date: 06-05-1998

Ranking Score (NPRS): 0 (EI)

Date of Formation: pre-1977

Date of Construction/

Modification:

Data Source: Project Office

Approximate Coordinates: Easting: 817106 Northing: 837212

### **CONSEQUENCE-TO-LIFE CATEGORY**

Facility at Crest: Undeveloped green belt

Distance of Facility from Crest (m): 0

Facility at Toe: District open space

Distance of Facility from Toe (m): 0

Consequence-to-life Category: 3

Remarks: N/A

# **SLOPE PART**

(1) Max. Height (m): 9 Length (m): 74 Average Angle (deg): 50

### **WALL PART**

## **MAINTENANCE RESPONSIBILITY**

(1) Sub Div.: O Government Feature Party: Lands D Agent: Lands D Land Cat.: 5b(vi) Reason Code: 62 MR Endorsement Date: 25-08-2006

# **DETAILS OF SLOPE / RETAINING WALL**

Date of Inspection: 08-12-2006

Data Source: Project Office

Slope Part Drainage: N/A

Wall Part Drainage: N/A

# **SLOPE PART**

Slope Part (1)

Surface Protection (%): Bare: 0 Vegetated: 100 Chunam: 0 Shotcrete: 0 Other Cover: 0

Material Description: Material type: Soil Geology: N/A

Berm: No. of Berms: N/A Min. Berm Width (m): N/A

Weepholes: Size (mm): N/A Spacing (m): N/A

# **WALL PART**

N/A

# **SERVICES**

N/A

## **CHECKING STATUS INFORMATION**

N/A

## **BACKGROUND INFORMATION**

GIU Cell Ref.: 2SW17C9

Map Sheet Reference (1:1000): 25W-17C

Aerial Photos: 16435 (1976), 16436 (1976)

Nearest Rainguage Station

Hong Shui House, Shui Pin Wai Estate(N12)

(Station Number):

Data Collected On: 08-12-2006

Date of Construction, Subsequent
Modification: Constructed Before: 1963 After: N/A
Modification and Demolition:
Modification: Modified Before: 1976 After: 1963

Related Reports/Files or Documents: N/A

Remarks: N/A

Follow Up Actions: N/A

DH-Order (To Be Confirmed None with Buildings Department):

Advisory Letter (To Be Confirmed None with Buildings Department):

LPMIS: None


# **ENHANCED MAINTENANCE INFORMATION**

From Maintenance Department: (Last Updated Date: 10/08/2023)

# **STAGE 1 STUDY REPORT**

Inspected On: 03-03-1998
Weather: Mainly Fine

District: MW



Section No: 1-1

Height(m): H1:9, H2:0

Type of Toe Facility: District open space

Distance from Toe(m): 0

Type of Crest Facility: Undeveloped green belt

Distance from Crest(m): 0
Consequence Category: 3
Engineering Judgement: P

Section No: 2-2

Type of Toe Facility: N/A

Distance from Toe(m): 0

Type of Crest Facility: N/A

Distance from Crest(m): 0
Consequence Category: 3
Engineering Judgement: P

Sign of Seepage: Slope : No signs of seepage

Wall: N/A

Criterion A satisfied: N

Sign of Distress: Slope : N/A

Wall: N/A

Criterion D satisfied: N

Non-routine maintenance required: N

Note: N/A

Masonry wall/Masonry facing: N

Note: N/A

Consequence category (for critical section): 3

Observations: N/A

Emergency Action Required: N

Action By: N/A

# **ACTION TO INITIATE PREVENTIVE WORKS**

Criterion A/Criterion D: N/A

Action By: N/A

Further Study: Y

Action By: Mixed

### OTHER EXTERNAL ACTION

Check / repair Services:

Action By: N/A

Non-routine Maintenance: N


Action By: N/A

# <u>PHOTO</u>





Feature No. 2SW-C/C 52



#### **BASIC INFORMATION**

Location: Wan Fau Sin Koon, Deep Bay Road, Lau Fau Shan

Registration Date: 06-05-1998

Ranking Score (NPRS): 0 (EI)

Date of Formation: post-1977

Date of Construction/

Modification:

Data Source: EI(Lands D)

Approximate Coordinates: Easting: 817137 Northing: 837135

## **CONSEQUENCE-TO-LIFE CATEGORY**

Facility at Crest: Undeveloped green belt

Distance of Facility from Crest (m): 0

Facility at Toe: Road/footpath with low traffic density

Distance of Facility from Toe (m): 0.5

Consequence-to-life Category: 3

Remarks: N/A

# **SLOPE PART**

(1) Max. Height (m): 6 Length (m): 105 Average Angle (deg): 35

### **WALL PART**

N/A

#### MAINTENANCE RESPONSIBILITY

(1) Sub Div.: 1 Mixed Feature Party: DD129 Lot1862 Agent: N/A Land Cat.: 1,5b(vi),7 Reason Code: 1 MR Endorsement Date: 01-06-1999 (2) Sub Div.: 2 Mixed Feature Party: Lands D Agent: Lands D Land Cat.: 1,5b(vi),7 Reason Code: 62 MR Endorsement Date: 01-06-1999

## **DETAILS OF SLOPE / RETAINING WALL**

Date of Inspection: 01-11-2001

Data Source: EI(Lands D)

Slope Part Drainage: N/A

Wall Part Drainage: N/A

## **SLOPE PART**

Slope Part (1)

Surface Protection (%): Bare: 0 Vegetated: 100 Chunam: 0 Shotcrete: 0 Other Cover: 0

Material Description: Material type: Soil Geology: Decomposed granite
Berm: No. of Berms: N/A Min. Berm Width (m): N/A

Weepholes: Size (mm): N/A Spacing (m): N/A

# **WALL PART**

N/A

# **SERVICES**

(1) Utilities Type: Water Main Size(mm): 25 Location: On slope Remark: N/A

## **CHECKING STATUS INFORMATION**

Tagmark: 15084\_1\_5 Part: 1 Checking Status: No checking records Checking Certificate No.: N/A

#### **BACKGROUND INFORMATION**

GIU Cell Ref.: 2SW22A3

Map Sheet Reference (1:1000): 2SW-22A

Aerial Photos: 39309 (1981), 39310 (1981)

Nearest Rainguage Station Hor

(Station Number):

Hong Shui House, Shui Pin Wai Estate(N12)

Data Collected On:

01-11-2001

Date of Construction, Subsequent

Modification: Constructed Before: 1981 After: 1979

**Modification and Demolition:** 

Related Reports/Files or Documents: File/Report: Development Ref. No.: GCMW 9068/95

File/Report: Development Ref. No.: GCMW 9068/95
File/Report: Development Ref. No.: GCMW 9068/95
File/Report: Development Ref. No.: GCMW 9068/95

Remarks: N/A

Follow Up Actions: N/A

DH-Order (To Be Confirmed None with Buildings Department):

Advisory Letter (To Be Confirmed None with Buildings Department):

LPMIS: None

# **ENHANCED MAINTENANCE INFORMATION**

From Maintenance Department: (Last Updated Date: 10/08/2023)

## **STAGE 1 STUDY REPORT**

Inspected	On:
Weat	her:

District: MW

Section No: 1-1

Height(m):

Type of Toe Facility: Road/footpath with low traffic density

Distance from Toe(m): 0.5

Type of Crest Facility: Undeveloped green belt

Distance from Crest(m): 0

Consequence Category:

**Engineering Judgement:** 

Section No: 2-2

Type of Toe Facility:

Distance from Toe(m):

Type of Crest Facility:

Distance from Crest(m):

Consequence Category:

**Engineering Judgement:** 

Sign of Seepage:

Criterion A satisfied:

Sign of Distress:

Criterion D satisfied:

Non-routine maintenance required:

Note:

Masonry wall/Masonry facing:

Note:

Consequence category (for critical section):

Observations: N/A

**Emergency Action Required:** 

Action By: N/A

# **ACTION TO INITIATE PREVENTIVE WORKS**

Criterion A/Criterion D: N/A

Action By: N/A

Further Study:

Action By: N/A

### OTHER EXTERNAL ACTION

Check / repair Services:

Action By: N/A

Non-routine Maintenance:

Action By: N/A


# <u>PHOTO</u>







Feature No. 2SW-C/C 69



#### **BASIC INFORMATION**

Location: Near Wan Fau Sin Koon, Deep Bay Road, Lau Fau Shan, Yuen Long.

Registration Date: 06-05-1998
Ranking Score (NPRS): 0 (EI)
Date of Formation: post-1977

Date of Construction/ Modification:
Data Source: EI

Approximate Coordinates: Easting: 817193 Northing: 837224

#### CONSEQUENCE-TO-LIFE CATEGORY

Facility at Crest: Undeveloped green belt

Distance of Facility from Crest (m): 0

Facility at Toe: Road/footpath with low traffic density

Distance of Facility from Toe (m): 0

Consequence-to-life Category: 3

Remarks: N/A

#### **SLOPE PART**

(1) Max. Height (m): 4 Length (m): 50 Average Angle (deg): 50

#### **WALL PART**

N/A

#### MAINTENANCE RESPONSIBILITY

(1) Sub Div.: 1 **Mixed Feature** Party: Lands D Agent: Lands D Land Cat.: 5b(vi) Reason Code: 62 MR Endorsement Date: 20-06-2012 (2) Sub Div.: 2 Mixed Feature MR Endorsement Date: 20-06-2012 Party: Lands D Agent: Lands D Land Cat.: 1,5b(vi) Reason Code: 59 (3) Sub Div.: 2 Mixed Feature Agent: N/A Land Cat.: 1,5b(vi) Reason Code: 3 MR Endorsement Date: 20-06-2012 Party: STT1345

## DETAILS OF SLOPE / RETAINING WALL

Date of Inspection: 13-09-2001

Data Source: El

Slope Part Drainage: (1) Position: Toe Size(mm): 325

Wall Part Drainage: N/A

#### **SLOPE PART**

Slope Part (1)

Other Cover: 100 Surface Protection (%): Bare: 0 Vegetated: 0 Chunam: 0 Shotcrete: 0

Material Description: Material type: Soil Geology: Decomposed granite No. of Berms: N/A Min. Berm Width (m): N/A Berm:

Weepholes: Size (mm): N/A Spacing (m): N/A

**WALL PART** 

N/A

**SERVICES** 

N/A

### CHECKING STATUS INFORMATION

Checking Status: Others (See remarks) Tagmark: SCS\_3342 Part: 0 Checking Certificate No.: N/A

#### BACKGROUND INFORMATION

GIU Cell Ref.: 2SW17C9 Map Sheet Reference (1:1000): 2SW-17C

**Aerial Photos:** 39309 (1981), 39310 (1981)

**Nearest Rainguage Station (Station** 

Number):

Hong Shui House, Shui Pin Wai Estate(N12)

Data Collected On: 13-09-2001

Date of Construction, Subsequent

Modification and Demolition:

Before: 1981 Modification: Constructed After: 1979

Related Reports/Files or Documents: File/Report: DLC/BC Ref. No.: GCMW 4/1C/2-2 pt.3 f(20), pt.18 f(6, 7)

> File/Report: DLC/BC Ref. No.: GCMW 4/1C/2-2 pt.3 f(20), pt.18 f(6, 7)

Remarks: N/A Follow Up Actions: N/A DH-Order (To Be Confirmed with None

**Buildings Department):** 

None

Advisory Letter (To Be Confirmed with Buildings Department):

LPMIS: None

# ENHANCED MAINTENANCE INFORMATION

From Maintenance Department: (Last Updated Date: 26/06/2025)

#### STAGE 1 STUDY REPORT

Inspected On:

Weather:

District: MW
Section No: 1-1

Height(m):

Type of Toe Facility: Road/footpath with low traffic density

Distance from Toe(m): 0

Type of Crest Facility: Undeveloped green belt

Distance from Crest(m):

Consequence Category: Engineering Judgement:

Section No: 2-2

Type of Toe Facility:
Distance from Toe(m):
Type of Crest Facility:
Distance from Crest(m):
Consequence Category:
Engineering Judgement:

Sign of Seepage: Criterion A satisfied: Sign of Distress:

Criterion D satisfied:

Non-routine maintenance required:

Note:

Masonry wall/Masonry facing:

Note:

Consequence category (for critical

section):

Observations: N/A

**Emergency Action Required:** 

Action By: N/A

# **ACTION TO INITIATE PREVENTIVE WORKS**

Criterion A/Criterion D: N/A

Action By: N/A

 $Further\ Study:$ 

Action By: N/A

# OTHER EXTERNAL ACTION

Check / repair Services:

Action By: N/A


Non-routine Maintenance:

Action By: N/A

# **PHOTO**







#### **BASIC INFORMATION**

Location: Near Wan Fau Sin Koon, Deep Bay Road, Lau Fau Shan, Yuen Long

Registration Date: 06-05-1998
Ranking Score (NPRS): 0 (EI)
Date of Formation: post-1977

Date of Construction/ Modification:
Data Source: EI

Approximate Coordinates: Easting: 817168 Northing: 837263

#### CONSEQUENCE-TO-LIFE CATEGORY

Facility at Crest: Road/footpath with low traffic density

Distance of Facility from Crest (m): 0

Facility at Toe: Lightly-used open area/facilities

Distance of Facility from Toe (m): 0

Consequence-to-life Category: 3

Remarks: N/A

#### **SLOPE PART**

(1) Max. Height (m): 5.5 Length (m): 85 Average Angle (deg): 55

#### **WALL PART**

N/A

#### MAINTENANCE RESPONSIBILITY

(1) Sub Div.: O Government Feature Party: Lands D Agent: Lands D Land Cat.: 5b(vi) Reason Code: 62 MR Endorsement Date: 24-11-2006

### DETAILS OF SLOPE / RETAINING WALL

Date of Inspection: 13-09-2001

Data Source: El
Slope Part Drainage: N/A
Wall Part Drainage: N/A

### **SLOPE PART**

Slope Part (1)

Surface Protection (%): Bare: 0 Vegetated: 0 Chunam: 0 Shotcrete: 0 Other Cover: 100

Material Description: Material type: Soil Geology: Decomposed granite
Berm: No. of Berms: N/A Min. Berm Width (m): N/A

Weepholes: Size (mm): N/A Spacing (m): N/A

**WALL PART** 

N/A

**SERVICES** 

N/A

### **CHECKING STATUS INFORMATION**

Checking Status: No checking records Checking Certificate No.: N/A 

Before: 1983

After: 1981

#### **BACKGROUND INFORMATION**

GIU Cell Ref.: 2SW17C9 Map Sheet Reference (1:1000): 2SW-17C

**Aerial Photos:** 51451 (1983), 51452 (1983)

**Nearest Rainguage Station (Station** Hong Shui House, Shui Pin Wai Estate(N12)

Number):

Data Collected On: 13-09-2001

Date of Construction, Subsequent **Modification: Constructed** 

Modification and Demolition:

Related Reports/Files or Documents: N/A Remarks: N/A Follow Up Actions: N/A DH-Order (To Be Confirmed with None

**Buildings Department):** 

Advisory Letter (To Be Confirmed

with Buildings Department):

None

LPMIS: None

#### **ENHANCED MAINTENANCE INFORMATION**

From Maintenance Department: (Last Updated Date: 26/06/2025)

#### STAGE 1 STUDY REPORT

Inspected On:

Weather:

District: MW
Section No: 1-1

Height(m):

Type of Toe Facility: Lightly-used open area/facilities

Distance from Toe(m): 0

Type of Crest Facility: Road/footpath with low traffic density

Distance from Crest(m): 0

Consequence Category: Engineering Judgement:

Section No: 2-2

Type of Toe Facility:
Distance from Toe(m):
Type of Crest Facility:
Distance from Crest(m):
Consequence Category:
Engineering Judgement:

Sign of Seepage: Criterion A satisfied: Sign of Distress:

Criterion D satisfied:

Non-routine maintenance required:

Note:

Masonry wall/Masonry facing:

Note:

Consequence category (for critical

section):

Observations: N/A

**Emergency Action Required:** 

Action By: N/A

#### **ACTION TO INITIATE PREVENTIVE WORKS**

Criterion A/Criterion D: N/A
Action By: N/A

Further Study:

Action By: N/A

#### OTHER EXTERNAL ACTION

Check / repair Services:

Action By: N/A

Non-routine Maintenance:

Action By:


N/A

# **PHOTO**









#### **BASIC INFORMATION**

Location: Near Wan Fau Sin Koon, Deep Bay Road, Lau Fau Shan, Yuen Long

Registration Date: 06-05-1998
Ranking Score (NPRS): 0 (EI)
Date of Formation: pre-1977

Date of Construction/ Modification:

Data Source: Project Office

Approximate Coordinates: Easting: 817106 Northing: 837212

#### CONSEQUENCE-TO-LIFE CATEGORY

Facility at Crest: Undeveloped green belt

Distance of Facility from Crest (m): 0

Facility at Toe: District open space

Distance of Facility from Toe (m): 0
Consequence-to-life Category: 3
Remarks: N/A

#### **SLOPE PART**

(1) Max. Height (m): 9 Length (m): 74 Average Angle (deg): 50

#### **WALL PART**

N/A

### MAINTENANCE RESPONSIBILITY

(1) Sub Div.: O Government Feature Party: Lands D Agent: Lands D Land Cat.: 5b(vi) Reason Code: 62 MR Endorsement Date: 25-08-2006

#### DETAILS OF SLOPE / RETAINING WALL

Date of Inspection: 08-12-2006

Data Source: Project Office

Slope Part Drainage: N/A
Wall Part Drainage: N/A

### **SLOPE PART**

Slope Part (1)

Surface Protection (%): Bare: 0 Vegetated: 100 Chunam: 0 Shotcrete: 0 Other Cover: 0

Material Description: Material type: Soil Geology: N/A

Berm: No. of Berms: N/A Min. Berm Width (m): N/A

Weepholes: Size (mm): N/A Spacing (m): N/A

**WALL PART** 

N/A

**SERVICES** 

N/A

### **CHECKING STATUS INFORMATION**

N/A

#### **BACKGROUND INFORMATION**

GIU Cell Ref.: 2SW17C9
Map Sheet Reference (1:1000): 2SW-17C

Aerial Photos: 16435 (1976), 16436 (1976)

Nearest Rainguage Station (Station

Number):

Hong Shui House, Shui Pin Wai Estate(N12)

Data Collected On: 08-12-2006

Date of Construction, Subsequent Modification: Constructed Before: 1963 After: N/A Modification and Demolition: Modification: Modified Before: 1976 After: 1963

Related Reports/Files or Documents: N/A
Remarks: N/A
Follow Up Actions: N/A
DH-Order (To Be Confirmed with None

**Buildings Department):** 

Advisory Letter (To Be Confirmed

with Buildings Department):

None

LPMIS: None


#### **ENHANCED MAINTENANCE INFORMATION**

From Maintenance Department: (Last Updated Date: 26/06/2025)

#### STAGE 1 STUDY REPORT

Inspected On: 03-03-1998
Weather: Mainly Fine

District: MW



Section No: 1-1

Height(m): H1 : 9 , H2 : 0

Type of Toe Facility: District open space

Distance from Toe(m): 0

Type of Crest Facility: Undeveloped green belt

Distance from Crest(m): 3 Consequence Category: P **Engineering Judgement:** 2-2 **Section No:** Type of Toe Facility: N/A Distance from Toe(m): 0 Type of Crest Facility: N/A Distance from Crest(m): 0 3 Consequence Category:

Sign of Seepage: Slope : No signs of seepage

Wall: N/A

Criterion A satisfied:

**Engineering Judgement:** 

Sign of Distress: Slope : N/A

Wall: N/A

Criterion D satisfied: N
Non-routine maintenance required: N
Note: N/A
Masonry wall/Masonry facing: N
Note: N/A

Consequence category (for critical

section):

Observations: N/A
Emergency Action Required: N
Action By: N/A

# **ACTION TO INITIATE PREVENTIVE WORKS**

Criterion A/Criterion D: N/A
Action By: N/A
Further Study: Y
Action By: Mixed


## OTHER EXTERNAL ACTION

Check / repair Services: N
Action By: N/A
Non-routine Maintenance: N
Action By: N/A

# **PHOTO**







#### **BASIC INFORMATION**

Location: Wan Fau Sin Koon, Deep Bay Road, Lau Fau Shan

Registration Date: 06-05-1998
Ranking Score (NPRS): 0 (EI)
Date of Formation: post-1977

Date of Construction/ Modification:

Data Source: El(Lands D)

Approximate Coordinates: Easting: 817137 Northing: 837135

#### CONSEQUENCE-TO-LIFE CATEGORY

Facility at Crest: Undeveloped green belt

Distance of Facility from Crest (m): 0

Facility at Toe: Road/footpath with low traffic density

Distance of Facility from Toe (m): 0.5
Consequence-to-life Category: 3
Remarks: N/A

#### **SLOPE PART**

(1) Max. Height (m): 6 Length (m): 105 Average Angle (deg): 35

#### **WALL PART**

N/A

#### MAINTENANCE RESPONSIBILITY

(1) Sub Div.: 1 Mixed Feature Party: DD129 Lot1862 Agent: N/A Land Cat.: 1,5b(vi),7 Reason Code: 1 MR Endorsement Date: 01-06-

1999

(2) Sub Div.: 2 Mixed Feature Party: Lands D Agent: Lands D Land Cat.: 1,5b(vi),7 Reason Code: 62 MR Endorsement Date: 01-06-

1999

#### DETAILS OF SLOPE / RETAINING WALL

Date of Inspection: 01-11-2001
Data Source: El(Lands D)
Slope Part Drainage: N/A
Wall Part Drainage: N/A

#### **SLOPE PART**

Slope Part (1)

Other Cover: 0 Surface Protection (%): Bare: 0 Vegetated: 100 Chunam: 0 Shotcrete: 0

Material Description: Geology: Decomposed granite Material type: Soil No. of Berms: N/A Min. Berm Width (m): N/A Berm:

Size (mm): N/A Weepholes: Spacing (m): N/A

#### **WALL PART**

N/A

#### **SERVICES**

**Utilities Type: Water Main** Size(mm): 25 Location: On slope (1)Remark: N/A

#### CHECKING STATUS INFORMATION

Tagmark: 15084\_1\_5 Part: 1 Checking Status: No checking records Checking Certificate No.: N/A

#### **BACKGROUND INFORMATION**

GIU Cell Ref.: 2SW22A3 Map Sheet Reference (1:1000): 2SW-22A

**Aerial Photos:** 39309 (1981), 39310 (1981)

**Nearest Rainguage Station (Station** 

Number):

Hong Shui House, Shui Pin Wai Estate(N12)

Data Collected On: 01-11-2001

Date of Construction, Subsequent

**Modification and Demolition:** 

Before: 1981 Modification: Constructed After: 1979

Related Reports/Files or Documents: File/Report: Development Ref. No.: GCMW 9068/95

File/Report: Development Ref. No.: GCMW 9068/95 File/Report: Development Ref. No.: GCMW 9068/95 File/Report: Development Ref. No.: GCMW 9068/95

Remarks: N/A Follow Up Actions: N/A DH-Order (To Be Confirmed with

**Buildings Department):** 

None

**Advisory Letter (To Be Confirmed** 

with Buildings Department):

None

LPMIS: None

#### **ENHANCED MAINTENANCE INFORMATION**

From Maintenance Department: (Last Updated Date: 26/06/2025)

(T)	\GF '	I STL	INV	RFP	NRT
JIF	1UL	ו טוע	וטי	IVEI	UNI

Ins	specte	d Un:

Weather:

District: MW Section No: 1-1

Height(m):

Type of Toe Facility: Road/footpath with low traffic density

Distance from Toe(m): 0.5

Type of Crest Facility: Undeveloped green belt

Distance from Crest(m): 0

Consequence Category: Engineering Judgement:

Section No: 2-2

Type of Toe Facility:
Distance from Toe(m):
Type of Crest Facility:
Distance from Crest(m):
Consequence Category:
Engineering Judgement:

Sign of Seepage:

Criterion A satisfied:

Sign of Distress:

Criterion D satisfied:

Non-routine maintenance required:

Note:

Masonry wall/Masonry facing:

Note:

Consequence category (for critical

section):

Observations: N/A

**Emergency Action Required:** 

Action By: N/A

#### **ACTION TO INITIATE PREVENTIVE WORKS**

Criterion A/Criterion D: N/A
Action By: N/A

Further Study:

Action By: N/A

#### OTHER EXTERNAL ACTION

Check / repair Services:

Action By: N/A

Non-routine Maintenance:

Action By: N/A

#### **PHOTO**







Feature No. 2SW-C/C 69 2SW-2SW-5/CR 27 2SW-C/C 30 2SW-C/CR 28 2SW-C/C 53 2SW-C/C 48 2SW-C/C 328W-C/C 32 2SW-C 2SW-C/C 55 2SW-C/C 49 2SW-C/CR 125 墓地 2SW-2SW C/C 51 2SW-C/C 56 50 2SW-C/C 54 2SW-C/C 52 2SW-C/F 2SW-C/C CIC 88 2SW-C/C 65 2SW-C/F 11 2SW-C/C 69 2SW-C/F 10 2SW-C/C 70 25 W-C/C 2SW-C/C 雲浮仙觀 Wan Fau Sin Koon 露天貨倉 2SW-C/F 15 2SW-C/R 11 2SW-C/R 2SW-C/C 2SW-C/CR 101 2SW-C/CSW-C/C 2SW-C/C 97 64 W-C/C 86 2SW-C/C 98 2SW-C/C 2SW-C/C 96 2SW-286V402 2SW-C/C 81 2SW-C

2SW-C/F

#### **BASIC INFORMATION**

Location: Near Wan Fau Sin Koon, Deep Bay Road, Lau Fau Shan, Yuen Long.

Registration Date: 06-05-1998
Ranking Score (NPRS): 0 (EI)
Date of Formation: pre-1977

Date of Construction/ Modification:

Data Source: El(Lands D)

Approximate Coordinates: Easting: 817177 Northing: 837205

#### CONSEQUENCE-TO-LIFE CATEGORY

Facility at Crest: Road/footpath with low traffic density

Distance of Facility from Crest (m): 0

Facility at Toe: Lightly-used open area/facilities

Distance of Facility from Toe (m): 0

Consequence-to-life Category: 3

Remarks: N/A

#### **SLOPE PART**

(1) Max. Height (m): 5.5 Length (m): 42 Average Angle (deg): 30

#### **WALL PART**

N/A

#### MAINTENANCE RESPONSIBILITY

(1) Sub Div.: O Government Feature Party: Lands D Agent: Lands D Land Cat.: 5b(vi) Reason Code: 62 MR Endorsement Date: 06-07-1999

#### DETAILS OF SLOPE / RETAINING WALL

Date of Inspection: 17-03-2015
Data Source: El(Lands D)
Slope Part Drainage: N/A
Wall Part Drainage: N/A

#### **SLOPE PART**

Slope Part (1)

Surface Protection (%): Bare: 0 Vegetated: 100 Chunam: 0 Shotcrete: 0 Other Cover: 0

Material Description: Material type: Soil Geology: N/A

Berm: No. of Berms: N/A Min. Berm Width (m): N/A

Weepholes: Size (mm): N/A Spacing (m): N/A

#### **WALL PART**

N/A

#### **SERVICES**

N/A

#### **CHECKING STATUS INFORMATION**

N/A

#### **BACKGROUND INFORMATION**

GIU Cell Ref.: N/A
Map Sheet Reference (1:1000): N/A
Aerial Photos: N/A

Nearest Rainguage Station (Station ()

Number):

Data Collected On: 17-03-2015

Date of Construction, Subsequent

Modification and Demolition:

Modification: Constructed Before: 1981 After: 1978

Related Reports/Files or Documents: File/Report: DLC/BC Ref. No.: GCMW 4/1C/2-3 pt.3 f(20), pt.18 f(6, 7)

File/Report: DLC/BC Ref. No.: GCMW 4/1C/2-3 pt.3 f(20), pt.18 f(6, 7)

File/Report: LA Ref. No.: GCMW 5/3/10(W) pt. 6 f(55, 60) File/Report: LA Ref. No.: GCMW 5/3/10(W) pt. 6 f(55, 60)

Remarks: N/A
Follow Up Actions: N/A
DN Order /To Do Confirmed with New

DH-Order (To Be Confirmed with

 $\label{eq:buildings} \textbf{Department)}:$ 

LPMIS:

None

Advisory Letter (To Be Confirmed

None

with Buildings Department):

None

#### **ENHANCED MAINTENANCE INFORMATION**

From Maintenance Department: (Last Updated Date: 26/06/2025)

#### STAGE 1 STUDY REPORT

Inspected On:

Weather:

District: N/A
Section No: 1-1

Height(m):

Type of Toe Facility: Lightly-used open area/facilities

Distance from Toe(m): 0

Type of Crest Facility: Road/footpath with low traffic density

Distance from Crest(m): 0

Consequence Category: Engineering Judgement:

Section No: 2-2

Type of Toe Facility:
Distance from Toe(m):
Type of Crest Facility:
Distance from Crest(m):
Consequence Category:
Engineering Judgement:

Sign of Seepage: Criterion A satisfied: Sign of Distress:

Criterion D satisfied:

Non-routine maintenance required:

Note:

Masonry wall/Masonry facing:

Note:

Consequence category (for critical

section):

Observations: N/A

**Emergency Action Required:** 

Action By: N/A

#### **ACTION TO INITIATE PREVENTIVE WORKS**

Criterion A/Criterion D: N/A
Action By: N/A

Further Study:

Action By: N/A

#### OTHER EXTERNAL ACTION

Check / repair Services:

Action By: N/A

Non-routine Maintenance:

Action By: N/A

#### **PHOTO**

















# В

### **Latest Architectural Drawings**





## **Appendix B – Latest Architectural Drawings**



NICHE CALCULATION:

NEW COLUMBARIUM A (QUAD) = 84 No.s

NEW COLUMBARIUM B (QUAD) = 228 No.s

NEW COLUMBARIUM C (QUAD) = 200 No.s

NEW COLUMBARIUM C (DOUBLE) = 1104 No.s

NEW COLUMBARIUM D (DOUBLE) = 1720 No.s


NEW COLUMBARIUM E (QUAD) = 488 No.s


QUAD NICHES SUB-TOTAL = 1000 No.s DOUBLE NICHES SUB-TOTAL = 2824 No.s

TOTAL NOS. OF NICHE = 3,824 (NOT INCLUDE EXISTING SOLD NICHES)

- PLEASE NOTE THE COLUMBARIUM E (FAMILY PRECINCT) WOULD BE A DEDICATED ZONE, CONSISTING OF A RANGE OF 22 -32 NOS. OF INDIVIDUAL STRUCTURES FOR FAMILY NICHES WITH A BUILT OVER AREA OF NOT MORE THAN 319.732SQM. PLEASE NOTE THAT THE DESIGN OF THE COLUMBARIUM E IS INDICATIVE ONLY AND WILL BE SUBJECT TO REVIEW IN THE DETAILED DESIGN STAGE
  - THE FAMILY PRECINCT IS A DEDICATED ZONE THAT HOLDS MULTIPLE INDIVIDUAL STRUCTURES WITH FAMILY NICHES. THE SITE FEATURES A FAMILY PRECINCT WHERE GENERATIONS ARE HONOURED TOGETHER IN PRIVATE FAMILY NICHES

MASTER LAYOUT PLAN Aed 1:600@A1 +





LAND FILL AREA

LAND EXCAVATION AREA

Assume the land fill and excavate depth is measured to site formation level, instead of foundation bottom level

