

A photograph showing a close-up of a drainage grate. The grate is made of a metal mesh with circular holes. A brown, flexible pipe is inserted into the grate. The surrounding area is concrete and shows signs of wear and damage. A metal mesh is also visible on the right side of the grate.

位置:A

拍攝日期:2026-03-05



位置:B

拍攝日期:2026-03-05



位置:C

拍攝日期:2026-03-05



位置:D

拍攝日期:2026-03-05



位置: E

拍攝日期: 2026-03-05



位置:F

拍攝日期:2026-03-05