Our Ref: 33120

VARIOUS LOTS IN DD185, SHEUNG WO CHE NO. 198 SAI LAM TEMPLE, SHATIN, NEW TERRITORIES

GEOTECHNICAL PLANNING REVIEW REPORT (AMENDMENT 1)

APRIL 2025

Prepared by

Henry Chan

Registered Geotechnical Engineer

RGE 12/05

TABLE OF CONTENTS

R to C

<u>SE</u>	CTIO]	N		PAGE NO
1.	INTF	RODUCT	TION	1
2.	SITE	DESCR	IPTION	1
	2.1.	GENE	RAL	1
	2.2.	SUBJE	CT SITE GEOLOGY	1
		2.2.1.	Geological Map	1
		2.2.2.	Geotechnical Area Studies Programme (GASP)	2
		2.2.3.	Natural Terrain Hazards	2
		2.2.4.	Previous Ground Investigation Records	2
	2.3.	ADJOI	NING STRUCTURES	3
	2.4.	ADJOI	NING GEOTECHNICAL FEATURES	3
3.	PRO	POSED '	WORKS FOR SITE	3
4.	EFFI	ECT ON	ADJACENT GROUND	4
5.	CON	CLUSIC	ONS AND RECOMMENDATIONS	4
<u>AP</u>	PEND	<u>ICES</u>		
AP	PEND	IX A	APPLICATION SITE (THIS ADMENDMENT)	
			APPLICATION SITE (OCTOBER 2020 SUBMISSION	J)
AP	PEND	IX B	SITE LOCATION PLAN AND GENERAL VIEWS	
AP	PEND	IX C	GEOLOGICAL MAP AND GASP	
ΑP	PEND	IX D	SLOPE INFORMATION SYSTEM (SIS) RECORDS	

1 INTRODUCTION

1.1 The Site Sai Lam Temple is at Lot No. 63, 296 (part), 331 RP (part) & 393 RP (part) in DD185, Sheung Wo Che no. 198, Sai Lam Temple, Shatin, New Territories Section 12A was made by Toco Planning Consultants Ltd to apply for regularization of the existing columbarium at the Site. An application to Town Planning Board is thus necessary. Under Town Planning Ordinance (CAP. 131), the applicant should submit a Geotechnical Planning Review Report (GPRR) with the planning application.

A Geotechnical Planning Review Report (GPRR) for the Site was submitted in October 2020. Subsequent comment to the Application was offered by CEDD (GEO). This is an Amendment Report presents latest site application layout and Response to Comments(R to C).

- 1.2 The area of the Application Site is actually reduced to Lot 63 and Lot 296 (Part) only as shown in Appendix A. The application site entailed in previous report is also attached in Appendix A for easy comparison.
- 1.3 All basic site geology information geotechnical contents of the Report based on 2020 version is still valid, comments by CEDD on the aforementioned Report is still valid. (R to C refers)
- 1.4 The number of registered geotechnical features are reduced to three registered features within the Application site.

2 SITE DESCRIPTION

2.1 GENERAL

The Site is currently occupied by existing building blocks A to E. General views of the existing conditions of the Site are attached in Appendix B for easy reference, together with a Site Location Plan.

2.2 SUBJECT SITE GEOLOGY

To reveal the geological information for the Site, the following information was reviewed and attached:

• 1:20,0000 – scale geological map;

- Geotechnical Area Studies Programme (GASP);
- Enhanced Natural Terrain Landslide Inventory (ENTLI);
- Existing Borehole Records

2.2.1 Geological Map

Based on the 1:20,000 scale Hong Kong Geological Survey Map for Shatin (Sheet No.: 5 HKGS – 2008 Edition), the Site is inferred to be underlain by solid geology Porphyritic medium and fine grain Granodiorite, Lamma Suite.

2.2.2 Geotechnical Area Studies Programme (GASP)

According to Geotechnical Area Studies Programme (GASP), Geotechnical Land Use Map Central New Territories GASP/20/II/1(2nd Ed), the Site is classified as Class II with Moderate Geotechnical limitations. The Physical Constraints Map North New Territories Map No. GASP/20/II/6 (2nd Ed) indicate the Site generally has no physical constraints. Generalised Limitations and Engineering Appraisal Map No. GASP/20/II/15 (2nd Ed) indicate the Site has no major concern.

Extracts of relevant GASP Maps are shown in **Appendix C** respectively.

2.2.3 Natural Terrain Hazards

There is no natural terrain present in the vicinity of the application site.

2.2.4 Previous Ground Investigation Records

No near ground investigation records could be found.

2.3 ADJOINING STRUCTURES

The nearby structures are squatters of Pai Tau Hang Hong Village located to the Site North. As the Site do not require any site formation, ELS and foundation works as such. These low rise structures will not affect adversely affect or be affected by Sai Lam Temple.

There are no other development nearby.

2.4 ADJOINING GEOTECHNICAL FEATURES

There are altogether 3 numbers of registered geotechnical features maintain by the lot owners. It should be noted that 7SW-B/CR362(1) is excluded outside the zoning application site under this application.

	Feature	Responsibilities lot / boundary	Remarks
1.	7SW-B/CR362(1)	DD185 Lot 296	-
2.	7SW-B/R102	DD185 Lot 296	-
3.	7SW-B/R96	DD185 Lot 296	-

All relevant registered slope information are attached in Appendix D.

Based on current desk study's findings, all the above 3 Features maintained by the Lot Owners has no record of Engineer Inspection been carried out. There are relevant documents to some Features that Stage Studies and LPM Studies have been carried out under Government contract, the current status of such Features understudy have not been fully established at this stage. Hence, further studies to all three Features including further ground investigation works to established each individual Factor of Safety is upto current Government safety standard is required. Based on GI findings, all slope stabilities shall be established and if found necessary to upgrade the Features upto current standard. All the above geotechnical works are required to be submitted to Buildings Department for approval.

3. PROPOSED WORKS FOR SITE

All existing structures on the Site do not require any further construction works. Hence, no site formation nor foundation work would be required.


4. EFFECT ON ADJACENT GROUND

The Site will required detail checking to all relevant Registered Slope Features to ensure each individual stability. Upgrade these as found necessary to ensure these Features will not adversely affect or be affected by the existing building Blocks within the application site. Although 7SW-B/CR362(1) lies outside the zoning plan, this Feature is maintained by the subject lot owners, in view of its close proximity, it is recommend include into further study.

5. CONCLUSIONS AND RECOMMENDATIONS


No further geotechnical works we envisaged to the existing building blocks. However, there are although 3 Registered Features responsible by Sai Lam Temple. Further studies to these Features are required, if found necessary to carry out slope upgrading works. All proposed works shall be submitted to Buildings Department for approval.

APPENDIX A APPLICATION SITE (THIS ADMENDMENT)




APPENDIX A

APPLICATION SITE (OCTOBER 2020 SUBMISSION)



APPENDIX B SITE LOCATION PLAN AND GENERAL VIEWS












Photo 1: Main Entrance of Sai Lam Temple



Photo 3: Building A (Worshipping Area)



Photo 5: Building B



Photo 7: Columbarium Halls on 1/F of Building E



Photo 2: Pedestrian Access and Gathering Area



Photo 4: Worshipping Area in Building A



Photo 6: Worship Hall on 1/F of Building E



Photo 8: Building C



Site Photos (1): Site Condition



Photo 9: Building D



Photo 11: Columbarium Hall on G/F of Building E (Previously Named '龍華堂')



Photo 13: Management Office



Photo 15: Bus Terminus near the Site



Photo 10: Building E



Photo 12: Shop



Photo 14: Temple Adjoining the Application Site (三元宮)





Photo 16: Sha Tin Railway Station near the Site





Site Photos (2): Site and Adjacent Land Uses


APPENDIX C GEOLOGICAL MAP AND GASP

























22 Low density development could be increased. Moderate to deep weathering on granite.

Ridges and adjacent colluvial valleymers and floors could be developed in floors conjunction as split-level platforms.

Now Substitution of split-level platforms.

Now Substitution of split-level platforms.

And Properties of Substitution of Substitution

Right Street along of the same	Steep upper Slope	E STATE OF THE STA	Wai	HEBE ANOLI MONTSE CHE
Po Z Ka	by andslide hazard fazard fazard	Kautin Waller Kautin Ka		Was Pitt

Note: The topographic base of this map is derived from Sheet 6 - Edition 2 of 1979, Sheet 7 - Sheet 10 - Edition 2 of 1980 and Sheet 11 - Edition 2 of 1979 of the HM2OC Series produ and Mapping Office of the Buildings and Lands Department, Hong Kong.

				LEGEND			
DEVELO	DEVELOPMENT PLANNING ZONES :	FEATUR	FEATURES OF ENGINEERING SIGNIFICANCE	I		Abbreviations	: 50
	Zone of potential for development (assessed in geotechnical terms)	-	Geological photolineament		Instability influencing area	cont.	control
	Zone of local geotechnical constraints (identified on PCM) within general PDA	<u> </u>	Ridgeline		Potential for borrow or extensive cut and fill :	devt. gran.	develo _l granite
	Zone of constraints for development (assessed principally in geotechnical terms)	=10==0=	Drainage, incised drainage			instab.	instabi
	Zone of existing development, (based on principal use of GEOTECS 2 hectares unit)	υ	Colluvium (also in 'zone of local constraints', and PCM)	NOTE		. pom	moder
•	Country Park boundary	Str.	Structure	Ovol Hono	Features are generally indicated only where	pot.	potenti
	Catchwater		91	TON	of significance to identified potential development areas	sed.	sedime
	High voltage power lines	*	Weathering	7)	ii) For explanation of significance of identified features,	sh.	shallov
NOTE	Numerals on map refer to relevant general	a ¹	Boulders	CIVIL ENGL		st.	steep
24 77 830	Reference	DDDD	Steeper slopes influencing area (orientation of symbols indicates downslope direction)	TE P	iii) Geological boundaries and photolineaments are shown in full on the EGM. Those lineaments indicated represent the surface expression of obvious structural discontinuities which affect the PDA's	volc.	volcan

MAP	Brown
APPRAISAL	
RING	DRIES

CIVIL ENGINEERING DEPARTMENT	AN LLITS	- 53682
CIVIL ENGINEER	CIVIL F	ACC. NO. \$66

I

O

Titie: GENERALIS	Titio: GENERALISED LIMITATIONS AND ENGINEERING APPRAIS CENTRAL NEW TERRITORIES	ITATIONS AND ENGINEERING CENTRAL NEW TERRITORIES	VEERING A	PPRAIS
Compiled:	A. Hansen	Drawn:	S. B.	S. B. Ho/S.
Scale:	1:20 000	Date:	Original May, 1 2nd Edition Ju	May, 1
Map Ref. No:	GASP/20/11/15 2nd Edition	2nd Edition	Sheet:	et:

Published by the Geotechnical Control Office, Civil Engineering Services Depa

APPENDIX D SLOPE INFORMATION SYSTEM (SIS) RECORDS

Slope Maintenance Responsibility Report

(DD185 Lot 296)



List of Slope Maintenance Responsibility Area(s)

1	7SW-B/CR362		Sub-Division	1
	Location	Partly within DD185 LOT 296	and partly on unallocated Government land	
	Responsible Lot/Party	DD185 LOT 296	Maintenance Agent	Not Applicable
	Remarks	Not Applicable		
2	7SW-B/R102		Sub-Division	Not Applicable
	Location	WITHIN STTL249 & ADJOIN	NING GOVERNMENT LAND SUPPORTING THE LOT	
	Responsible Lot/Party	DD185 LOT296	Maintenance Agent	Not Applicable
	Remarks Not Applicable			
3	7SW-B/R96		Sub-Division	Not Applicable
	Location WITHIN SOUTH PORTION C		OF DD185 LOT296	
	Responsible Lot/Party	DD185 LOT296	Maintenance Agent	Not Applicable
	Remarks	Not Applicable		


- End of Report -

Notes:

- (i) The location plan in Annex is for identification purposes of slope(s) only.
- (ii) The slope(s) as listed in the Slope Maintenance Responsibility Report may not be shown on the location plan in Annex.

The use of this report and plan is subject to the terms and conditions set out under the respective Disclaimers, Copyright Notice and Privacy Policy displayed on the Slope Maintenance Responsibility Information System webpage at http://www.slope.landsd.gov.hk/smris/disclaimer. The contents of this report and plan, including but not limited to all text, graphics, drawings, diagrams and compilation of data or other materials are protected by copyright. The users of this report and plan acknowledge that the Government of the Hong Kong Special Administrative Region is the owner of all copyright works contained in this report and plan. Any reproduction, adaptation, distribution, dissemination or making available of any copyright works contained in this report and plan to the public is strictly prohibited unless prior written authorization is obtained from the Lands Department.

Search Criteria: DD185 Lot 296






This Plan is **NOT TO SCALE** and intended for **IDENTIFICATION** only. All information shown on this plan **MUST** be verified by field survey.

Printed on: 27/03/2025

The use of this report and plan is subject to the terms and conditions set out under the respective Disclaimers, Copyright Notice and Privacy Policy displayed on the Slope Maintenance Responsibility Information System webpage at http://www.slope.landsd.gov.hk/smris/disclaimer. The contents of this report and plan, including but not limited to all text, graphics, drawings, diagrams and compilation of data or other materials are protected by copyright. The users of this report and plan acknowledge that the Government of the Hong Kong Special Administrative Region is the owner of all copyright works contained in this report and plan. Any reproduction, adaptation, distribution, dissemination or making available of any copyright works contained in this report and plan to the public is strictly prohibited unless prior written authorization is obtained from the Lands Department.



BASIC INFORMATION

Location:

WEST OF NO. 194 PAI TAU TSUEN, SHATIN, N.T.

Registration Date:

06-05-2003

Ranking Score (NPRS):

14 (LPMit)

Date of Construction/

Pre-1977

Modification:

Data Source:

LPM

Approximate Coordinates:

Easting : 837463

Northing: 827470

CONSEQUENCE-TO-LIFE CATEGORY

Facility at Crest:

Temple

Distance of Facility from Crest (m):

2.5

Facility at Toe:

Temple

Distance of Facility from Toe (m):

2.5

Consequence-to-life Category:

1

Remarks:

N/A

SLOPE PART

N/A

WALL PART

(1) Max. Height (m): 3.2

Length (m): 20

Face Angle (deg): 85

MAINTENANCE RESPONSIBILITY

(1) Sub Div.: O Private Feature Party: DD185 LOT296 Agent: N/A Land Cat.: 1 Reason Code: 1 MR Endorsement Date: 01-09-2004

DETAILS OF SLOPE / RETAINING WALL

Date of Inspection:

16-04-2012

Data Source:

LPM

Slope Part Drainage:

N/A

Wall Part Drainage:

NI/A

SLOPE PART

N/A



WALL PART

Wall Part (1)

Type of Wall: Wall Material: Masonry

Wall Location: Retaining wall with level platform

Berm:

No. of Berms: N/A

Min. Berm Width (m): N/A

Weepholes:

Size (mm): N/A Spacing (m): N/A

SERVICES

N/A



CHECKING STATUS INFORMATION

Tagmark: SCS_7638 Part: 0 Checking Status: Others (See remarks)

BACKGROUND INFORMATION

GIU Cell Ref.:

7SW15B3

Map Sheet Reference (1:1000):

7SW-15B

Aerial Photos:

19893-4 (1977),

Nearest Rainguage Station

Shun Wo House, Wo Che Estate(NO2)

(Station Number):

Data Collected On:

16-04-2012

Date of Construction, Subsequent

Modification and Demolition:

Modification: Constructed

Before: 1977 After: 0

Related Reports/Files or Documents:

N/A

Remarks:

N/A

Follow Up Actions:

N/A

DH-Order (To Be Confirmed with Buildings Department):

Advisory Letter (To Be Confirmed with Buildings Department):

None

LPMIS: None

ENHANCED MAINTENANCE INFORMATION

From Maintenance Department: (Last Updated Date: 15/09/2020)

STAGE 1 STUDY REPORT

Inspected On: 11-10-2002

> Weather: **Mainly Fine**

District: MW

Section No: 1-1

Height(m):

H1:3,H2:3

Type of Toe Facility:

Temple

Distance from Toe(m):

2.5

Type of Crest Facility:

Temple

Distance from Crest(m): 2.5

Consequence Category:

Engineering Judgement:

Section No:

2-2

Type of Toe Facility:

Distance from Toe(m):

Type of Crest Facility:

Distance from Crest(m):

Consequence Category:

Engineering Judgement:

Sign of Seepage:

Slope: N/A

Wall: Signs of seepage

Criterion A satisfied:

Sign of Distress:

Slope: N/A Wall: Minimal(near crest, mid-portion)

Criterion D satisfied:

Non-routine maintenance required:

N N/A

Note:

Masonry wall/Masonry facing:

Note:

DRESSED BLOCK WITH POINTING

Consequence category (for critical section):

Observations:

Action By:

N/A

Emergency Action Required:

N/A

ACTION TO INITIATE PREVENTIVE WORKS

Criterion A/Criterion D:

N/A

Action By:

N/A

Further Study:

Action By:

Government

OTHER EXTERNAL ACTION

Check / repair Services:

N

Action By:

N/A


Non-routine Maintenance:

N

Action By:

PHOTO





BASIC INFORMATION

Location:

Sheung Wo Che Village, Sha Tin.

Registration Date:

19-11-1997

Ranking Score (NPRS):

327 (EI)

Date of Construction/

Pre-1977

Modification:

Data Source:

LPM

Approximate Coordinates:

Easting : 837452

Northing: 827483

CONSEQUENCE-TO-LIFE CATEGORY

Facility at Crest:

Road/footpath with low traffic density

Distance of Facility from Crest (m):

0

Facility at Toe:

Cottage, licensed and squatter area

Distance of Facility from Toe (m):

11/: |

Consequence-to-life Category:

Remarks:

N/A

SLOPE PART

(2) Max. Height (m): 3.5

Length (m): 15

Average Angle (deg): 55

WALL PART

(2) Max. Height (m): 3.5

Length (m): 15

Face Angle (deg): 90

Feature No. 7SW-B/CR 362

MAINTENANCE RESPONSIBILITY

(1) Sub Div.: 1 Mixed Feature Party: DD185 LOT 296 Agent: N/A Land Cat.: 1 Reason Code: 1 MR Endorsement Date: 15-08-2018 (2) Sub Div.: 2 Mixed Feature Party: Lands D Agent: Lands D Land Cat.: 5b(vi) Reason Code: 62 MR Endorsement Date: 15-08-2018

DETAILS OF SLOPE / RETAINING WALL

Date of Inspection:

21-12-2016

Data Source:

Slope Part Drainage:

LPM

Position: Toe Size(mm): 300

Wall Part Drainage:

N/A

SLOPE PART

Slope Part (1)

Surface Protection (%):

Bare: 0

Vegetated: 100

Chunam: 0

Shotcrete: 0 Other Cover: 0

Material Description:

Material type: Soil

Geology: N/A

Berm: Weepholes: No. of Berms: $\ensuremath{\text{N}}/\ensuremath{\text{A}}$

Min. Berm Width (m): N/A

Size (mm): N/A

Spacing (m): N/A

WALL PART

Wall Part (1)

Type of Wall: Wall Material: Concrete Wall Location: Wall at toe
Berm: No. of Berms: N/A Min. Berm Width (m): N/A

Weepholes:

Size (mm): N/A Spacing (m): N/A

SERVICES

(1) Utilities Type: Water Main Size(mm): 30 Location: On slope Remark: N/A



CHECKING STATUS INFORMATION

Tagmark: SCS_7637

Part: 0

Checking Status: Others (See remarks)

Tagmark: SCS_17201 Part: 0

Checking Status: Feature to be upgraded by prescriptive measures and GEO Checking being

waived

BACKGROUND INFORMATION

GIU Cell Ref .:

7SW15B3

Map Sheet Reference (1:1000):

7SW-15B

Aerial Photos:

Y12441-2 (1964),

Nearest Rainguage Station

(Station Number):

Shun Wo House, Wo Che Estate(NO2)

Data Collected On:

21-12-2016

Date of Construction, Subsequent

Modification and Demolition:

Modification: Constructed

Before: 1963

After: 1949

Related Reports/Files or Documents:

File/Report: Development

Ref. No.: GCMd 2/B3/68

File/Report: Development

Ref. No.: GCMd 2/B3/68

Remarks:

N/A

Follow Up Actions:

DH-Order (To Be Confirmed with Buildings Department):

None

Advisory Letter (To Be Confirmed with Buildings Department):

Date of Recommendation to BD: N/A Date Served by BD: 14/06/2019 File Reference: N/A

LPMIS: N

None

ENHANCED MAINTENANCE INFORMATION

From Maintenance Department: (Last Updated Date: 15/09/2020)

STAGE 1 STUDY REPORT

Inspected On:

17-03-1997

Weather:

Some Rain

District: ME

Section No:

1-1

Height(m):

H1:4,H2:0

Type of Toe Facility:

Cottage, licensed and squatter area

Distance from Toe(m):

Type of Crest Facility:

Road/footpath with low traffic density

Distance from Crest(m):

Consequence Category:

Engineering Judgement:

Section No:

2-2

Type of Toe Facility:

N/A

Distance from Toe(m):

0

Type of Crest Facility:

N/A

Distance from Crest(m):

Consequence Category:

Engineering Judgement:

Feature No. 7SW-B/CR 362

Sign of Seepage:

Slope: No signs of seepage

Wall: N/A

Criterion A satisfied:

N

Sign of Distress:

Slope: Reasonable (near crest, mid-portion, at toe)

Wall: N/A

Criterion D satisfied:

N

Non-routine maintenance required:

N N/A

Note:

Masonry wall/Masonry facing:

N N/A

Note:

Consequence category (for critical section):

1

Observations:

N/A

Emergency Action Required:

N

Action By:

N/A

ACTION TO INITIATE PREVENTIVE WORKS

Criterion A/Criterion D:

N/A

Action By:

N/A

Further Study:

Υ

Action By:

Mixed

OTHER EXTERNAL ACTION

Check / repair Services:

N

Action By:

N/A

Non-routine Maintenance:

N

Action By:




PHOTO











BASIC INFORMATION

Location:

18M, NORTH OF NO.194, SHEUNG WO CHE TSUEN, SHATIN

Registration Date:

03-06-2003

Ranking Score (NPRS):

5 (LPMit)

Date of Construction/

Pre-1977

Modification:

):

Data Source:

Agreement CE 60/2002 (GE)

Approximate Coordinates:

Easting: 837489 Northing: 827505

CONSEQUENCE-TO-LIFE CATEGORY

Facility at Crest:

Densely-used open area/facilities

Distance of Facility from Crest (m):

0

Facility at Toe:

Temple

Distance of Facility from Toe (m):

Consequence-to-life Category:

aregory:

Remarks:

N/A

SLOPE PART

N/A

WALL PART

(3) Max. Height (m): 3

Length (m): 4

Face Angle (deg): 90

MAINTENANCE RESPONSIBILITY

(1) Sub Div.: O Private Feature Party: DD185 LOT296 Agent: N/A Land Cat.: 1 Reason Code: 1 MR Endorsement Date: 14-10-2003

DETAILS OF SLOPE / RETAINING WALL

Date of Inspection:

19-11-2002

Data Source:

Agreement CE 60/2002 (GE)

Slope Part Drainage:

N/A

Wall Part Drainage:

N/A

SLOPE PART



WALL PART

Wall Part (1)

Type of Wall:

Wall Material: Concrete

Wall Location: Retaining wall with level platform

Berm:

No. of Berms: N/A

Min. Berm Width (m): N/A

Weepholes:

Size (mm): N/A

Spacing (m): N/A

SERVICES

- (1) Utilities Type: Electricity Size(mm): O Location: On crest Remark: Size cannot be determined
- (2) Utilities Type: Water Main Size(mm): 20 Location: On crest Remark: N/A



CHECKING STATUS INFORMATION

Tagmark: SCS_7639 Part: 0 Checking Status: Others (See remarks)

BACKGROUND INFORMATION

GIU Cell Ref.:

7SW15B3

Map Sheet Reference (1:1000):

7SW-15B

Aerial Photos:

Y12441-2 (1964),

Nearest Rainguage Station

Shun Wo House, Wo Che Estate(NO2)

(Station Number):

Data Collected On:

19-11-2002

Date of Construction, Subsequent

Modification and Demolition:

Modification: Constructed

Before: 1964

After: 0

Related Reports/Files or Documents:

N/A

Remarks:

N/A

Follow Up Actions:

DH-Order (To Be Confirmed None with Buildings Department):

Advisory Letter (To Be Confirmed with Buildings Department):

LPMIS: None

ENHANCED MAINTENANCE INFORMATION

From Maintenance Department: (Last Updated Date: 15/09/2020)

STAGE 1 STUDY REPORT

Inspected On:

19-11-2002

Weather:

Mainly Fine

District:

: MW

Section No:

1-1

Height(m):

H1:3, H2:3

Type of Toe Facility:

Temple

Distance from Toe(m):

0

Type of Crest Facility:

Densely-used open area/facilities

Distance from Crest(m):

): 0

Consequence Category:

Engineering Judgement:

Section No:

2-2

Type of Toe Facility:

Distance from Toe(m):

Type of Crest Facility:

Distance from Crest(m):

Consequence Category:

Engineering Judgement:

D

Sign of Seepage:

Slope: N/A

Wall: Signs of seepage

Criterion A satisfied:

N

Sign of Distress:

Slope : N/A

Wall: N/A

Criterion D satisfied:

N

Non-routine maintenance required:

N N/A

Note:

4

Masonry wall/Masonry facing:

N

Note: N/A

Consequence category (for critical section):

1

Observations:

N/A N

N/A

Emergency Action Required:

Action By:

ACTION TO INITIATE PREVENTIVE WORKS

Criterion A/Criterion D:

N/A

Action By:

N/A

Further Study:

Υ

Action By:

Private

OTHER EXTERNAL ACTION

Check / repair Services:

N

Action By:

N/A

Non-routine Maintenance:

N

Action By:



<u> PHOTO</u>







