

Table 1: Responses to Comments from Fire Services Department on Planning Application No. A/NE-LYT/868 (16 March, 2026)

COMMENTS		RESPONSES	
1.	Fire Services Department (Contact Person: Mr. LI Chi-fung; Tel: 2733 5844)		
	Based on the revised fire services installations (FSIs) proposal, he has the following comments:		
(1)	According to FSD Circular Letter No. 5/2020 (https://www.hkfsd.gov.hk/eng/source/circular/2020_05_eng_20200911_151307.pdf), the sprinkler inlet and control valve shall be located in a prominent position on the exterior of the building, near the entrance.	(1)	The sprinkler inlet and control valve will be provided in a prominent position on the exterior of the building, near the entrance (see the revised FSIs proposal attached).