Your Ref.: A/YL-HTF/1189 Our Ref.: 24034

Comments from Drainage Services Department dated 1.8.2025

Contact Person: Mr. Daniel CHAN (Tel: 2332 2471)

Comments	Responses
The proposed installation of weir inside the	Weir will not be installed inside the drainage pipe.
drainage pipe will likely reduce the pipe size and	A downpipe will be installed at the outlet of the
drainage flow. Please review the way to reduce the	drainage pipe to reduce the velocity of the flow.
velocity. If the proposed weir installation is	
maintained, please supplement details including	Please refer to the attached drawing for details.
drawing to show the weir inside the drainage pipe,	
and assess the drainage impact in calculation	
accordingly.	