

Serial Number

10059628132






Name of Client 顧客姓名

Hong Kong Concrete Company Limited

**Part 1 Annual Maintenance ONLY****第一部 只適用於年檢事項**

In accordance with Regulation 8(b) of the Fire Service (Installations and Equipment) Regulations, the owner of any fire service installation or equipment which is installed in any premises shall have such fire service installation or equipment inspected by a registered contractor at least once in every 12 months. 根據消防(裝置及設備)規例第八條(b)款, 擁有裝置在任何處所內的任何消防裝置或設備的人, 須每12個月由一名註冊承辦商檢查該等消防裝置或設備至少一次。

Code 編碼 (1-35)	Type of FSI 裝置類型	Location(s)位置	Comment on Condition 狀況評述	Completion Date 完成日期 (DD/MM/YYYY)	Next Due Date 下次到期日 (DD/MM/YYYY)
12	Exit Signs	G/F - M/F, R/F	Conforms with FSD requirement	25/04/2023	24/04/2024
13	Fire Alarm System	G/F - M/F, R/F	Defects see part 3	25/04/2023	24/04/2024
15	Fire Detection System	G/F - M/F, R/F	Conforms with FSD requirement	25/04/2023	24/04/2024
16	FH / HR System	G/F - M/F, R/F	Defects see part 3	25/04/2023	24/04/2024
28	Sprinkler System	G/F - M/F, R/F	Defects see part 3	25/04/2023	24/04/2024



Serial Number






10059628132

Name of Client 顧客姓名

Hong Kong Concrete Company Limited

## Part 3 第三部 Defects 損壞事項

Code 編碼 (1-35)	Type of FSI 裝置類型	Location(s)位置	Outstanding Defects 未修缺點	Comment on Defects 缺點評述
16	FH / HR System	G/F	FS inlet x 1 - over 4 years without detail inspected	need to inspect
28	Sprinkler System	G/F	Spr. inlet & Spr. control valve set - over 4 years without detail inspected	need to inspect
28	Sprinkler System	G/F	Water alarm gong x 1 no. Malfunction	need to replace



Serial Number

10059628132

Name of Client 顧客姓名

Hong Kong Concrete Company Limited

