Comments		Response
1. (	Comments of the Director of Environmental Protection Department as follows:	
<u>I</u>	EPD's Comments on the EA	
<u>(</u>	Comments on General	
1.	Section 1.1 and 1.2: Please revise as " at Lot 232 Various Lots in D.D. 23" and	Section 1.1 and 1.2 are revised accordingly.
	update all relevant sections accordingly.	
<u>(</u>	Comments on air quality assessment	
2.	Section 2.1.1: Please supplement the information about the future predicted	Future predicted background air quality is supplemented in Section 2.2.1 and Table 2-2 for review.
	background air quality by quoting PATH data.	
3.	Section 2.1.2: Since this section is about the ASRs but not "Air Quality Standards", it	The section of ASRs is moved to Section 2.2 accordingly.
	should not be under Section 2.1. Please assign this section to be Section 2.2 and move	
	it before the section "Construction Air Quality Impact".	
4.	Section 2.1.2: Please check whether there will be any planned development on the	According to the Town Planning Board, there is no planned development within 500m study area
	north-western side of the proposed development.	of the proposed development.
5.	Section 2.1.2: Please supplement a figure to show the location points of the identified	Representative ASRs of the proposed development during operational phase are presented in
	ASRs of the proposed development during operational phase.	Figure 2.1.2 to 2.1.4. More than 5m buffer distance between the first-tier ASRs and the access
		road is allowed.
6.	Section 2.1.3: Please also include the buffer distance requirement for odour source.	Buffer distance requirement in accordance with HKPSG Ch.9 is supplemented in Table 2-3.
7.	Section 2.2 and Table 2-4: The distances quoted in this section for Treasure Spot	Section 2.3 is revised accordingly.

Comments		Response
	Garden II are not consistent with Table 2-4. Please clarify whether the distance	
	between Treasure Spot Garden II and the proposed development is 7m or 10m or 14m	
	and make consistent.	
8.	Section 2.2: Please improve the readability of the sentence "other ASRs are not	Section 2.3 is revised accordingly.
	immediately located the Project Site and".	
9.	Section 2.3.1: Please be reminded to provide the confirmation from Transport	Confirmation from Transport Department will be provided once available.
	Department for the road types which is important for determining the buffer distance	Please refer to Appendix 2.1 (Figure 2.1.2-2.1.4) of the buffer distance information.
	requirements. Also, there is no information about the buffer distance in Appendix 1.1.	
	Please check.	
10.	Appendix 2.1, Figure 2.1.1a: Please overlay the PATH gird.	PATH grid with coordination is supplemented in Figure 2.1.1a accordingly.
11.	Appendix 2.1, Figure 2.1.2: Our previous comment has not been addressed properly.	Please be kindly advised that the proposed building layout has been revised which allows
	The buffer distance shown in this figure is not clear. Please rectify.	sufficient buffer distance between sensitive uses and Project boundary. Please refer to Figure 2.1.2
<u>C</u>	Comments on noise assessment	to 2.1.4 for review.
12.	Item 17 of RtC: The endorsement of traffic data from the Transport Department should	Noted, the endorsement of traffic data from the Transport Department will be provided once
	be provided and appended before finalizing the EA report.	available.
13.	Section 3.1.2: Please confirm and supplement the thickness of the window pane at the	Section 3.1.2 is updated accordingly.
	last sentence by adding the wording "The openable window is well-gasketted with at	
	least 6mm thick window pane".	

Comments	Response
14. Section 3.4.1: Please review whether the last sentence should mean "However, the	Section 3.4.1 is revised accordingly.
noise impact of those small power rating outdoor units shall be minimal, and adverse	
noise impact from these outdoor units is not anticipated."	
15. Section 3.4.2: Please add the examples of the noise mitigation requirements, such as	Section 3.4.2 is updated accordingly.
the use of silencer and noise enclosure, in governing the allowable sound power level	
for the cooling towers.	
16. Figure 3.2.2: The figure shows that there are silencers at cooling tower air intake with	Indication at Figure 3.2.2 is removed to avoid confusion. Suitable fixed noise mitigation measure
IL 20 dB(A) but it is not mentioned in the report. Please clarify.	would be designed and applied by the design and build contractor.
17. Figure 3.2.3:	
- Please explain why the 1st layer of the village houses, i.e. 86 Wai Ha and 96 Wai	Representative NSRs of Figure 3.2.3 are revised accordingly.
Ha, are not selected as the representative NSRs.	
- Please provide a table showing the address for NSR01 - 03 in Section 3.4.1.	Table 3-5 is supplemented in Section 3.4.1 accordingly.
Comments on water quality assessment	
18. Section 4.3: Paragraph above Table 4-2: please check if reference to Appendix 4.2 is	The section should refer to Appendix 4.1. Revised accordingly.
correct.	

Comments	Response
19. Table 4-2: Please validate the presence of WSR1.	According to site survey and desktop study, there is a section of U-channel at the west of the site.
	Location of WSR1 is amended accordingly.
	U-channel  BLOCK 15 BLOCK 15 BLOCK 15 BLOCK 15 BLOCK 25 B

Comments	Response
20. Section 4.4.2: Please revise as "Sediment laden runoff".	Section 4.4.2 is revised accordingly.
21. Section 4.4.5: Please revise as "no unacceptable adverse water quality impacts	Section 4.4.5 is revised accordingly.
would be arising".	
22. Section 4.6.1: The number of bedspaces (428 no.) does not match with Section 1.2.	The confirmed number of bedspaces should be 225+40=265. Section 4.6.1 is revised.
23. Table 4-3:	
- Please correct the typo "Tung Tyz".	Typo of Table 4-3 is revised accordingly.
- The no. of residents (253) does not match with Section 1.2	
- Please update the table in accordance with the latest SIA Report.	Table 4-3 is updated in accordance with the latest SIA Report accordingly.
24. Figure 4.1.1:	
- Please align text with icons in legend.	Legend of Figure 4.1.1 is amended accordingly.
- Suggest to place a red dot next to WSR5, similar to other WSRs.	Red dot is placed to WSR5 accordingly.

Comments		Response
1.	Comments of the Director of Environmental Protection Department as follows:	
	RtC Item 6: Your response is not justified. In section 4iv) and section 5, despite the	The number of the existing foul manhole for proposed sewage discharge is provided in Section
	sewage generation from the proposed development may be small, it does not guarantee	4.5.
	there are no impact induced at all. Besides, information on which exact manhole (and	Hydraulic calculations are supplemented in the revised report and detailed in Appendix A to
	its manhole no.) would your generated sewage be discharged to was not provided.	demonstrate the increase sewage flow from the proposed development will have no adverse
	Please obtain flow data of all upstream developments (e.g. Treasure Spot Garden phase	impact to the existing system.
	2) and demonstrate with hydraulic calculations on whether the cumulative impact	
	downstream is acceptable.	