## Gold Rich Planners & Surveyors Ltd.

#### 金潤規劃測量師行有限公司

Your Ref.: A/YL-TYST/1335

Our Ref.: P25053/TL25346

16 October 2025

The Secretary
Town Planning Board
15/F., North Point Government Offices
333 Java Road, North Point, Hong Kong

By Post and E-mail tpbpd@pland.gov.hk

Dear Sir,

#### Submission of Further Information (FI)

Renewal of Planning Approval for Temporary Shop and Services for a Period of 3 Years in "Residential (Group B)1" Zone, Lot 1075 (Part) in D.D. 121 and Adjoining Government Land, Tong Yan San Tsuen, Yuen Long, New Territories

(Application No. A/YL-TYST/1335)

We write to submit FI in response to departmental comment(s) for the captioned application. We would also like to submit a set of drainage photographs taken on 13.10.2025 with the approved drainage proposal showing the viewpoints of the photos (**Plan 5**) and the approved FSI proposal (**Plan 6**) with FS251 certificate for the captioned application. It serves to supersede our previous FI submission under our reference P25053/TL25342 dated 14.10.2025.

Yours faithfully, For and on behalf of Goldrich Planners & Surveyors Ltd.

Francis LAU

Encl.


c.c.

DPO/TM&YLW, PlanD (Attn.: Mr. Edwin YEUNG) By E-mail only


# Further Information for Planning Application No. A/YL-TYST/1335 Response-to-Comments

#### **Comments from EPD**


I.	Comments	Responses
1.	Grateful if you could ask the applicant to	The toilets within the Site have been
	confirm whether the proposed toilets are	connected to the public sewer to dispose the
	portable toilets, if affirmative, whether licensed	sewage and waste.
	collectors will be arranged to collect and dispose	
	the sewage and waste from the proposed use. If	
	not, please advise whether septic tank and	
	soakaway system will be provided. If	
	affirmative, whether the septic tank and	
	soakaway system will be designed and	
	constructed according to the requirements of	
	EPD's ProPECC PN 1/23, including	
	requirements for minimum clearance distance,	
	percolation test and certification by Authorized	
	Person.	




#### Point A




#### Point B




### Point C




#### Point D




#### Point E




#### Point F




### Point G



#### Point H





消防(裝置及設備)規例

FSD Ref.: 消防處檔號

## A 9723429

(Regulation 9(1)) (第九條(1)款) CERTIFICATE OF FIRE SERVICE INSTALLATION AND EQUIPMENT 消防裝置及設備證書

	<b></b>	Lot 10/3 (I all	) in D.D.121 & Adjoining	Government Lanc	a .
	p./Town Lot: 数/市地段	4 -	Street/Road/Estate Name : 街道/屋苑名稱	Tong Yan San	Tsuen
Block: 座		District 分區		rea: HK 1. 画香港	□ K 九龍 □ NT 新界
	Building 樓宇類型:□Ind	147 000	ercial商業 Domestic住宅 Composite ordance with Regulation 8(b) of Fire Service (Installations		
	t 1 Annual Inspection ( 一部 只適用於年檢	自工百 equipm	pent which is installed in any premises shall have such fire set every 12 months. 根據消防(裝置及設備)規例第八 2個月由一名註冊承辦商檢查該等消防裝置或設備:	rvice installation or equipment inspecte 、條(b)款,擁有裝置在任何處所內	ed by a registered contractor at lea
Code編碼 (1-35)	Type of FSI 裝置類型	Location(s) 位置	Comment on Condition 狀況評述	Completion Date 完成日期(DD/MM/YY)	Next Due Date 下次到期日(DD/MM/Y
24	7 x 5 kg. Co2 type F.E.		Conformed with FSD requirement	18-3-2025	17-3-2026
1_				3 Yr - 3	
a tete	— <del>∀</del> 0 - 11 - 12 - 13 - 13 - 13 - 13 - 13 - 13		# PP (76 H+ 1/6)	工四、社会本工作	
ode編碼		Location(s) 位置	/ Inspection work 装置/改装/修 Nature of Work Carried out 完成之工作内容		Completion Dat
(1-35)	The REMA	3444 and 1		Tarin a supplied	完成日期(DD/MM
			Nil		
				a sayye month	
				The state of the s	
;					
art 3 第	三部 Defects 損壞事功			Signal Company	
22	三部 Defects 損壞事功	頁 Location(s) 位置	Outstanding Defects 未修缺點	Comment on Do	efects 缺點評述
Code编碼		Fire Ferries Son Switzenburg	Outstanding Defects 未修缺點	Comment on Do	efects 缺點評述
Code编碼		Fire Ferries Son Switzenburg	Outstanding Defects 未修缺點	Comment on Do	efects 缺點評述
Code编碼		Fire Ferries Son Switzenburg	Outstanding Defects 未修缺點 Nil	Comment on Do	efects 缺點評述
ode编碼		Fire Ferries Son Switzenburg	Outstanding Defects 未修缺點 Nil	Comment on Do	efects 缺點評述
Code编碼		Fire Ferries Son Switzenburg	Outstanding Defects 未修缺點Nil	Comment on Do	efects 缺點評述
Code编碼		Fire Ferries Son Switzenburg	Outstanding Defects 未修缺點	Comment on De	efects 缺點評述
ode編碼 (1-35) 'e hereby cer kking order uipment and	Type of FSI 装置類型  tify that the above installations/equi in accordance with the Codes of Pl. Inspection, Testing and Maintenance	Deprive the following the fol	I found to be in efficient ervice Installations and ent published from time	Comment on De	efects 缺點評述 For Fuse of
ode編碼 (1-35)  /e hereby cer king order uipment and ime by the D 人 着 此 遊 處 處	Type of FSI 装置類型  tify that the above installations/equin accordance with the Codes of Pr	Deprive the Location (s) 位置  property that the Loc	I found to be in efficient ervice Installations and ent published from time	Comment on Do  Wong Wai K  RC3/484	For F use o