


Appendix XI Photo Record of the Exterior and Interior of Existing Common
Staircase

Location	Exterior of the Common Staircase Facing Tai Yau Street
Photo No.P01	
Location	Exterior of the Common Staircase Facing Tai Yau Street
Photo No.P02	

Location	Interior of the Common Staircase Facing Tai Yau Street
Photo No.P03	 A photograph showing a wide, multi-level concrete staircase. The stairs are dark and worn. Metal railings are on the left and right. Two small rectangular windows are visible on the upper levels. The walls are light-colored concrete with some staining and wear.
Location	Interior of the Common Staircase Facing Tai Yau Street
Photo No.P04	 A photograph showing a view down a concrete staircase. The stairs are dark and worn. A metal railing is visible in the foreground. On the left wall, there is a small plaque with text and a small sign below it. On the right wall, there is another plaque with text and a small sign below it. The ceiling is high and made of concrete.

Location	Interior of the Common Staircase Facing Tai Yau Street
Photo No.P05	 A photograph showing the interior of a common staircase. The ceiling is dark grey, and the walls are light beige. On the left, there is a dark doorway. In the center, there is a dark metal door. To the right, there is a window with a grid pattern. A red "EXIT" sign is mounted on the wall above the door. There are also some small notices or signs on the walls.
Location	Interior of the Common Staircase Facing Tai Yau Street
Photo No.P06	 A photograph showing the interior of a common staircase. The ceiling is dark grey, and the walls are light beige. On the left, there is a dark doorway. In the center, there is a window with a grid pattern. To the right, there is a dark metal door. The floor is made of light-colored tiles. There are some notices or signs on the walls.