[16P6Y]		2526 7430			
<u>ME</u>		<u>MO</u>			
From	Chief Highway Engineer/NT East	То	CBS/NTE2&RA	IL, Buildii	ngs Department
Ref. (18R66) in HyD NT/13-5/SK/DD216/859	(Attn:	Ms. Sharon TON	G)
Tei. No.	2762 4932	Email.			
Fax. No.	2714 5228	Your Ref.	(175) in BD 2/9264/10(Pt. II)		
Email	desk.nt@hyd.gov.hk	dated	03 Aug 2021	Fax No.	2526 7430
Date	9 August 2021	Total Pages		1	

AP's Certificate of Completion of Vchicular Run-in and Run-out Lot No(s).: D.D. 216 Lots 859 Address: No. 101 Tai Mong Tsai Road, Sai Kung

I refer to your above quoted memo dated 03.08.2021.

- 2. Please be advised that site inspection with the AP for the vehicular run-in/run-out has been held on 22 April 2021 and defect rectification completed on 15 July 2021. I consider the works for the above-mentioned vehicular run-in/run-out have been completed to our satisfaction subject to the following conditions:
 - i) Grating shall be provided for the U-channel after WSD remove the pipe work
 - ii) The U-channel within their lot boundary shall maintain the proper fall direction to prevent flooding on public road / footway

(CHAN Siu-yan)
for Chief Highway Engineer/NT East
Highways Department

c.c.

AC for T/NT, TD Attn.: Mr. Thomas WANG by fax: 2381 3799

DLO/SK by fax: 2792 0706

Internal ME/SK