Durgent Directurn receipt Dexpand Group Directicted Derevent Copy Dentidential			
Christina Ki Na LEE/PLAND			
寄件者: 寄件日期:	Danny Ng 2025年06月18日星期三 14:51		
收件者: 副本:	tpbpd/PLAND Christina Ki Na LEE/PLAND; Bon Tang; Matthew Ng; Louis Tse; Christian Chim; Kevi		
主旨: 附件:	Lam; Grace Wong [FI] S.16 Planning Application No. A/YL-LFS/558 - Further Information FI1 for A_YL-LFS_558 (20250618).pdf		
類別:	Internet Email		
Dear Sir,			
We write to submit further infor	mation to provide additional information of the subject application.		
Should you require more inform	ation, please do not hesitate to contact us. Thank you for your kind attention.		
Kind Regards,			
Danny NG Town Planner R-riches Group (HK) Limited			
T: (852 F: (852)	imited R-riches Planning Limited R-riches Construction Limited M: (852) E: Hing Wai, Kam Tin, New Territories, Hong Kong		



Our Ref.:

DD129 Lot 2092 & 2093

Your Ref.:

TPB/A/YL-LFS/558

The Secretary,
Town Planning Board,
15/F, North Point Government Offices,
333 Java Road,
North Point, Hong Kong

By Email

18 June 2025

Dear Sir,

1st Further Information

Proposed Temporary Warehouse (Excluding Dangerous Goods Godown)
with Ancillary Office for a Period of 3 Years in "Recreation" Zone,
Lots 2092 and 2093 (Part) in D.D. 129, Lau Fau Shan, Yuen Long, New Territories

(S.16 Planning Application No. A/YL-LFS/558)

We write to submit further information to address departmental comments of the subject application (Appendix I).

Should you require more information regarding the application, please contact the undersigned at your convenience. Thank you for your kind attention.

Yours faithfully,

For and on behalf of

R-riches Property Consultants Limited

Danny NG

Town Planner

cc DPO/TMYLW, PlanD

(Attn.: Ms. Christina LEE

email: cknlee@pland.gov.hk)







Responses-to-Comments

Proposed Temporary Warehouse (Excluding Dangerous Goods Godown)
with Ancillary Office for a Period of 3 Years in "Recreation" Zone,
Lots 2092 and 2093 (Part) in D.D. 129, Lau Fau Shan, Yuen Long, New Territories

(Application No. A/YL-LFS/558)

(i) A RtoC Table:

Departmental Comments Applicant's Responses Comments from the Chief Town Planner/Urban Design and Landscape Section, Planning Department (CTP/UD&L, PlanD) (Contact Person: Ms. May CHAN; Tel: 3565 3949) It is stated in the application form that no tree According to the tree survey report conducted (a) felling is proposed within the Site, however on 06.06.2025, 2 nos. of trees were identified within the site boundary (Annex I). No OVT or the aerial photo and site photos show existing trees which would be in conflict with the protected species has been identified in proposed Structures B1 and B3 as shown in accordance with the DEVB TC(W) No. 5/2020 -Registration and Preservation of Old and the "Layout Plan (Dwg no. PLAN 4)". Valuable Trees and the Forests Countryside Ordinance (Cap.96) respectively. All identified trees are proposed to be felled. (b) No landscape technical assessment such as information of existing landscape resources A landscape proposal is provided by the are provided with the application. The applicant (Annex II) where 2 new trees (i.e. applicant should provide the broad-brush Bauhinia Blakeana) (T1 and T2) are proposed to tree survey including nos. of existing trees, be planted at the western portion of the Site as tree species and their conservation status a landscape buffer. The proposed 2 new trees with landscape proposal and mitigation will be planted at least 1.2m soil depth for measures to demonstrate that the proposed better tree health. uses would not have adverse landscape impact on the Site and surrounding areas. The new proposed trees are for mitigating any potential visual and landscape impact (if any) towards nearby sensitive receivers. The new trees planted within the Site will be maintained by the applicant in good condition during the planning approval period.



Tree Survey Report

Date of Survey: 6th June 2025

Location:

Lots 2092 and 2093 (Part) in D.D. 129, Lau Fau Shan, Yuen Long, New Territories

Prepared by:

Mak Ka Hei

Registered Arborist

Date: 7th June 2025



Table of contents

1. Introduction 3

2. Summary of Existing Trees 4

Appendix:

I. Tree Survey Plan

II. Tree Survey Schedule

III. Photo Records

Disclaimer:

The tree survey conducted indicates the condition of the surveyed trees at the time of inspection only. The assessments of amenity value, form, health and structural condition of the trees surveyed are based on visual inspection from the ground only. No aerial inspection, root digging or mapping, or diagnostic testing has been conducted as part of this survey. Wing Ho Yuen Landscaping Company Limited cannot accept responsibility for future failure or defects detected after the time of inspection of the trees surveyed in this report.



1. Introduction

The survey conducted is to record all the existing trees in the tree survey boundary. The survey include tree species identification, tree tagging with durable labels, the measurements of overall tree height, Diameter at Breast Height (DBH), average crown spread, the evaluation on amenity value, form, health and structural conditions.

The tree survey was conducted on 6^{th} June 2025. Plants with DBH less than 95mm were not recorded in the survey.



2. Summary of Existing Trees


The surveyed site is located at Lots 2092 and 2093 (Part) in D.D. 129, Lau Fau Shan, Yuen Long, New Territories.

At the time of inspection on 6th June 2025, **2 nos.** trees were found within the Site. Location of individual tree refers to Appendix I.

Details of tree conditions and photo records for individual tree are recorded in the Appendix II and Appendix III respectively.



Appendix I – Tree Survey Plan





Appendix II – Tree Survey Schedule

一水 豪 園 綠化工程有限公司 WING HO YUEN LANDSCAPING CO., LTD.

Tree Survey Schedule

Location:

Tree surveyor(s):

Lots 2092 and 2093 (Part) in D.D. 129, Lau Fau Shan, Yuen Long, New Territories

Mak Ka Hei Field Survey was conducted on: 6 June 2025

Remarks		decay at trunk, trunk conflict with fencing	1
Suitability for Transplanting	High /Med /Low	Low	row
Structural Condition	Good /Fair /Poor	Poor	Fair
Health Condition	Good /Fair /Poor /Dead	Poor	Fair
Form	Good /Fair /Poor	Poor	Fair
Amenity Value	High /Med /Low	Low	Low
Tree Size Measurements	Average Crown Spread (m)	6.0	7.0
	DBH (mm)	490	230
	Overall Height (m)	8.0	0.9
	Chinese Name Height (m)	榕樹(細葉榕)	榕樹(細葉榕)
Tree Species	Botanical Name	Ficus microcarpa	Ficus microcarpa
Tree No.		T1	T2

Notes: Amenity Value, Form, Health Condition and Structural Condition of trees were obtained by Visual Assessment Only.



Appendix III – Photo Records

General View



General view 01



Photo Records



T1 (Overview)




T1 Decay at trunk



T1 Trunk conflict with fencing




T2 (Overview)



NO. OF PROPOSED TREES : 2
SPECIES OF TREES
SPACING OF TREES
INOT LESS THAN 4m
HEIGHT OF TREES
INOT LESS THAN 2.75m
DIMENSION OF TREE PITS
THOW X 17m (L) X 1.2m (D)

: 2,234 m² (ABOUT)

APPLICATION SITE AREA LANDSCAPE PROPOSAL



R-Riches
Property Consultants Lid.

NOTES:
1) THE APPLICANT WILL MAINTAIN TREES IN GOOD CONDITION DURING THE PLANNING APPROVAL PERIOD.
2) THE APPLICANT WOULD REPLACE TREES WHICH ARE DYING OR DEAD DURING THE PLANNING APPROVAL PERIOD.
3) THE APPLICANT WOULD PROVIDE ADEQUATE IRRIGATION FOR TREES.

001

LANDSCAPE PROPOSAL
DWG140. VEI
PLAN 6 00

• H-POLE (ELECTRICITY)

PROPOSED TREES

NGRESS / EGRESS

11,6,2025